

LICENSEE EVENT REPORT

CONTROL BLOCK

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME 01 A L B R F 3														LICENSE NUMBER 00 - 000000 - 00														LICENSE TYPE 4 1 1 1 1				EVENT TYPE 0 3	
CATEGORY 01 CONT														REPORT TYPE L				REPORT SOURCE L				DOCKET NUMBER 0 5 0 - 0 2 0 6				EVENT DATE 0 9 1 4 7 6				REPORT DATE			

EVENT DESCRIPTION

02 Drywell air sampling system twice remained inoperable for periods greater than 24 hours																																																																															
03 Analyses of grab samples were not performed as required. (BFRO-50-296/7614)																																																																															
04																																																																															
05																																																																															
06																																																																															

SYSTEM CODE 07 1 E										CAUSE CODE A										COMPONENT CODE I N S T R U										PRIME COMPONENT SUPPLIER 4										COMPONENT MANUFACTURER N 3 0 5										VIOLATION N									
-----------------------	--	--	--	--	--	--	--	--	--	-----------------	--	--	--	--	--	--	--	--	--	-------------------------------	--	--	--	--	--	--	--	--	--	-------------------------------	--	--	--	--	--	--	--	--	--	-----------------------------------	--	--	--	--	--	--	--	--	--	----------------	--	--	--	--	--	--	--	--	--

CAUSE DESCRIPTION

09 Condensation from air sample collected in the radiation monitor causing detector																																																																															
09 failure. Alternate redundant sampling requirements were not met.																																																																															
10																																																																															

FACILITY STATUS 11 13										% POWER 0 1 0										OTHER STATUS NA										METHOD OF DISCOVERY 13										DISCOVERY DESCRIPTION NA									
FORM OF ACTIVITY RELEASED 12 Z										CONTENT OF RELEASE Z										AMOUNT OF ACTIVITY NA										LOCATION OF RELEASE NA																			

PERSONNEL EXPOSURES

NUMBER 13 0 0 0										TYPE Z										DESCRIPTION NA									
--------------------	--	--	--	--	--	--	--	--	--	-----------	--	--	--	--	--	--	--	--	--	-------------------	--	--	--	--	--	--	--	--	--

PERSONNEL INJURIES

NUMBER 14 0 0 0										DESCRIPTION NA									
--------------------	--	--	--	--	--	--	--	--	--	-------------------	--	--	--	--	--	--	--	--	--

OFFSITE CONSEQUENCES

15 NA																																																																															
-------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

LOSS OR DAMAGE TO FACILITY

TYPE 16 4										DESCRIPTION NA									
--------------	--	--	--	--	--	--	--	--	--	-------------------	--	--	--	--	--	--	--	--	--

PUBLICITY

17 S										NA									
------	--	--	--	--	--	--	--	--	--	----	--	--	--	--	--	--	--	--	--

8306270037 761013
PDR ADDCK 05000296
PDR

ADDITIONAL FACTORS

18 Temperature of systems heat tracing has been increased to help eliminate condensation.																																																																															
---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

19 Signs will be placed on monitors stating when to initiate sampling program.																																																																															
--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--



TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

October 13, 1976



Mr. Norman C. Moseley, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
230 Peachtree Street, NW., 8th Floor
Atlanta, Georgia 30303

Dear Mr. Moseley:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 -
DOCKET NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE
OCCURRENCE REPORT BFRO-50-296/7614

The enclosed report is to provide details concerning the drywell air sampling system that remained inoperable twice for periods greater than 24 hours. Analyses of grab samples were not performed as required. This report is submitted in accordance with Browns Ferry Technical Specifications Section 6. This event occurred on Browns Ferry Nuclear Plant unit 3.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

(COPY SENT REGION II)

H. S. Fox
Director of Power Production

Enclosure (3)

CC (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director (40)

Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

10552