

LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME		LICENSE NUMBER										LICENSE TYPE					EVENT TYPE							
01	A	L	B	R	F	2	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	1
7	8	9	14	15	25	26	30	31	32															

CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER										EVENT DATE					REPORT DATE				
01	CON'T	*	T	L	0	5	0	-	0	2	6	0	0	6	1	9	7	6							
7	8	57	58	59	60	61	68	69	74	75	80														

EVENT DESCRIPTION

02	HCU 30-31 was found incapable of being scrambled due to valves 2-85-612 and																								80
03	2-85-615 being in the closed position. Interim Technical Specification 4.3.C																								80
04	requires valves 2-85-612 and 2-85-615 for each HCU to be open at all times.																								80
05	(BFRO-50-260/765)																								80
06																									80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE					PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER					VIOLATION	
07	R	B	A	C	R	D	R	V	E	N	G	O	8	O	Y	48	
7	8	9	10	11	12	17	43	44	47								

CAUSE DESCRIPTION

08	Incorrect verification of required valve position caused by personnel																								80
09	error.																								80
10																									60

FACILITY STATUS		% POWER			OTHER STATUS			METHOD OF DISCOVERY		DISCOVERY DESCRIPTION										
11	H	0	0	0	NA	B	NA	44	45	46										
7	8	9	10	12	13	44	45	46												

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY					LOCATION OF RELEASE										
12	Z	Z	NA						NA										
7	8	9	10	11	44	45													

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION											
13	0	0	0	Z	NA										
7	8	9	11	12	13										

PERSONNEL INJURIES

NUMBER		DESCRIPTION												
14	0	0	0	NA										
7	8	9	11	12										

OFFSITE CONSEQUENCES

15	NA																								80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION											
16	Z	NA											
7	8	9	10										

PUBLICITY

17	NA																								80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	NA																								80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

8306290043 760702
PDR ADOCK 05000260
S PDR

19																									80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: _____ PHONE: _____



260/76-5

TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401

July 2, 1976

Mr. Norman C. Moseley, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
230 Peachtree Street, NW., 8th Floor
Atlanta, Georgia 30303



Dear Mr. Moseley:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 -
DOCKET NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE
OCCURRENCE REPORT BFRO-50-260/765

The enclosed report is to provide details concerning HCU 30-31 that was found incapable of being scrambled due to valves 2-85-612 and 2-85-615 being in the closed position and is submitted in accordance with Appendix E to Regulatory Guide 1.16, Revision 4, August 1975. This event occurred on Browns Ferry Nuclear Plant unit 2.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. S. Fox
Director of Power Production

Enclosure (3)
CC (Enclosure):
Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

6846

COPY SENT REGION 4