

CONTROL BLOCK: 

--	--	--	--	--	--

 ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
WHILE PERFORMING ROUTINE SURVEILLANCE VALVE LINEUP ON 1AB DIESEL GENERATOR, THE  
FUEL OIL DAY TANK LEVEL COLUMN HIGH SIDE ISOLATION WAS FOUND CLOSED. THE COLUMN  
LEVEL WOULD HAVE REMAINED ARTIFICIALLY HIGH PREVENTING THE LOW LEVEL ALARM AND  
AUTO START OF THE FUEL OIL TRANSFER PUMPS. THIS IS NON-CONSERVATIVE WITH RESPECT  
TO T.S. 3.8.1.1. SIMILAR EVENTS OF VALVES BEING FOUND OUT OF POSITION WERE  
REPORTED VIA LER 315/77-038, 78-015, 81-010, 81-057, AND 316/78-078. THE HEALTH  
AND SAFETY OF THE PUBLIC WERE NOT AFFECTED.

SYSTEM CODE [0][9]		CAUSE CODE [E][E]		CAUSE SUBCODE [X]		COMPONENT CODE [V][A][L][V][E][X]				COMP. SUBCODE [F]		VALVE SUBCODE [D]	
7	8	9	10	11	12	13	14	15	16	17	18	19	20
LER/RO REPORT NUMBER [17]		EVENT YEAR [18][3]		SEQUENTIAL REPORT NO. [0][5][4]		OCCURRENCE CODE [0][3]		REPORT TYPE [L]		REVISION NO. [0]			
21	22	23	24	25	26	27	28	29	30	31	32		
ACTION TAKEN [E]		FUTURE ACTION [Z]		EFFECT ON PLANT [Z]		SHUTDOWN METHOD [Z]		HOURS [0][0][0][0]		ATTACHMENT SUBMITTED [Y]			
33	34	35	36	37	38	39	40	41	42	43	44		
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)		NPRD-4 FORM SUB [N]		PRIME COMP. SUPPLIER [L]		COMPONENT MANUFACTURER [H][0][3][7]							
45	46	47	48	49	50	51	52						

1 0 INVESTIGATION TO DATE OF THE EVENT REVEALED THAT FOR EVERY DOCUMENTED MANIPULATION  
1 1 OF THE VALVE DURING THE PRECEDING MONTH THAT THE DOCUMENTATION EXISTS INDICATING  
1 2 THAT THE VALVE WAS RESTORED TO NORMAL. AS IT CAN NOT BE DETERMINED WHY OR WHO LEFT  
1 3 THE VALVE CLOSED NO FURTHER CORRECTIVE ACTION WILL BE TAKEN AT THIS TIME. (SEE  
1 4 ATTACHED SUPPLEMENT)

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION			
1	5	E	28	0	4	8	29	NA			B	31	OPERATOR OBSERVATION		
ACTIVITY			CONTENT			AMOUNT OF ACTIVITY			LOCATION OF RELEASE						
1	6	Z	33	Z	34	35	NA			NA					
PERSONNEL EXPOSURES			NUMBER			TYPE			DESCRIPTION						
1	7	0	0	0	37	38	NA								
PERSONNEL INJURIES			NUMBER			DESCRIPTION									
1	8	0	0	0	40	41	NA			8307050090 830624					
LOSS OF OR DAMAGE TO FACILITY			TYPE			DESCRIPTION						PDR ADOCK 05000315			
1	9	Z	42				43	NA			S PDR				
PUBLICITY			ISSUED			DESCRIPTION						NRC USE ONLY			
2	0	N	44				45	NA							

PHONE: (616) 465-5901

SUPPLEMENT TO LER # 83-054/03L-0

27)

INVESTIGATION TO DATE OF THE EVENT REVEALED THAT FOR EVERY DOCUMENTED MANIPULATION OF THE VALVE DURING THE PRECEDING MONTH THAT THE DOCUMENTATION EXISTS INDICATING THAT THE VALVE WAS RESTORED TO NORMAL. AS IT CAN NOT BE DETERMINED WHY OR WHO LEFT THE VALVE CLOSED NO FURTHER CORRECTIVE ACTION WILL BE TAKEN AT THIS TIME. IF FURTHER INVESTIGATION REVEALS A POSSIBLE CAUSE FOR WHICH MEANINGFUL CORRECTIVE ACTION CAN BE TAKEN, AN UPDATED LER WILL BE SUBMITTED.



**INDIANA & MICHIGAN ELECTRIC COMPANY**

DONALD C. COOK NUCLEAR PLANT  
P.O. Box 458, Bridgman, Michigan 49706  
(616) 465-5901

June 24, 1983

Mr. J.G. Keppler, Regional Administrator  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Operating License DPR-58  
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications,  
the following report/s are submitted:

RO 83-054/03L-0

Sincerely,

*W.G. Smith, Jr.*  
W.G. Smith, Jr.  
Plant Manager

/hab

cc: J.E. Dolan  
M.P. Alexich  
R.F. Kroeger  
B. Germano  
E.R. Swanson/N.E. DuBry RO:III  
R.C. Callen MPSC  
G. Charnoff, Esq.  
J.M. Hennigan  
R.O. Bruggee EPRI  
INPO  
PNRSC  
J.F. Stietzel  
E.L. Townley  
Dir., IE (30 copies)  
Dir., MIPC (3 copies)

*IE 22*  
*11*  
JUN 27 1983