

LICENSEE EVENT REPORT

AO-S2-75-19

CONTROL BLOCK

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME C V A S P S 2														LICENSE NUMBER 0 0 - 0 0 0 0 - 0 0														LICENSE TYPE 1 1 1 0										EVENT TYPE 0 1																	
CATEGORY CONT P O														REPORT TYPE T				REPORT SOURCE L				DOCKET NUMBER 0 5 0 - 0 2 8 1														EVENT DATE 1 0 1 5 7 5										REPORT DATE 1 0 2 8 7 5									

EVENT DESCRIPTION

(a) During normal operation of Unit No. 2 at 100 per cent power the "D" boric acid																																																																															
transfer pump motor failed resulting in loss of recirculation of the No. 2																																																																															
boron injection tank. An immediate rampdown of 150 MWe/hour was initiated.																																																																															
(con't)																																																																															

SYSTEM CODE S F										CAUSE CODE E										COMPONENT CODE M O T O R X										PRIME COMPONENT SUPPLIER A										COMPONENT MANUFACTURER W 1 2 0										VIOLATION Y									
--------------------	--	--	--	--	--	--	--	--	--	-----------------	--	--	--	--	--	--	--	--	--	-------------------------------	--	--	--	--	--	--	--	--	--	-------------------------------	--	--	--	--	--	--	--	--	--	-----------------------------------	--	--	--	--	--	--	--	--	--	----------------	--	--	--	--	--	--	--	--	--

CAUSE DESCRIPTION

(a) Examination of the defective motor revealed boric acid present in the stator																																																																															
windings although the present motors are the drip proof type. It is assumed																																																																															
that the boric acid worked its way into the windings during a recent failure (cont)																																																																															

FACILITY STATUS E										% POWER 1 0 0										OTHER STATUS N/A										METHOD OF DISCOVERY A										DISCOVERY DESCRIPTION N/A									
FORM OF ACTIVITY RELEASED Z										CONTENT OF RELEASE Z										AMOUNT OF ACTIVITY N/A										LOCATION OF RELEASE N/A																			

PERSONNEL EXPOSURES

NUMBER 0 0 0										TYPE Z										DESCRIPTION N/A									
-----------------	--	--	--	--	--	--	--	--	--	-----------	--	--	--	--	--	--	--	--	--	--------------------	--	--	--	--	--	--	--	--	--

PERSONNEL INJURIES

NUMBER 0 0 0										DESCRIPTION N/A									
-----------------	--	--	--	--	--	--	--	--	--	--------------------	--	--	--	--	--	--	--	--	--

OFFSITE CONSEQUENCES

N/A																																																																															
-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

LOSS OR DAMAGE TO FACILITY

TYPE Z										DESCRIPTION N/A									
-----------	--	--	--	--	--	--	--	--	--	--------------------	--	--	--	--	--	--	--	--	--

PUBLICITY

N/A																																																																															
-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

8403120263 751016
PDR ADOCK 05000281
S PDR

ADDITIONAL FACTORS

The health and safety of the general public were in no way affected by this occurrence																																																																															
in that the boron injection tank remained full and the capability of the safety (con't)																																																																															

NAME: E. M. Sweeney, Jr.

PHONE: (304) 357-3184

EVENT DESCRIPTION (con't)

- (b) The "B" boric acid transfer pump was placed in service recirculating the No. 2 boron injection tank minimizing the loss of recirculation to 15 minutes. The tank was then sampled and determined to have the correct boric acid concentration and the unit was returned to 100 per cent power.
- (c) This is a similar occurrence to that reported on May 23, 1974 (AO-S1-74-07).
- (d) The defective motor has been replaced with one of the same type and the pump has been returned to service.

CAUSE DESCRIPTION (con't)

of a mechanical joint in the boric acid system (See AO-S2-75-16).


- (b) Manufacturer's Nameplate Data
Model #TUDP Style #6904257
- (c) The licensee intends to replace existing motors with a totally enclosed fan cooled type which would eliminate any possibility of motor failure due to boric acid entering the windings. The orderly replacement of the existing motors will be dependent on the availability of the replacements.

ADDITIONAL FACTORS (con't)

injection system was in no way impaired.

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

October 30, 1975



Mr. Norman C. Moseley, Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region II - Suite 818
230 Peachtree Street, Northwest
Atlanta, Georgia 30303

Serial No. 762
PO&M/JTB:clw

Docket No. 50-281
License No. DPR-37

Dear Mr. Moseley:

Pursuant to Surry Power Station Technical Specification 6.6.B.1, the Virginia Electric and Power Company hereby submits forty (40) copies of Abnormal Occurrence Report No. AO-S2-75-19.

The substance of this report has been reviewed by the Station Nuclear Safety and Operating Committee and will be placed on the agenda for the next meeting of the System Nuclear Safety and Operating Committee.

Very truly yours,

C. M. Stallings

C. M. Stallings
Vice President-Power Supply
and Production Operations

Enclosures

40 copies of AO-S2-75-19

cc: Mr. Robert W. Reid

~~12587~~

12701

COPY SENT REGION *II*