

## LICENSEE EVENT REPORT (LER)

APPROVED OMB NO. 3160-0104  
EXPIRES - 8/31/85FACILITY NAME (1)  
Peach Bottom Atomic Power Station - Unit 3DOCKET NUMBER (2)  
0 8 0 0 0 2 7 8PAGE (3)  
1 OF 03TITLE (4)  
Reactor Scram Due to APRM High FluxEVENT DATE (5)  
MONTH DAY YEAR  
0 2 0 9 8 4 8 4

LER NUMBER (6)

SEQUENTIAL NUMBER

REVISION NUMBER

REPORT DATE (7)

MONTH DAY YEAR

0 0 3 0 7 8 4

OTHER FACILITIES INVOLVED (8)

FACILITY NAMES

DOCKET NUMBER(S)

0 8 0 0 0

0 8 0 0 0

OPERATING  
MODES (9)

N

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following) (11)

20.402(b)

20.406(a)

X 60.73(a)(2)(iv)

73.71(b)

20.406(a)(1)(ii)

60.36(a)(1)

(6.73(a)(2)(v)

73.71(a)

20.406(a)(1)(ii)

60.36(a)(2)

60.73(a)(2)(v)

OTHER (Specify in Abstract  
below and in Test, NRC Form  
306A)

20.406(a)(1)(iii)

60.73(a)(2)(i)

60.73(a)(2)(v)(A)

20.406(a)(1)(iv)

60.73(a)(2)(ii)

60.73(a)(2)(v)(B)

20.406(a)(1)(v)

60.73(a)(2)(iii)

60.73(a)(2)(i)

LICENSEE CONTACT FOR THIS LER (12)

NAME

B. L. Clark, Senior Engineer - Special Projects

TELEPHONE NUMBER

AREA CODE

2 1 5 8 4 1 1 5 0 1 7

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC
X	SR	CPLG	Z010	Y					
X	TC		2A109	Y					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)

X NO

EXPECTED  
SUBMISSION  
DATE (15)

MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

Abstract 3-84-05

On February 9, 1984, at 6:07 p.m., a runback and subsequent relay failure in the Main Turbine Electrohydraulic Control System (EHC) resulted in a Unit 3 reactor auto scram on high neutron flux.

With Unit 3 operating at about 92% power, the 3B reactor feed pump (RFP) turbine experienced high vibration. Manually tripping the reactor feedpump turbine caused an automatic runback of the recirculation pumps and the turbine EHC system. A faulty relay contact in the EHC system kept the closing circuit of the main turbine control valves energized which resulted in a reactor auto scram on high neutron flux.

The faulty EHC relay and a faulty reactor feedpump turbine coupling which was causing the vibration were replaced. A routine test will be instituted to functionally test this relay and the EHC runback logic each refueling outage.

IER2

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Peach Bottom Atomic Power Station Unit 3	0500027884	84	005	00	02	OF	03

TEXT (If more space is required, use additional NRC Form 368A (1))

Description of the Event:

On February 9, 1984, Peach Bottom Atomic Power Station, Unit 3, was operating at about 92% power. At approximately 6:00 p.m., the 3B reactor feed pump experienced high vibration. The reactor operator, in an effort to decrease the vibration, reduced flow through the pump. Vibration continued and the operator manually tripped the pump. The ensuing transient caused reactor water level to decrease.

With feedwater flow greater than 95% and reactor water level below plus 17 inches, recirculation pump and EHC runback signals were correctly initiated.

The EHC runback is designed to slowly pulse down the turbine load at approximately 1% per minute. An Agastat relay (Model 2432 PDC) failure caused the EHC system to runback at a rapid continuous rate. The main turbine bypass valves opened to compensate for the reduced turbine load. When all bypass valves were fully open and the control valves continued to close, a high neutron flux auto scram occurred at 6:07 p.m.

Consequences of the Event:

The Reactor Protection System functioned properly and the reactor successfully auto scrammed on high flux. Since the Reactor Protection System functioned properly and no design limits were exceeded, the safety consequences of this event are considered minimal.

Cause of the Event:

The cause of the event was the failure of an Agastat relay (Model 2432 PDC) in the turbine EHC runback logic.

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES 8/31/86

FACILITY NAME (1)  Peach Bottom Atomic Power Station Unit 3	DOCKET NUMBER (2)  05000278	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		84	005	00	03	OF	03

TEXT (if more space is required, use additional NRC Form 368A) (17)

The relay, if operating properly, should have decreased turbine load at approximately 1% per minute until feedwater flow was less than 95%. However, a contact within this relay remained closed after the EHC runback was initiated causing a runback at a much faster rate and preventing the runback from stopping when it was no longer needed. The cause of the 3B reactor feedpump vibration problem was a faulty Zurn coupling.

Corrective Actions:

The Agastat relay was replaced. A routine test has been written and will be instituted to functionally test this relay and the EHC runback logic each refueling outage.

The Zurn coupling on the 3B reactor feedpump turbine was replaced and the turbine was returned to satisfactory service.

PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

(215) 841-4000

March 7, 1984

Docket No. 50-278

Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555


SUBJECT: Licensee Event Report

This LER deals with a reactor scram on APRM high flux caused by the failure of a relay in the turbine EHC runback logic.

Reference:	Docket No. 50-278
Report Number:	3-84-05
Event Date:	February 9, 1984
Report Date:	March 7, 1984
Facility:	Peach Bottom Atomic Power Station RD #1, Box 208, Delta, PA 17314

This LER is submitted pursuant to the requirements of 10 CFR 50.73(a)(2)(IV).

Very truly yours,



W. T. Ullrich  
Superintendent  
Nuclear Generation Division

cc: Dr. Thomas E. Murley, Administrator  
Region I, USNRC

Mr. A. R. Blough  
Site Inspector

IE22  
1/1