

NRC FORM 366 (12-81)		U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT		APPROVED BY OMB 3150-0011 EXPIRES 4-30-82	
CONTROL BLOCK: 1		(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)			
<div style="display: flex; justify-content: space-between;"> 0 1 M D C C N 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 </div>		<div style="display: flex; justify-content: space-between;"> LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT </div>			
CONT					
<div style="display: flex; justify-content: space-between;"> 0 1 REPORT SOURCE L 6 0 5 0 0 0 3 1 7 7 0 5 2 5 8 3 8 0 3 0 6 8 4 9 </div>		<div style="display: flex; justify-content: space-between;"> DOCKET NUMBER EVENT DATE REPORT DATE </div>			
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10					
0 2 At 1925 during normal operation, 12 ECCS pump room cooler was taken out					
0 3 of service for maintenance. The cooler was declared inoperable rendering					
0 4 one ECCS subsystem inoperable (T.S. 3.5.2). The cooler salt water supply					
0 5 piping and strainer were cleaned and the cooler returned to service at					
0 6 1655 on 5/26/83. The redundant ECCS subsystem remained operable throughout					
0 7 the event. Similar events: none.					
0 8					
<div style="display: flex; justify-content: space-between;"> <div> SYSTEM CODE S F 11 </div> <div> CAUSE CODE D 12 </div> <div> CAUSE SUBCODE Z 13 </div> <div> COMPONENT CODE P I P E X X 14 </div> <div> COMP. SUBCODE C 15 </div> <div> VALV. SUBCODE Z 16 </div> </div>					
<div style="display: flex; justify-content: space-between;"> <div> LER/RO REPORT NUMBER 17 8 3 </div> <div> EVENT YEAR 8 3 </div> <div> SEQUENTIAL REPORT NO. 0 3 4 </div> <div> OCCURRENCE CODE 0 3 </div> <div> REPORT TYPE X </div> <div> REVISION NO. 1 </div> </div>					
<div style="display: flex; justify-content: space-between;"> <div> ACTION TAKEN G 18 </div> <div> FUTURE ACTION Z 19 </div> <div> EFFECT ON PLANT Z 20 </div> <div> SHUTDOWN METHOD Z 21 </div> <div> HOURS 0 0 0 0 22 </div> <div> ATTACHMENT SUBMITTED N 23 </div> <div> NPRD-4 FORM SUB. N 24 </div> <div> PRIME COMP. SUPPLIER A 25 </div> <div> COMPONENT MANUFACTURER D 2 1 5 26 </div> </div>					
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27					
1 0 The supply piping and strainers on both units have been disassembled,					
1 1 inspected and cleaned. Existing operations PM procedures(flow test)have					
1 2 been reviewed and found to be satisfactory. New mechanical maintenance					
1 3 PM procedures have been implemented to inspect and clean the strainers					
1 4 upon completion of the operations PM procedures					
<div style="display: flex; justify-content: space-between;"> <div> FACILITY STATUS E 28 </div> <div> % POWER 1 0 0 29 </div> <div> OTHER STATUS NA 30 </div> <div> METHOD OF DISCOVERY A 31 </div> <div> DISCOVERY DESCRIPTION Operator Observation 32 </div> </div>					
<div style="display: flex; justify-content: space-between;"> <div> ACTIVITY CONTENT RELEASED OF RELEASE Z 33 </div> <div> AMOUNT OF ACTIVITY Z 34 </div> <div> LOCATION OF RELEASE NA 36 </div> </div>					
<div style="display: flex; justify-content: space-between;"> <div> PERSONNEL EXPOSURES NUMBER 0 0 0 37 </div> <div> TYPE Z 38 </div> <div> DESCRIPTION NA 39 </div> </div>					
<div style="display: flex; justify-content: space-between;"> <div> PERSONNEL INJURIES NUMBER 0 0 0 40 </div> <div> DESCRIPTION NA 41 </div> </div>					
<div style="display: flex; justify-content: space-between;"> <div> LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 </div> <div> DESCRIPTION NA 43 </div> </div>					
<div style="display: flex; justify-content: space-between;"> <div> PUBLICITY ISSUED DESCRIPTION N 44 </div> <div> NRC USE ONLY <div style="border: 1px solid black; width: 100px; height: 20px;"></div> </div> </div>					
<div style="display: flex; justify-content: space-between;"> <div>NAME OF PREPARER K. T. Brant</div> <div>PHONE: 301-260-4002</div> </div>					

8403130295 840306
PDR ADOCK 05000317
S PDR

BALTIMORE GAS AND ELECTRIC COMPANY

P.O. BOX 1475

BALTIMORE, MARYLAND 21203

NUCLEAR POWER DEPARTMENT
CALVERT CLIFFS NUCLEAR POWER PLANT
LUSBY, MARYLAND 20657

March 6, 1984

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Docket No. 50-317
License No. DPR-53

Dear Sir:

The attached supplemental report to LER 83-34/3X, Revision 1, is being sent to you as required by 10 CFR 50.73.

Should you have any questions regarding this report, we would be pleased to discuss them with you.

Very truly yours,

LBR
L. B. Russell
Plant Superintendent

LBR:KTB:mst

cc: Dr. T. E. Murley
Director, Office of Management Information
and Program Control
Messrs: A. E. Lundvall, Jr.
J. A. Tiernan

IE22
1/1