

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

34 MAR 15 A 8:38 March 12, 1984

BLRD-50-438/83-42

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:


BELLEFONTE NUCLEAR PLANT UNIT 1 - MAKEUP/HIGH PRESSURE INJECTION PUMP
VIBRATION -BLRD-50-438/83-42- THIRD INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector Linda Watson on June 22, 1983 in accordance with 10 CFR 50.55(e) as NCR 2393. This was followed by our interim reports dated July 20, and November 30, 1983. Enclosed is our third interim report. We expect to submit our next report by July 23, 1984. We consider 10 CFR Part 21 applicable to this deficiency.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



L. M. Mills, Manager
Nuclear Licensing

Enclosure

cc: Mr. Richard C. DeYoung, Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center (Enclosure)
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8403190287 840312
PDR ADOCK 05000438
S PDR

1983-TVA 50TH ANNIVERSARY

An Equal Opportunity Employer

OFFICIAL COPY

IF27

ENCLOSURE

BELLEFONTE NUCLEAR PLANT UNIT 1
MAKEUP/HIGH PRESSURE INJECTION PUMP VIBRATION
BLRD-50-438/83-42
NCR 2393
10 CFR 50.55(e)
THIRD INTERIM REPORT

Description of Deficiency

Measured vibration levels on one of the three makeup/high pressure injection (MU/HPI) pumps provided by Babcock & Wilcox (B&W) for Bellefonte unit 1 are not consistently below the established high level limit of 0.75 mils. After the high vibration problem was noted, an attempt by B&W was made to balance the rotating assembly in November 1982. The effort was not successful. It was noted at that time that the vibration level on the pump varied with the temperature of the pump.

Since the attempt to balance the rotating assembly on site was not successful, the inner casing and rotating assembly were removed and shipped to the manufacturer, Bingham-Willamette in Portland, Oregon. The shaft and rotating assembly were examined by Bingham and returned to Bellefonte in March 1983. The pump was reassembled and further vibration testing was completed. The initial vibration levels of the reassembled pump were high (2.5 to 3.0 mils displacement). B&W again attempted to balance the pump rotating assembly. Vibration levels were reduced to a level below the 0.75 mils limit for approximately 70 percent of the measurements, with the remainder of the measurements at or greater than the 0.75 mils limit. The pump to date has failed to operate within the vibration limit on a consistent basis and still shows a significant variation of the vibration level with temperature.

Interim Progress

In response to NCR 2393, B&W performed several tests on the pump to determine if a bowed shaft was causing the high vibration levels or if changes in the resonant frequency caused by thermal transients resulted in the high vibration levels. The tests consisted of the following:

- (1) The rotating element was removed from the pump.
- (2) A shaft straightness check was made with the rotating element at room temperature.
- (3) The rotating element was placed in a 145°-150°F water bath and allowed to stabilize at that temperature.
- (4) The element was removed from the bath and a second shaft straightness test was performed.

- (5) The element was allowed to stabilize at ambient conditions and a final shaft straightness test was performed.
- (6) A "rap" test on the rotating assembly was performed to determine the resonant frequency at each thermal condition.

In each case, the shaft straightness test detected no bowing in the shaft. The results did not show any susceptibility to the thermal transient imposed on it. B&W's conclusion was that a bowed shaft was not producing the vibration pattern observed.

The "rap" test data was obtained using accelerometers mounted on the shaft and resulted from impacts in both the horizontal and vertical directions at two locations. The data indicated that the vertical first resonant frequency was unchanged from the hot to cold condition. B&W indicated that, since this is the most reliable test configuration, the absence of frequency changes indicates no shaft stiffness change. There were measured changes in the horizontal direction for the first, second, and third resonant frequencies. B&W believes that these changes were due to the lack of control over the horizontal support boundary conditions and should not be of concern. B&W concluded from the frequency tests that the vibration problem was not the result of a thermally induced rotor characteristic change.

Based on B&W's and Bingham-Willamette's operating experience, the current levels of vibration are not injurious to the pump and can be "used-as-is" after reassembly/balancing is complete. (Current levels are based on the last 7.5 hours of pump operation occurring in May 1983 after B&W had balanced the pump rotating assembly. Maximum vibration seen during this time was 0.6 mil/s.). TVA will reassemble and attempt to balance the pump on site by June 1, 1984, and balance weights, where necessary, will be permanently attached and documented during the field balancing. TVA will provide additional information on this item after the balancing is complete.