

# LICENSEE EVENT REPORT

50-285/76-22

CONTROL BLOCK

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME														LICENSE NUMBER														LICENSE TYPE										EVENT TYPE	
01	N	E	F	C	S	1	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	1															
7	8	9	14	15	25	26	30	31	32																														
01 CONT		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER										EVENT DATE					REPORT DATE																		
0	1			T	L	0	5	0	-	0	2	8	5	0	7	1	0	7	6	0	7	2	0	7	6														
7	8	57	58	59	60	61	68	69	74	75	80																												

## EVENT DESCRIPTION

02	During normal operation the river delta-temperature limit of 20 degrees F. specified																																																																															
03	in Appendix B Section 1.1.2 was exceeded at 2150 hours for a period of ten (10) min-																																																																															
04	utes. A peak delta-temperature of 24 degrees F. was reached momentarily. Failure of																																																																															
05	a condenser backwash valve to operate properly caused violation. Faulty backwash																																																																															
06	valve was repaired. This is the third violation of the river delta-temperature limit.																																																																															

SYSTEM CODE		CAUSE CODE		COMPONENT CODE														PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER					VIOLATION	
07	H	C	E	V	A	L	V	E	X	A	L	2	0	0	Y											
7	8	9	10	11	12	13	14	15	16	17	43	44	45	46	47	48										

## CAUSE DESCRIPTION

08	Condenser backwash valve MOV-A-D4 failed to open electrically after backwashing the																																																																															
09	condenser. The valve was immediately opened manually to return the river delta-																																																																															
10	temperature to 19 degrees F. The valve operator worm and worm gear (continued)																																																																															

FACILITY STATUS		% POWER		OTHER STATUS										METHOD OF DISCOVERY		DISCOVERY DESCRIPTION																	
11	E	0	9	6	NA	A	Local valve position indication and																										
7	8	9	10	11	12	13	44	45	control room alarm																								
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY												LOCATION OF RELEASE																	
12	Z	Z	NA	NA																													
7	8	9	10	11	44	45																											

## PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION																			
13	0	0	0	Z	NA																		
7	8	9	11	12	13																		

## PERSONNEL INJURIES

NUMBER		DESCRIPTION																				
14	00	00	00	NA																		
7	8	9	11	12																		

## OFFSITE CONSEQUENCES

15	NA																																																																															
7	8	9																																																																														

## LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION																																																																														
16	Z	NA																																																																														
7	8	9	10																																																																													

## PUBLICITY

17	NA																																																																															
7	8	9																																																																														

8403230211 760720  
PDR 4DOCK 05000285  
S PDR

## ADDITIONAL FACTORS

18	Cause Description (continued): were replaced and a satisfactory retest was performed.																																																																															
7	8	9																																																																														
19	See Attachments 1, 2 and 3 (LER 50-285/76-22)																																																																															
7	8	9																																																																														

NAME: W. Dermeyer / R. Andrews

PHONE: 402-426-4011

ATTACHMENT NO. 1

Safety Analysis/Analysis of Occurrence

At 2150 hours on July 10, 1976, the Turbine Building Equipment Operator - Nuclear (EO-N) was transferring the main condenser from the backwash mode to the normal mode of operation.

The inlet and outlet valves in the backwash flow path moved from the open to the closed position. However, the outlet valve (MOV-A-D4) in the normal flow path failed to open when the backwash valves shut. The EO-N at the backwash panel noticed the failure and started opening the valve manually. A low vacuum alarm in the main control room annunciated and the shift supervisor proceeded to the backwash panel. When the shift supervisor arrived, the operator had manually opened MOV-A-D4.

The shift supervisor suspecting that a violation of the river delta-temperature specification had occurred, checked the delta-temperature recorder in the Intake Structure. Upon observing that the specification was exceeded the shift supervisor notified the Manager - Fort Calhoun Station. The Manager - Fort Calhoun Station informed Mr. Jack Ward, NRC-OIE, Region IV, by telephone at 1315 hours, on July 11, 1976.

This is the third violation of the river delta-temperature limit. Previous violations occurred on January 12, 1975, and January 9, 1976, but those were caused by severe icing conditions on the Missouri River.

ATTACHMENT NO. 2

Corrective Action

Maintenance Order No. 11364 was initiated to repair MOV-A-D4. The control switch for MOV-A-D4 was caution tagged to prevent reoccurrence until the valve could be repaired.

The valve operator for MOV-A-D4 was inspected and the worm and worm gear were replaced. The valve was tested after repair and normal operation was verified both visually and by confirmation of normal amperage to the motor.

ATTACHMENT NO. 3

Failure Data

This is the first failure of a motor operated condenser valve which resulted in a violation of the Technical Specifications.

# Omaha Public Power District

1623 HARNEY ■ OMAHA, NEBRASKA 68102 ■ TELEPHONE 536-4000 AREA CODE 402



July 20, 1976  
FC-227-76



Mr. E. Morris Howard  
U. S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive  
Suite 1000  
Arlington, TX 76012

Dear Mr. Howard:

Reference: Fort Calhoun Station Unit No. 1  
Docket No. 50-285

In accordance with the Fort Calhoun Station's Technical Specifications, the Omaha Public Power District, as holder of facility operating license DPR-40, submits three copies of the following licensee event report 50-285/76-22 to satisfy the requirements of Regulatory Guide 1.16.

Sincerely,

W. C. Jones  
Section Manager  
Operations

WCJ/WDD:rge

Enclosures

cc: Director, Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555 (3)

Director, Office of Inspection and  
Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555 (30)

Mr. L. C. Shalla  
SARC Chairman  
PRC Chairman  
Fort Calhoun File (2)

~~COPY SENT REGION~~

7504