

LICENSEE EVENT REPORT

50-285/76-5 Supplement No. 4

CONTROL BLOCK 1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: [01] N E F C S 1 14
 LICENSE NUMBER: [00] 0 0 - 0 0 0 0 0 0 - 0 0 25
 LICENSE TYPE: [41] 1 1 1 1 30
 EVENT TYPE: [03] 0 3 31 32
 CATEGORY: [01] CONT 57 58
 REPORT TYPE: [L] 59
 REPORT SOURCE: [L] 60
 DOCKET NUMBER: [05] 0 5 0 - 0 2 8 5 68
 EVENT DATE: [09] 0 9 0 1 7 7 74
 REPORT DATE: [09] 0 9 1 5 7 7 80

EVENT DESCRIPTION

[02] During the installation of new recirculation actuation pressure switches (RAS) per 80
 [03] Design Change Request DCR 75A-36 it was noted that one of the A Channel switches failed 80
 [04] to hold setpoint. The remaining switches for B, C and D Channels remained operable as 80
 [05] the installation of these switches had not yet been completed. 80
 [06] LER 50-285/76-5 Supplement No. 4 80

SYSTEM CODE: [07] I A 10
 CAUSE CODE: [A] 11
 COMPONENT CODE: [I N S T R U] 17
 PRIME COMPONENT SUPPLIER: [O] 43
 COMPONENT MANUFACTURER: [S 3 8 2] 47
 VIOLATION: [Y] 48

CAUSE DESCRIPTION

[08] The new static-o-ring model 12NN-K6A-XIV switch was found to have drifted out of speci- 80
 [09] fication due to being calibrated with less than actual tank level (pressure) causing 80
 [10] switch to drift from setpoint. The switch was recalibrated satisfactorily. 80

FACILITY STATUS: [11] E 9
 % POWER: [10] 1 0 0 12 13
 OTHER STATUS: [Normal Operation] 44
 METHOD OF DISCOVERY: [C] 45
 DISCOVERY DESCRIPTION: [Design Change Request in Progress] 80
 FORM OF ACTIVITY RELEASED: [12] Z 9
 CONTENT OF RELEASE: [Z] 10
 AMOUNT OF ACTIVITY: [NA] 11
 LOCATION OF RELEASE: [NA] 45 80

PERSONNEL EXPOSURES

[13] NUMBER: [00] 0 0 0 11
 TYPE: [Z] 12
 DESCRIPTION: [NA] 13 80

PERSONNEL INJURIES

[14] NUMBER: [00] 0 0 0 11
 DESCRIPTION: [NA] 12 80

OFFSITE CONSEQUENCES

[15] NA 80

LOSS OR DAMAGE TO FACILITY

[16] TYPE: [Z] 9
 DESCRIPTION: [NA] 10 80

PUBLICITY

[17] NA 80

ADDITIONAL FACTORS

[18] See Attachments 1, 2 and 3 80

[19] 80

8403260388 771031
 PDR ADOCK 05000285
 S PDR

NAME: J. L. Connolley/G. R. Peterson

PHONE: 402-426-4011

ATTACHMENT NO. 1

Safety Analysis

The failure of the new static-o-ring pressure switch for initiation of recirculation actual signal (RAS) would not have impaired the system from performing its design function if required. RAS is initiated on either Channel A or Channel B of the Engineered Safety Features (ESF) System. The A signal switches (A/LC-383) is one of the two out of four logic inputs to Channel A. With one switch failed Channel A of the ESF System was in a two out of three logic while Channel B of the ESF System remained in a two out of four logic. This exceeds the minimum degree of redundancy required by Table 2-3 of the Technical Specification.

ATTACHMENT NO. 2

Corrective Action

The new static-o-ring pressure switch was initially calibrated using a 140" water column. During this calibration the switch operated satisfactorily and was returned to service where a SIRWT level corresponding to approximately 190" water column was placed on the switch causing the shift in setpoint.

The switch was then recalibrated at maximum tank level and has been calibrated/checked on several occasions with no apparent setpoint drift. The calibration procedure for the RAS switches has been revised to calibrate the switches at maximum tank level.

The remaining switches to be installed under DCR 75A-36 will be calibrated at maximum tank level and calibrated/checked prior to being placed in service.

ATTACHMENT NO. 3

Failure Data

This is the first failure of a static-o-ring pressure switch in the RAS system; however, the switches have performed satisfactorily once calibrated at maximum SIRWT tank level.

Also, see Barksdale pressure switch failures LER 50-285/76-5 and subsequent supplements.



Omaha Public Power District

1623 HARNEY ■ OMAHA, NEBRASKA 68102 ■ TELEPHONE 536-4000 AREA CODE 402

September 27, 1977
FC-418-77

Mr. E. Morris Howard
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive
Suite 1000
Arlington, TX 76012

Dear Mr. Howard:

Reference: Fort Calhoun Station Unit No. 1
Docket No. 50-285

In accordance with the Fort Calhoun Station's Technical Specifications, the Omaha Public Power District, as holder of facility operating license DPR-40, submits three copies of the following licensee event report supplement 50-285/76-5 to satisfy the requirements of Regulatory Guide 1.16.

Sincerely,

W. C. Jones
Section Manager
Operations

WCJ/WDD:rge

Enclosures

cc: Director, Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, DC 20555 (3)

Director, Office of Inspection and
Enforcement
U. S. Nuclear Regulatory Commission
Washington, DC 20555 (30)

Mr. L. C. Shalla
SARC Chairman
PRC Chairman
Fort Calhoun File (2)

772850084