

NRC Form 308
(9-83)

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES 8/31/85

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Washington Nuclear Project - Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 3 9 7	PAGE (3) 1 OF 0 2
--	--------------------------------------	----------------------

TITLE (4)
Dampers Fail to Meet UL Standards

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)																																
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)																															
1	2	2	8	3	0	0	3	2	8	8	4	0 5 0 0 0																													
<p>THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)</p> <table border="1"> <tr> <td>OPERATING MODE (9) 5</td> <td>20.402(b)</td> <td>20.406(e)</td> <td>50.73(a)(2)(iv)</td> <td>73.71(b)</td> </tr> <tr> <td>POWER LEVEL (10) 0 0 0</td> <td>20.406(a)(1)(i)</td> <td>50.36(a)(1)</td> <td>50.73(a)(2)(v)</td> <td>73.71(e)</td> </tr> <tr> <td></td> <td>20.406(a)(1)(ii)</td> <td>50.36(a)(2)</td> <td>50.73(a)(2)(vi)</td> <td>OTHER (Specify in Abstract below and in Text, NRC Form 266A)</td> </tr> <tr> <td></td> <td>20.406(a)(1)(iii)</td> <td>50.73(a)(2)(i)</td> <td>50.73(a)(2)(vii)(A)</td> <td></td> </tr> <tr> <td></td> <td>20.406(a)(1)(iv)</td> <td>X 50.73(a)(2)(ii)(B)</td> <td>50.73(a)(2)(vii)(B)</td> <td></td> </tr> <tr> <td></td> <td>20.406(a)(1)(v)</td> <td>50.73(a)(2)(iii)</td> <td>50.73(a)(2)(ix)</td> <td></td> </tr> </table>												OPERATING MODE (9) 5	20.402(b)	20.406(e)	50.73(a)(2)(iv)	73.71(b)	POWER LEVEL (10) 0 0 0	20.406(a)(1)(i)	50.36(a)(1)	50.73(a)(2)(v)	73.71(e)		20.406(a)(1)(ii)	50.36(a)(2)	50.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 266A)		20.406(a)(1)(iii)	50.73(a)(2)(i)	50.73(a)(2)(vii)(A)			20.406(a)(1)(iv)	X 50.73(a)(2)(ii)(B)	50.73(a)(2)(vii)(B)			20.406(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(ix)	
OPERATING MODE (9) 5	20.402(b)	20.406(e)	50.73(a)(2)(iv)	73.71(b)																																					
POWER LEVEL (10) 0 0 0	20.406(a)(1)(i)	50.36(a)(1)	50.73(a)(2)(v)	73.71(e)																																					
	20.406(a)(1)(ii)	50.36(a)(2)	50.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 266A)																																					
	20.406(a)(1)(iii)	50.73(a)(2)(i)	50.73(a)(2)(vii)(A)																																						
	20.406(a)(1)(iv)	X 50.73(a)(2)(ii)(B)	50.73(a)(2)(vii)(B)																																						
	20.406(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(ix)																																						

LICENSEE CONTACT FOR THIS LER (12)

NAME L. D. Kassakatis, Plant Compliance Engineer	TELEPHONE NUMBER AREA CODE 5 0 9 3 7 7 - 2 5 0 1
---	--

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)											
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDs		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDs	
B	V,H	D,M,P R 4 1 1		N							
B	V,J	D,M,P R 4 1 1		N							

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)	X NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

A walk down was performed on fire dampers and those listed below were found which did not meet UL fire rating requirements, thus violating Tech Spec 3/4.7.7. The system remained fully functional even though the dampers were not in compliance with UL standards. Thus potential consequences were minimal. Damper identification: WMA-FD-1, -2, -3, -6, -7, -8, -9, -10, -11, -14, and DRA-FD-34-1.

8404040190 840328
PDR ADOCK 05000397
S PDR

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 2/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Washington Nuclear Project - Unit 2	0 5 0 0 0 3 9 7	8 3	— 0 0 3	— 0 1	0 2	OF	0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

The fire dampers which were originally reported as being modified by the vendor were numbered incorrectly. This was due to personnel error when reading the associated drawings. Dampers WMA-FD-3 and 6 were originally reported as WMA-FD-18 and 15 respectively. The modification made to the dampers was minor cutting to obtain the size required to allow installation into the existing duct work. This cutting, however, voided the U.L. fire rating of the dampers, thus violating Technical Specification 3/4.7.7, which requires all fire rated assemblies to be operable at all times.

Corrective Action:

A fire watch has been established to monitor the affected areas.

Each modified damper is being removed and replaced with a U.L. approved damper.

Washington Public Power Supply System

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000

Docket No. 50-397
March 28, 1984


Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Subject: **NUCLEAR PROJECT NO. 2**
LICENSEE EVENT REPORT NO. 83-003 REVISION 1

Dear Sir:

Transmitted herewith is Revision 1 to Licensee Event Report No. 83-003 for WNP-2 Plant. This report is submitted in response to the report requirements of Technical Specification Section 6.9.1.7 and discusses the item of noncompliance and corrective action taken. The revision was necessary because of component misidentification in the original report.

Very truly yours,


J. D. Martin (M/D 927M)
WNP-2 Plant Manager

JDM:de

Enclosure:

Licensee Event Report No. 83-003 Revision 1

cc: Mr. John B. Martin, Administrator
Region V, Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
1450 Maria Lane
Walnut Creek, California 94596
Mr. A. D. Toth, NRC Resident Inspector (901A)

IE22
11