

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	C	0	F	S	V	1	2	0	0	1	-	0	0	0	0	0	0	-	0	0	0	3	4	1	1	1	2	0	4	1	5
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39
LICENSEE CODE		LICENSE NUMBER										LICENSE TYPE										CAT		58								

CON'T

0	1	L	6	0	5	0	0	0	2	6	7	7	0	6	0	4	8	0	8	0	3	2	8	8	4	9						
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39
REPORT SOURCE		DOCKET NUMBER										EVENT DATE										REPORT DATE										

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On June 4, 1980, during normal power operation while performing SR 5.2.16a-m, Loop 2 steam generator penetration leakage appeared to be greater than 400 pounds per day. Further testing revealed the leakage was internal to the steam generator and not through the seals. Leakage was greater than 700 pounds per day on several occasions during February and March, 1981, and resulted in a plant shutdown on March 22, 1981, for further investigation. These events were reported as operation in a degraded mode of LCO 4.2.9 per Fort St. Vrain Technical Specification AC 7.5.2(b)2. No effect on public health or safety. No similar reportable occurrences.

0	9	H	B	11	X	12	Z	13	H	T	E	X	C	H	14	F	15	Z	16	17	8	0	21	1	22	0	3	0	23	0	3	24	0	3	25	X	26	1	27	3	28	3	29	3	30	3	31	3	32	3	33	3	34	3	35	3	36	3	37	3	38	3	39
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE										COMP. SUBCODE		VALVE SUBCODE		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER																	
LER/RO REPORT NUMBER		ACTION		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER																																													

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The purified helium leakage is internal to the penetration interspace and occurred between the interspace and associated cold reheat steam piping. Public Service Company Change Notice (CN) 1436 modified the steam generator interspace to operate at a pressure slightly greater than cold reheat steam. Revisions to LCO 4.2.7 and 4.2.9 were approved to allow operation in this manner and set limits on possible releases of primary coolant activity. No further corrective action is anticipated or required.

1	5	E	28	0	6	7	29	N/A	30	B	31	Regular Scheduled Surveillance	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		ACTIVITY CONTENT		AMOUNT OF ACTIVITY		LOCATION OF RELEASE		PERSONNEL EXPOSURES		DESCRIPTION		PERSONNEL INJURIES		LOSS OF OR DAMAGE TO FACILITY		PUBLICATION		ISSUED		DESCRIPTION		NAME OF PREPARER		PHONE		NRC USE ONLY																											

NAME OF PREPARER

PHONE: (303) 785-2224

REPORT DATE: March 28, 1984

REPORTABLE OCCURRENCE 80-30
ISSUE 3

OCCURRENCE DATE: June 4, 1980

Page 1 of 6

FORT ST. VRAIN NUCLEAR GENERATING STATION
PUBLIC SERVICE COMPANY OF COLORADO
16805 WELD COUNTY ROAD 19 1/2
PLATTEVILLE, COLORADO 80651-9298

REPORT NO. 50-267/80-30/03-X-3

Revised Final

IDENTIFICATION OF
OCCURRENCE:

During performance of plant test T-147, the steam generator penetration interspace leakage appeared to be in excess of the limit allowed by LCO 4.2.9 and the variance granted by the Nuclear Regulatory Commission on June 5, 1980.

This was reported as operation in a degraded mode of LCO 4.2.9 per Fort St. Vrain Technical Specification AC 7.5.2(b)2.

EVENT
DESCRIPTION:

On May 28, 1980, during performance of the scheduled surveillance on PCRV leakage, Loop 2 steam generator penetration was found to have a leak rate of 8.23 pounds per hour or 198 pounds per day. This was well within the 400 pounds per day limit of LCO 4.2.9.

On June 4, 1980, the surveillance was again performed and indicated steam generator penetration leakage to be 17.83 pounds per hour. This was 428 pounds per day and in excess of the LCO 4.2.9 limit of 400 pounds per day. A special test, T-145, using a pressure decay method, was written, approved, and performed later that day and showed the leakage rate to be 10.74 pounds per hour or 258 pounds per day, within the limits of LCO 4.2.9. T-145 was a more accurate test and was used at this time to insure Technical Specification compliance.

During performance of T-145, it was noted that the pressure decay rate did not decrease as reactor pressure was approached. This indicated that a primary closure seal was not leaking. Further investigation revealed a noncondensable gas was in the hot reheat sample line. A sample was taken, analyzed, and determined to be clean helium. The leakage flow path was believed to be from the penetration interspace to the cold reheat piping and out of the steam generator via the hot reheat piping (see Figure 1).

On June 5, 1980, T-145 was again performed and revealed a leakage rate of 10.37 pounds per hour or 249 pounds per day. A letter was sent to the Nuclear Regulatory Commission explaining the situation and requesting temporary relief from LCO 4.2.9, permitting up to 700 pounds per day instead of 400 pounds per day for the suspected internal leakage path.

The Nuclear Regulatory Commission granted the requested temporary relief, agreed to the four administrative controls proposed by Public Service Company, and added one additional administrative control. The five administrative controls agreed to are as follows:

1. SR 5.3.7, Secondary Coolant Activity, be conducted once each 72 hours in lieu of once per week.
2. A pressure decay test be conducted for the Loop 2 steam generator penetration closures on a weekly basis. This pressure decay test was utilized to determine the leakage rate. Leakage rate increases of 25% over previous values required conducting pressure decay tests daily until it was established that the leak rate had reached an equilibrium value within the 700 pounds per day.
3. SR 5.2.16, PCRV Closure Leakage, be conducted once every two weeks for Loop 2 steam generator penetration closure rather than monthly as a comparison to the pressure decay tests.
4. Radiation process monitors for the reheat steam system will be monitored once per shift for indication of primary coolant leakage into the secondary system.
5. Check and record the interspace differential pressure once per shift to comply with LCO 4.2.7.

To collect all the required data, T-145 was expanded and renumbered T-147. Both T-147 and SR 5.2.16 were performed during each power increase, as required, and also as the leakage appeared to be somewhat dependent on power level.

The leakage was within the 700 pounds per day limit, except for three occasions during power level increases:

1. On February 23, 1981, SR 5.2.16a-M was performed and indicated 902.4 pounds per day leakage. Test T-147 was performed as part of this surveillance and indicated the leakage to be 680.4 pounds per day. Later the same day, T-147 was again performed and indicated the leakage to be 777.6 pounds per day.
2. On February 25, 1981, T-147 was performed and indicated leakage of 709.7 pounds per day.

3. On March 4, 1981, T-147 was performed and indicated leakage of 709.7 pounds per day.

Plant operation was changed in each of these three situations and the leakage rate was reduced to less than the 700 pound per day limit.

On March 21, 1981, at 0227 hours, during plant testing, a turbine trip occurred. Prior to this trip, reactor power had been 69%, and the Loop 2 steam generator interspace leakage rate had been 568 pounds per day. The plant was restored to a stable condition, power increased, and the generator placed back on line at 0702 hours the same day. Reactor power was increased, and normal plant operation resumed during the remainder of the day shift. At 1600 hours, T-147 was performed and indicated the steam generator interspace leakage to be 1312 pounds per day at 57% reactor power. Various changes were made to plant operations, but the steam generator interspace leakage rate remained above the 700 pounds per day limit. An orderly plant shutdown was initiated at 1832 hours with the turbine generator off line at 0358 hours on March 22, 1981, and the reactor manually scrammed from approximately 2% power at 1145 hours. The reactor was depressurized and investigation began on the cause of the excessive steam generator Loop 2 interspace leakage.

CAUSE

DESCRIPTION:

Other.

The purified helium leakage was internal to the Loop 2 steam generator penetration and occurred between the penetration interspace and the cold reheat steam piping internal to the penetration (see Figure 1).

CORRECTIVE

ACTION:

Public Service Company Change Notice (CN) 1436 was initiated in November, 1981, and has installed instrumentation, piping, valves, and control equipment to allow operation of the steam generator penetration interspaces at a pressure slightly greater than cold reheat but less than reactor pressure. Additional capability to monitor the interspace helium was also provided. These modifications maintain steam generator interspace helium leakage to within the limits of LCO 4.2.9.

Revisions to the Fort St. Vrain Technical Specifications, LCO 4.2.7 and LCO 4.2.9, were proposed by Public Service Company in January, 1982, and approved by the Nuclear Regulatory Commission in March, 1982, as Amendment No. 26 to the Fort St. Vrain Facility Operating License DPR-34.

Amendment No. 26 revised the Technical Specifications to:

- (1) permit the interspace between primary and secondary closures of the steam generator modules to be maintained at a pressure slightly above cold reheat steam pressure; and
- (2) set a limit on the possible release of primary coolant activity through the primary closure seals of no greater than 1.4 curies per day.

No further corrective action is anticipated or required.




FIGURE 1 - STEAM GENERATOR - REACTOR - MAIN STEAM OUTLET	
DATE	12/27/1
BY	6 OF 51
REVISIONS	
NO.	DESCRIPTION
1	REVISION
2	REVISION
3	REVISION
4	REVISION
5	REVISION
6	REVISION
7	REVISION
8	REVISION
9	REVISION
10	REVISION

Prepared By: Duane L. Frye
Duane L. Frye
Senior Technical Services Technician

Reviewed By: Frank J. Novachek
Frank J. Novachek
Technical Services Engineering Supervisor

Reviewed By: L. Milton McBride
L. M. McBride
Station Manager

Approved By: Don Warembourg
Don Warembourg
Manager, Nuclear Production