

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)

Turkey Point Plant - Unit 4

DOCKET NUMBER (2)

0 5 0 0 0 2 5 1 1 OF 0 1

PAGE (3)

TITLE (4)

Engineered Safety Features Actuation - Containment and Control Room Ventilation Isolation

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)			
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)	
03	07	84	84	004	000	04	05	84	N/A		0 5 0 0 0	
THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)												
OPERATING MODE (9)			20.4C2(b)			20.406(c)			50.73(a)(2)(iv)			73.71(b)
POWER LEVEL (10)			20.406(a)(1)(i)			50.36(c)(1)			50.73(a)(2)(v)			73.71(c)
			20.406(a)(1)(ii)			50.36(c)(2)			50.73(a)(2)(vii)			OTHER (Specify in Abstract below and in Text, NRC Form 365A)
			20.406(a)(1)(iii)			50.73(a)(2)(i)			50.73(a)(2)(viii)(A)			
			20.406(a)(1)(iv)			50.73(a)(2)(ii)			50.73(a)(2)(viii)(B)			
			20.406(a)(1)(v)			50.73(a)(2)(iii)			50.73(a)(2)(x)			

LICENSEE CONTACT FOR THIS LER (12)

NAME

Jesus Arias, Jr., Regulation and Compliance Lead Engineer

TELEPHONE NUMBER

AREA CODE

3 0 5 2 4 5 - 2 9 1 0

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC

SUPPLEMENTAL REPORT EXPECTED (14)

☐ YES (If yes, complete EXPECTED SUBMISSION DATE) ☒ NO

EXPECTED SUBMISSION DATE (15)

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

While performing routine shutdown operations, OP 0205.2, on Unit 4, a containment purge was initiated in preparation for personnel containment entry. While purging, a spurious signal (spike) to Process Radiation Monitor R-II, actuated the containment and control room ventilation system's logic thus closing the purge valves and placing the control room ventilation system in the recirculation mode. No abnormal levels of activity were detected in containment. The R-II alarm was reset and the containment purge was re-initiated. The control room ventilation system was returned to normal operating mode.

A significant event notification was made to NRCOC via ENS.

The health and safety of the public were not affected. Similar occurrences: None.

8404100236 840405
PDR ADOCK 05000251
S PDR



April 5, 1984
PNS-LI-84-118

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Gentlemen:

Re: Reportable Event 84-04
Turkey Point Unit 4
Date of Event: March 7, 1984
Engineered Safety Feature Actuation-
Containment and Control Room Ventilation Isolation

The attached Licensee Event Report is being submitted pursuant to the requirements of 10 CFR to provide notification of the subject event.

Very truly yours,

A handwritten signature in dark ink, appearing to read "J. W. Williams, Jr.", is written over a horizontal line.

J. W. Williams, Jr.
Vice President
Nuclear Energy

JWW/PLP/js

Attachment

cc: J. P. O'Reilly, Region II, USNRC
Harold F. Reis, Esquire
File 933.1 TP

IE22
1/1