

Arizona Public Service Company

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

April 3, 1984
ANPP-29213-BSK/TRB

U. S. Nuclear Regulatory Commission
Region V
Creskside Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, CA 94596-5368

Attention: Mr. T. W. Bishop, Director
Division of Resident
Reactor Projects and Engineering Programs

Subject: Interim Report - DER 84-11
A 50.55(e) Potentially Reportable Deficiency Relating to
Conduit Used In PVMP Instrumentation Is Contaminated.
File: 84-019-026; D.4.33.2


Reference: Telephone Conversation between P. Johnson and T. Bradish on
March 8, 1984

Dear Sir:

The NRC was notified of a potentially reportable deficiency in the
referenced telephone conversation. At that time, it was estimated that a
determination of reportability would be made within thirty (30) days.

Due to the extensive investigation and evaluation required, an Interim
Report is attached. It is now expected that this information will be
finalized by May 29, 1984, at which time a complete report will be
submitted.

Very truly yours,



E. E. Van Brunt, Jr.
APS Vice President, Nuclear
ANPP Project Director

EEVB/TRB:db
Attachment

cc: See Page Two

8404130274 840403
PDR ADOCK 05000528
S PDR

RECEIVED
APR 11 1984

1E-2711

Mr. T. W. Bishop
DER 84-11
Page Two

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
W. E. Ide
D. B. Fasnacht
A. C. Rogers
B. S. Kaplan
L. A. Souza
J. Vorees
J. R. Bynum
P. P. Klute
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
H. D. Foster
D. R. Hawkinson
L. E. Vorderbrueggen
G. A. Fiorelli
S. R. Frost
J. Self
D. Canady

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, GA 30339

INTERIM REPORT - DER 84-11
POTENTIAL REPORTABLE DEFICIENCY
ARIZONA PUBLIC SERVICE COMPANY (APS)
PVNGS UNITS 1

I. Potential Problem

It has been determined by chemical analysis that the conduit used in the installation of the PVMP instrumentation is contaminated with chlorides, fluorides and other contaminants. The conduit was not cleaned internally prior to it being installed on the CEA shroud both in Newington and at the PVNGS site. The possibility exists for contamination of the RCS.

II. Approach To and Status of Proposed Resolution

Bechtel Engineering is currently corresponding with Combustion Engineering to determine reportability and technical justification for corrective action.

III. Projected Completion of Corrective Action and Submittal of the Final Report

Evaluation of this condition and submittal of the Final Report is forecast to be completed by May 29, 1984.