

## LICENSEE EVENT REPORT

CONTROL BLOCK: 

--	--	--	--	--	--

  
                    1                                6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME						LICENSE NUMBER						LICENSE TYPE					EVENT TYPE							
01	N	Y	N	M	P	1			-					-			4	1	1	1	1	0	1	
7	8	9				14	15										25	26				30	31	32

  

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE					REPORT DATE										
01	CON'T	M	I	L	L	0	5	0	-	0	2	2	0	0	9	1	3	7	5	1	0	0	1	7	5
7	8	57	58	59	60	61								68	69					74	75				80

### EVENT DESCRIPTION

02	During a routine reactor shutdown for refueling and with 200 psig reactor pressure,	80
7 8 9		
03	the Drywell Floor Drain leakage increased above 5 gpm. An operator was sent	80
7 8 9		
04	into the drywell to investigate and found a leak on #15 Reactor Recirculation	80
7 8 9		
05	Pump Motor Cooling Line (Not a part of the Reactor Coolant Boundary).	80
7 8 9		
06		80
7 8 9		

AOR 75-26

DDME

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION			
0	7	W	G	E	Z	Z	Z	Z	Z	Z	N	Z	Z	Z	Z	N
7	8	9	10	11	12				17		43	44				48

## CAUSE DESCRIPTION

08	Leak to be repaired. Insulated bushing in pump oil cooling system was the cause	80
09	of leak. Part will be replaced.	80
10		80

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	G	0	0	0	380°F Shutting down		a	Rate of rise instrument (Analog)		
7	8	9	10	11	12	13	44	45	46	80

  

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
12	Z	0	N/A				
7	8	9	10	11	44	45	80

## PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION	
13	0	0	0	Z	N/A

## PERSONNEL INJURIES

NUMBER				DESCRIPTION
14	0	0	0	N/A

DESTRUCTIVE CONSEQUENCES	Probable
--------------------------	----------

19	None
7 8 9	

## LOSS OR DAMAGE TO FACILITY

PUBLCITY		8302180138 751001
17	None	PDR ADOCK 05000220
		S PDR

### ADDITIONAL FACTORS

NAME: Thomas J. Dente

PHONE (315) 343-2110