

EVENT DESCRIPTION (continued)

The bypass valve was opened again to allow additional flow.

Modifications are underway which will ensure drywell pressurization by means of compressed air. These were the first reported events of this type, (050-237/1976-7)

CAUSE DESCRIPTION (continued)

flow to the drywell. Portable heaters were used to remove ice from the evaporator.



Commonwealth Edison

Dresden Nuclear Power Station

R.R. #1

Morris, Illinois 60450

Telephone 815/942-2920

BBS Ltr. #260-76

March 29, 1976



Mr. James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Enclosed please find Reportable Occurrence number 50-237/1976-7.
This report is being submitted to your office in accordance with the
Dresden Nuclear Power Station Technical Specifications, Section 6.6.B.

B. B. Stephenson
Station Superintendent
Dresden Nuclear Power Station

BBS:smp

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC

3349