

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

PLEASE PRINT ALL REQUIRED INFORMATION

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
G1 F I L T P S 4										0 0 - 0 0 0 0 0 - 0 0										4 1 1 1 1					0 3	
8 9 14 15 25 25 31 32																										
CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER										EVENT DATE					REPORT DATE							
01 CONT		L	L	0 5 0 - 0 2 5 1										0 7 2 6 7 6					0 8 2 4 7 6							
7 8		57 58	59 60	61 65 69 74 75																						

## EVENT DESCRIPTION

02 During normal steady state operation, the No. 4 Generator was tripped by  
 03 generator lockout action. The startup transformer breaker (4B 4160  
 04 Volt Bus No. 4W26456) failed to close during the automatic transfer  
 05 sequence from the auxiliary transformer. This left the 4B 4160 Volt Bus  
 06 deenergized. Inspection of the breaker showed that the HH switch was not

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					POWER COMPONENT SUPPLIER	COMPONENT MANUFACTURER			VIOLATION
07 E B		E	C K T B R K					N	W 1 2 0			N
7 8 9 10		11	12 17					43	44 47			43

## CAUSE DESCRIPTION

08 Inspection of the breaker showed that the HH switch was not making  
 09 proper contact which prevented the breaker from closing. The breaker was  
 10 lowered then raised to establish contact. The followup investigation

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11 E		1 0 0		N/A				N/A	
7 8 9		10 12 13		44 45		45			
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
12 Z		Z		N/A		N/A			
7 8 9		10 11		44 45					

## PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
13 0 0 0	Z	N/A
7 8 9	11 12	13

## PERSONNEL INJURIES

NUMBER	DESCRIPTION
14 0 0 0	N/A
8 9	11 12

## PROBABLE CONSEQUENCES

15	N/A
7 8 9	

## LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION
16 Z	
7 8 9	10

## PUBLICITY

17	
7 8 9	

8304040027 760824  
 PDR ADOCK 05000251  
 S PDR

## ADDITIONAL FACTORS

18 See Page Two for continuation of Event Description and Cause Description

19	
7 8 9	

NAME: R. S. Abraham

PHONE: 305/552-3779

Reportable Occurrence 251-76-6  
Licensee Event Report  
Page Two

---

Event Description (continued)

making full contact which prevented the breaker from closing. Previous occurrences involving this type breaker have been described in Reports 3-72-3, 3-72-4, 250-74-2, 250-75-4, 250-75-5, 250-75-6, 251-75-8 and 250-76-2. (251-76-6)

Cause Description (continued)

being conducted by the Off-Site Support Staff as mentioned in Report 250-76-2 will include the operation of this switch.



October 6, 1976

PRN-LI-76-250

Mr. Norman C. Moseley, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
230 Peachtree Street, N. W., Suite 818  
Atlanta, Georgia 30303



Dear Mr. Moseley:

**50-251**

REPORTABLE OCCURRENCE 251-76-6  
TURKEY POINT UNIT 4  
DATE OF OCCURRENCE: JULY 26, 1976

CORRECTION

A Licensee Event Report for the subject occurrence was sent to you on August 25, 1976. The last sentence of the Cause Description stated that a followup investigation was being conducted as mentioned in previous Reportable Occurrence Report 250-72-2. The referenced report number is incorrect and should be changed to 250-76-2. A corrected Licensee Event Report is attached.

Very truly yours,

*J. R. Bensen*  
John D. Schmidt  
Vice President  
Power Resources

MAS/cpc

Attachment

cc: Jack R. Newman, Esquire  
Director, Office of Inspection and Enforcement (40)  
Director, Office of Management Information and  
Program Control (3)

10440

COPY SENT REGION

CONTROL BLOCK:

2

6

LICSNSFF

LICENSE NUMBER

LICENSE  
TYPE

EVENT

NAME					LICENSE NUMBER										TYPE					TYPE					
0	1	F	L	T	P	S	4	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	3
7	8	9					14	15									25	26					30	31	32

C1 CONT		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER				EVENT DATE				REPORT DATE											
7	8	57	58	59	60	0	5	0	-	0	2	5	1	0	7	2	6	7	6	0	8	2	4	7	6

02 During normal steady state operation, the No. 4 Generator was tripped by  
03 generator lockout action. The startup transformer breaker (4B 4160  
04 Volt Bus No. 4W26456) failed to close during the automatic transfer  
05 sequence from the auxiliary transformer. This left the 4B 4160 Volt Bus  
06 deenergized. Inspection of the breaker showed that the HH switch was not

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION	
07	E B	E	C	K	T	B	R	K	N	W	1	2	0	N
7	8 9 10	11	12					17	43	44			47	48

7 8 9 Inspection of the breaker showed that the HH switch was not making  
7 8 9 proper contact which prevented the breaker from closing. The breaker was  
7 8 9 lowered then raised to establish contact. The followup investigation

11	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60
FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION																																										
E			100			N/A						N/A																																										
FORM OF ACTIVITY RELEASED			CONTENT OF RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE																																													
Z			Z			N/A			N/A																																													

NUMBER				TYPE	DESCRIPTION	
1	3	0	0	0	Z	N/A

NUMBER			DESCRIPTION
14	0	0	N/A

15	8	9	N/A	80
----	---	---	-----	----

TYPE		DESCRIPTION
15	Z	
8	9	10

117 | *Handwritten signature* | 89

1B See Page Two for continuation of Event Description and Cause Description.

19 89

NAME: R. S. Abraham

PHONE: 305/552-3779

Reportable Occurrence 251-76-6  
Licensee Event Report  
Page Two


Event Description (continued)

making full contact which prevented the breaker from closing. Previous occurrences involving this type breaker have been described in Reports 3-72-3, 3-72-4, 250-74-2, 250-75-4, 250-75-5, 250-75-6, 251-75-8 and 250-76-2. (251-76-6)

Cause Description (continued)

being conducted by the Off-Site Support Staff as mentioned in Report 250-72-2 will include the operation of this switch.





FLORIDA POWER & LIGHT COMPANY

IE FILE COPY

August 25, 1976

PRN-LI-76-228

Mr. Norman C. Moseley, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
23<sup>rd</sup> Peachtree Street, N. W., Suite 818  
Atlanta, Georgia 30303

Dear Mr. Moseley:

REPORTABLE OCCURRENCE 251-76-6  
TURKEY POINT UNIT 4  
DATE OF OCCURRENCE: JULY 26, 1976

MALFUNCTION OF 4B  
STARTING TRANSFORMER BREAKER

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide 30 day notification of the subject occurrence.

Very truly yours,

A. D. Schmidt  
Vice President  
Power Resources

RSA/cpc

Attachment

cc: Jack R. Newman, Esquire  
Director, Office of Inspection and Enforcement (40)  
Director, Office of Management Information and  
Program Control (3)

COPY SENT REGION

9159