

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE										EVENT TYPE									
01 7 8 9 14 15 25 26 30 31 32										0 0 - 0 0 0 0 0 - 0 0										4 1 1 1 1										0 3									
CATEGORY										DOCKET NUMBER										EVENT DATE										REPORT DATE									
01 57 58										0 5 0 - 0 2 5 0 61 68 69										0 5 1 9 7 6 74 75										0 6 1 8 7 6 80									

EVENT DESCRIPTION

02 While performing operating procedure 14004.4, output number 1 of pres-																																																																																																			
03 surizer level comparator LC-459A was found to be tripping at 4.685 volts																																																																																																			
04 instead of at the upper limit of 4.680 volts. Technical Specification																																																																																																			
05 2.3 requires the high pressurizer water level trip setting to be less																																																																																																			
06 than or equal to 92% of full scale, but 4.685 volts is equivalent to																																																																																																			
07																																																																																																			
SYSTEM CODE										CAUSE CODE										COMPONENT CODE										PRIME COMPONENT SUPPLIER										COMPONENT MANUFACTURER										VIOLATION																																																	
I A										E										I N S T R U										N										H O 2 O										Y																																																	

CAUSE DESCRIPTION

08 The cause of the occurrence was setpoint drift. The trip setpoint which																																																																																																			
09 was initially set at the upper limit of 4.680 volts, is now being set																																																																																																			
10 at a more conservative value to allow for normal setpoint drift.																																																																																																			

FACILITY STATUS										% POWER										OTHER STATUS										METHOD OF DISCOVERY										DISCOVERY DESCRIPTION									
E										1 0 0										N/A										b										N/A									
FORM OF ACTIVITY RELEASED										CONTENT OF RELEASE										AMOUNT OF ACTIVITY										LOCATION OF RELEASE																			
Z										Z										N/A										N/A																			

PERSONNEL EXPOSURES

NUMBER										TYPE										DESCRIPTION									
0 0 0										Z										N/A									

PERSONNEL INJURIES

NUMBER										DESCRIPTION									
0 0 0										N/A									

PROBABLE CONSEQUENCES

15 N/A																																																																																																			
--------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

LOSS OR DAMAGE TO FACILITY

TYPE										DESCRIPTION									
Z										N/A									

PUBLICITY

17 N/A																																																																																																			
--------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

ADDITIONAL FACTORS

18 See page two (2) for continuation of Event Description.																																																																																																			
--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

19																																																																																																			
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

NAME: M. A. SCHOPPMAN


PHONE: 305/552-3779

8304040116 760618
PDR ADOCK 05000250
S PDR

REPORTABLE OCCURRENCE 250-76-3
LICENSEE EVENT REPORT
PAGE TWO

Event Description (Continued)

92.125%. Redundant protection channels LC 460A and LC 461A were available. Comparator LC 459A was recalibrated and the trip setpoint was verified to be within specification. This was the first occurrence of this type (250-76-3).



June 18, 1976
PRN-LI-76-151

Mr. Norman C. Moseley, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N.W., Suite 818
Atlanta, Georgia 30303

Dear Mr. Moseley:

REPORTABLE OCCURRENCE 250-76-3
TURKEY POINT UNIT 3
DATE OF OCCURRENCE: MAY 19, 1976

SETPOINT DRIFT

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide 30-day notification of the subject occurrence.

Very truly yours,

A. D. Schmidt
Vice President
Power Resources

MAS/ao

Attachment

cc: Jack R. Newman, Esquire
Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)



COPY SENT REGION

6725