

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME		LICENSE NUMBER										LICENSE TYPE					EVENT TYPE								
01	F	L	T	P	S	3	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	3	
7	8	9				14	15											25	26				30	31	32

CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER										EVENT DATE					REPORT DATE							
01	CONT			L	L	0	5	0	-	0	2	5	0	0	2	1	9	7	6	0	3	1	9	7	6			
7	8	57	58	59	60	61	68										69	74					75	80				

EVENT DESCRIPTION

02	During normal steady state operation, water was found leaking from the																								80
03	3A charging pump. The pump was removed from service. The pump was dis-																								80
04	mantled and a crack was found in the pump casing between one of the																								80
05	valve chambers and its stuffing box. The crack was weld repaired and																								80
06	the pump was returned to standby service. Redundant charging pumps 3B																								80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE								PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER					VIOLATION	
07	P	C	E	P	U	M	P	X	X	N	U	0	5	5	N					
7	8	9	10	11	17								43	47					48	

CAUSE DESCRIPTION

08	The cause of the crack in the casing of the 3A charging pump, Type TX150,																								80
09	has not been determined. After weld repair, the pump was operated for a																								80
10	short period of time without exhibiting observable leakage. A new pump																								80

FACILITY STATUS		% POWER		OTHER STATUS								METHOD OF DISCOVERY		DISCOVERY DESCRIPTION										
11	E	1	0	0	NA								b	Routine visual inspection.										
7	8	9	10	12	13								44	45	46									

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY								LOCATION OF RELEASE											
12	Z	Z	NA								NA												
7	8	9	10	11	44								45	80									

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION										
13	0	0	0	Z	NA									
7	8	9	11	12	13									

PERSONNEL INJURIES

NUMBER		DESCRIPTION											
14	0	0	0	NA									
7	8	9	11	12									

PROBABLE CONSEQUENCES

15	NA																								80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION										
16	Z	NA										
7	8	9	10									

PUBLICITY

8304040130 760319																								80
PDR ADDCK 05000250																								80
S PDR		NA																						80

ADDITIONAL FACTORS

18	See page two for continuation of Event and Cause descriptions.																								80
19																									80

NAME: M. A. SCHOPPMAN

PHONE: 305/552-3779

Reportable Occurrence 250-76-1
Licensee Event Report
Page Two

Event Description (continued)

and 3C were operable throughout this occurrence. This was the first occurrence of this type at Turkey Point. (250-76-1).

Cause Description (continued)

casing is on order and when it arrives, the pump will be rebuilt.



March 19, 1976

PRN-LI-76-56



Mr. Norman C. Moseley, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N.W., Suite 818
Atlanta, Georgia 30303

Dear Mr. Moseley:

REPORTABLE OCCURRENCE 250-76-1
TURKEY POINT UNIT 3
DATE OF OCCURRENCE: FEBRUARY 19, 1976

LEAKAGE FROM 3A CHARGING PUMP

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide 30-day notification of the subject occurrence.

Very truly yours,

for A. D. Schmidt
A. D. Schmidt
Vice President
Power Resources

MAS/ms

Attachment

cc: Jack R. Newman, Esquire
Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)

3038