

CONTROL BLOCK:

							1
--	--	--	--	--	--	--	---

 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

SYSTEM CODE 0 9		CAUSE CODE C I		CAUSE SUBCODE A		COMPONENT CODE X I N S T R U						COMP SUBCODE C		VALVE SUBCODE Z			
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22		
LER NO REPORT NUMBER		EVENT YEAR 8 3		SEQUENTIAL REPORT NO. 0 5 3		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0							
23	24	25	26	27	28	29	30	31	32								
ACTION TAKEN E		FUTURE ACTION X		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED Y		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER A		COMPONENT MANUFACTURER N 3 0 5	
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50

ISSUED DESCRIPTION (45) NA

714/492-7700

ATTACHMENT TO LER 83-053
SOUTHERN CALIFORNIA EDISON COMPANY
SAN ONOFRE NUCLEAR GENERATION STATION
UNIT NO. 2, DOCKET NO. 50-361

SUPPLEMENTAL INFORMATION FOR CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

The low setpoint value of Monitor RI-7807C is an isolated occurrence and no further corrective action is required.

An evaluation to prevent unauthorized manipulation of the setpoint controller is in progress and appropriate corrective actions will be taken. The placement of locking setscrews on the setpoint potentiometers is under consideration.

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY

STATION MANAGER

June 20, 1983

RECEIVED
MPC
SCE
1983 JUN 23 AM 11:06
REGION V
TELEPHONE
(714) 492-7700

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator

Dear Sir:

Subject: Docket No. 50-361
30-Day Report
Licensee Event Report No. 83-053
San Onofre Nuclear Generating Station, Unit 2

Pursuant to Section 6.9.1.13.b of Appendix A, Technical Specifications to Facility Operating License NPF-10 for San Onofre Unit 2, this submittal provides the required 30-day written report and a copy of the Licensee Event Report (LER) form for an occurrence involving Limiting Condition for Operation (LCO) 3.4.5.1 associated with the containment atmosphere gaseous radioactivity monitoring system. Enclosed LER 83-053 addresses this event, including corrective actions and measures to prevent recurrence.

If there are any questions regarding this event, please so advise.

Sincerely,



Enclosure: LER 83-053

11 IE-22

Mr. J. B. Martin

-2-

June 20, 1983

cc: A.E. Chaffee (USNRC Resident Inspector, Units 2 and 3)
R.J. Pate (USNRC Resident Inspector, Units 2 and 3)
J.P. Stewart (USNRC Resident Inspector, Units 2 and 3)

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission
Office of Management Information and Program Control (MIPC)

Institute of Nuclear Power Operations (INPO)