

DUKE POWER COMPANY

P.O. BOX 33189

CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

TELEPHONE  
(704) 373-4531

84 JUL 18 1984

Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

Re: Oconee Nuclear Station  
Docket Nos. 50-269, 270, 287  
IE Bulletin 84-02


Dear Sir:

In response to IE Bulletin 84-02 dated March 12, 1984 concerning recent failures of the General Electric type HFA Relays in use in Class IE Safety Systems, please find attached a report for Oconee Nuclear Station pursuant to Action Item 1d of the bulletin.

In addition to the written report requested per Action Item 1d, the results of a generic review of the general concerns expressed in the bulletin were also to be provided. This review is still in progress and the results will be provided shortly after the completion of the investigation.

I declare under penalty of perjury that the information contained herein is correct to the best of my knowledge as executed on July 13, 1984.

Very truly yours,



Hal B. Tucker

PFG/rhs

Attachment

cc: Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. J. C. Bryant  
NRC Resident Inspector  
Oconee Nuclear Station

8407260323 840713  
PDR ADOCK 05000269  
Q PDR

Ms. Helen Nicolaras  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

11/11

DUKE POWER COMPANY  
OCONEE NUCLEAR STATION

Response  
to  
IE Bulletin 84-02

Action Item 1a

Develop plans and schedules for replacing (1) nylon or Lexan coil spool-type HFA relays used in normally energized safety-related\* applications and (2) nylon coil spool-type HFA relays used in normally de-energized safety-related applications. The replacement relays and any replacements made in the future should meet the requirements of the applicable IEEE standards. The replacement program for energized and de-energized relays should be performed on a "best efforts" basis during plant outages of sufficient duration. The entire replacement program should be completed within two years from the date of this bulletin.

The replacement schedule should consider the following recommended priority:

Nylon or Lexan normally energized in the reactor trip system  
Nylon or Lexan normally energized in other safety-related applications  
Nylon normally de-energized in the reactor trip system  
Nylon normally de-energized in other safety-related applications

Response 1a

A station modification has been initiated to replace all GE type HFA 51A relays used in normally energized as well as normally de-energized safety-related applications. The scheduled completion date for the modification to replace all GE type HFA 51A relays used in safety related applications is March 1, 1986.

Action Item 1b

During the period before relay replacement, develop and implement surveillance plans that include:

- (1) Monthly functional tests of all reactor trip system normally energized relays that verify relay contacts change state when the relay coil is de-energized;
- (2) Visual inspections of all safety-related normally energized relays as soon as practical upon receipt of this bulletin. Thereafter, similar inspections should be accomplished in

conjunction with the monthly functional test. These visual inspections should verify that relay coils are not deteriorating (e.g., inspect coil bobbins for visible cracks or melting), and should confirm cleanliness of the relay pole pieces.

Response 1b

A review was performed and it was determined that there are no GE type HFA relays used in the Reactor Protective System (RPS). Therefore, monthly functional tests of the normally energized relays in the RPS trip systems is not applicable. An inspection of all GE HFA relays in safety-related applications was performed on June 18, 1984. The results of the inspection confirmed the cleanliness of the relay poles and verified that no relay coil deterioration had occurred. A monthly inspection will be performed on all GE HFA safety-related normally energized relays to assure that the relay coils are not deteriorating. This monthly inspection is to be initiated July 1984, and will continue until all GE HFA relays are installed in safety-related applications.

Action Item 1c

Provide a basis for continuing operation for the period of time until the normally energized relays are replaced. This basis should include a discussion of those measures addressed in Items 1a and 1b and any other preventive and/or corrective measures taken or planned.

Response 1c

The initial inspection confirmed the cleanliness of the relay poles and verified that no relay coil deterioration had occurred. The monthly inspection program initiated in July 1984, shall ensure that the relays will operate properly. There are no GE HFA relays installed in the RPS. Furthermore, a review of the maintenance records indicate that these relays have not been a problem. Based on the above discussion, the continued safe operation of Oconee during the period of time that it will take to replace all of the GE HFA relays used in safety-related applications is assured.