

May 4, 1984
(NMP2L 0048)

Mr. R. W. Starostecki, Director
U. S. Nuclear Regulatory Commission
Region I
Division of Project and Resident Programs
631 Park Avenue
King of Prussia, PA 19406

Dear Mr. Starostecki:

SUBJECT: Nine Mile Point Unit 2
Docket No. 50-410

Enclosed is an interim report in accordance with 10CFR50.55(e) for the problem concerning Rosemount 510DU Racks (55(e)-84-15). This problem was reported in a telephone conversation between Mr. S. Collins, of your staff, and Mr. T. Loomis (Nine Mile Point Unit 2 Licensing) on April 2, 1984.

Very truly yours,

C. V. Mangan

C. V. Mangan
Vice President
Nuclear Licensing Engineering

CVM/TRL:1f

cc: Director of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, DC 20555

R. Gramm (NRC Resident Inspector)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
DOCKET NO. 50-410

Interim Report for a Problem Concerning Rosemount
510DU Racks (55(e)-84-15)

Description of the Problem

The problem concerns Rosemount 510DU racks installed at Nine Mile Point Unit 2 which are not attached to the rear unistrut supports. During a seismic event, the safety-related racks could be rendered inoperable.

This problem was identified to Niagara Mohawk in General Electric Field Deviation Disposition Request No. KG1-1955.

A final report concerning this issue will be submitted by July 18, 1984.