

Arizona Public Service Company

May 14, 1984  
ANPP-29493-TDS/TRB

U. S. Nuclear Regulatory Commission  
Region V  
Creskide Oaks Office Park  
1450 Maria Lane - Suite 210  
Walnut Creek, CA 94596-5368

Attention: Mr. T. W. Bishop, Director  
Division of Resident  
Reactor Projects and Engineering Programs

Subject: Interim Report - DER 84-23  
A 50.55(e) Potentially Reportable Deficiency Relating to  
Auxiliary Feed Water Pump 'B' Discharge Valve To The  
Condensate Storage Tank  
File: 84-019-026; D.4.33.2


Reference: Telephone Conversation between S. Long and T. Bradish on  
April 15, 1984

Dear Sir:

The NRC was notified of a potentially reportable deficiency in the referenced telephone conversation. At that time, it was estimated that a determination of reportability would be made within thirty (30) days.

Due to the extensive investigation and evaluation required, an Interim Report is attached. It is now expected that this information will be finalized by July 13, 1984, at which time a complete report will be submitted.

Very truly yours,



E. E. Van Brunt, Jr.  
APS Vice President, Nuclear  
ANPP Project Director

EEVB/TRB:db  
Attachment

cc: See Page Two

8405240038 840514  
PDR ADOCK 05000528  
S PDR

11  
1E-27

Mr. T. W. Bishop  
DER 84-23  
Page Two

cc: Richard DeYoung, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

T. G. Woods, Jr.  
D. B. Karner  
W. E. Ide  
D. B. Fasnacht  
A. C. Rogers  
B. S. Kaplan  
L. A. Souza  
D. E. Fowler  
J. Vorees  
J. R. Bynum  
J. M. Allen  
P. P. Klute  
A. C. Gehr  
W. J. Stubblefield  
W. G. Bingham  
R. L. Patterson  
R. W. Welcher  
H. D. Foster  
D. R. Hawkinson  
L. E. Vorderbrueggen  
G. A. Fiorelli  
S. R. Frost  
J. Self  
D. Canady

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, GA 30339

INTERIM REPORT - DER 84-23  
POTENTIAL REPORTABLE DEFICIENCY  
ARIZONA PUBLIC SERVICE COMPANY (APS)  
PVNGS UNIT 1, 2, 3

I. Potential Problem

The "B" Train Auxiliary Feedwater Discharge Valve (AFB-V027) to the Condensate Storage Tank had the potential to vibrate open due to a yoke sleeve pin loosening. The sleeve had not been properly doweled. If this had happened during operations, there would have been the potential for loss of flow to the Steam Generator due to flow circulating to the Condensate Storage Tank rather than the Steam Generator as required.

II. Approach To and Status of Proposed Resolution

Bechtel engineering is currently studying this problem to determine reportability and technical justification for correction.

III. Projected Completion of Corrective Action and Submittal of the Final Report

Evaluation of this condition and submittal of the Final Report is Forecast to be completed by July 13, 1984.