

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS MINNESOTA 55401

March 29, 1978

Mr J G Keppler, Director
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR 22

SBGTS "A" Train Low Flow

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2.b since it constitutes operation in a degraded mode for a period of time permitted by the Limiting Conditions for Operation.

Yours very truly,

L O Mayer

L O Mayer, PE
Manager of Nuclear Support Services

LOM/MHV/deh

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
MPCA
Attn: J W Ferman

780950030

9105230307 780329
PDR ADOCK 05000263
S PDR

-over-

A002/s *
1/40

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	N	M	N	P	1	2	0	0	-	1	0	0	0	0	0	-	1	0	0	3	4	1	1	1	1	4		5
LICENSEE CODE					LICENSEE NUMBER										LICENSEE TYPE					ST. CAT. NO.										

CONT

0	1	R	E	P	O	R	T	S	O	U	R	C	E	1	6	0	5	0	0	0	2	6	3	7	0	2	2	8	7	8	8	0	3	2	9	7	8	9
REPORT SOURCE					DOCKET NUMBER										EVENT DATE					REPORT DATE																		

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 DURING SURVEILLANCE TEST, MINIMUM FLOW IN "A" TRAIN SBGTS COULD NOT BE ATTAINED AS
0 3 REQUIRED BY T.S. 3.7.B.1. "B" TRAIN WAS SHOWN TO BE OPERATIONAL. ALSO ADEQUATE FLOW
0 4 WOULD HAVE BEEN OBTAINED THROUGH BOTH SBGTS UNDER AUTOMATIC INITIATION CONDITIONS.
0 5 NO EFFECT ON THE PUBLIC HEALTH AND SAFETY. PREVIOUS SIMILAR EVENT REPORTABLE OCCUR-
0 6 ENCE M-RO-77-13 DATE 6-23-77.

0	9	S	C	11	E	12	B	13	V	A	L	I	V	O	P	14	D	15	2	16	7	8	0	0	3	0	3	1	0	17	7	8	0	0	3	0	3	1	0					
SYSTEM CODE					CAUSE CODE					CAUSE SUBCODE					COMPONENT CODE					COMP SUBCODE					VALVE SUBCODE																			
EVENT YEAR					SEQUENTIAL REPORT NO.					OCCURRENCE CODE					REPORT TYPE					REVISION NO.																								
ACTION TAKEN					EFFECT ON PLANT					SHUTDOWN METHOD					HOURS					ATTACHMENT SUBMITTED					NPRD-4 FORM SUB					PRIME COMP SUPPLIER					COMPONENT MANUFACTURER									
A					E					Z					B					0					N					Y					X					M				

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 DILUTION FLOW FROM COMPRESSED STORAGE NOT ISOLATED BY BV-4 WHEN SBGTS "A" TRAIN
1 1 STARTED. FOREIGN MATERIAL IN BV-4 POSITIONER (MODEL 6608-004, 6" STROKE, DOUBLE
1 2 ACTING). REPLACED POSITIONER AND INSTALLED FILTER IN CYLINDER SUPPLY/RETURN LINE.

1	5	E	28	1	0	0	29	NA	30	B	31	MONTHLY SURVEILLANCE	32	NA	36									
FACILITY STATUS					% POWER					OTHER STATUS					METHOD OF DISCOVERY					DISCOVERY DESCRIPTION				
ACTIVITY RELEASED OR RELEASE					AMOUNT OF ACTIVITY					LOCATION OF RELEASE														
Z					Z					NA					NA									

1	7	0	0	37	2	38	NA	39						
PERSONNEL EXPOSURES NUMBER					TYPE					DESCRIPTION				

1	1	0	0	40	NA	41			
PERSONNEL INJURIES NUMBER					DESCRIPTION				

1	9	Z	42	NA	43				
LOSS OF OR DAMAGE TO FACILITY TYPE					DESCRIPTION				

2	0	N	44	NA	45				
PUBLICITY ISSUED					DESCRIPTION				

NAME OF PREPARER D. D. TILLYPHONE (612) 295-5151