

**LICENSEE EVENT REPORT**

EXHIBIT A

CONTROL BLOCK: 1		(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)																					
01	F L C R P 3	2	0	0	-	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4	8		
LICENSE CODE		LICENSE NUMBER										LICENSE TYPE					CAT						
CONT		REPORT SOURCE		DOCKET NUMBER										EVENT DATE					REPORT DATE				
01		L		6050-0302										7082780					8060184				
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10																							
02 While performing SP-320, Operability of Boron Injection Sources and Pumps,																							
03 DHV-111, "B" decay heat pump discharge throttle valve, would not control flow																							
04 in automatic. This created an event contrary to Technical Specification																							
05 3.5.2. DHV-111 did respond in manual control; decay heat loop "A" provided																							
06 redundancy. There was no effect upon the general public health or safety.																							
07 This is the second event of this type and the tenth report under this Speci-																							
08 fication.																							
09																							
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE					COMP. SUBCODE		VALVE SUBCODE										
C F 11		E 12		E 13		I N S T R U 14					C 15		Z 16										
17		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.													
LER/NO REPORT NUMBER		80		036		03		X		1													
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NRC-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER							
E 18		X 19		Z 20		Z 21		0000		Y 22		N 24		A 25		C 6 8 0 26							
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27																							
10 The cause is attributed to water in the sensing line. Operability was re-																							
11 stored by blowing down the sensing line and performing a functional check. An																							
12 engineering evaluation has determined the following additional corrective ac-																							
13 tions to be implemented: (1) replace existing flow switches with electronic																							
14 controls; (2) change out helical gears in valve actuators.																							
15																							
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION															
E 28		080		N/A		B 31		Operator Observation															
ACTIVITY RELEASED OF RELEASE		CONTENT		AMOUNT OF ACTIVITY		LOCATION OF RELEASE																	
Z 33		Z 34		N/A		N/A																	
PERSONNEL EXPOSURES		TYPE		DESCRIPTION																			
000		Z 37		N/A																			
PERSONNEL INJURIES		TYPE		DESCRIPTION																			
000		40		N/A																			
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION																			
Z 42		43		N/A																			
PUBLICATION		TYPE		DESCRIPTION																			
N 44		45		N/A																			
ISSUED		DESCRIPTION		N/A																			
20		46		N/A																			
<div style="display: flex; justify-content: space-between;"> <div> NAME OF PREPARER R. H. Thompson </div> <div> PHONE (904) 795-3802 </div> </div>																							

## SUPPLEMENTARY INFORMATION

REPORT NO. : 50-302/80-036/03X-1

FACILITY : Crystal River Unit 3

REPORT DATE : June 1, 1984

OCCURRENCE DATE: August 27, 1980

### IDENTIFICATION OF OCCURRENCE:

Failure to have two independent ECCS subsystems operable, contrary to Technical Specification 3.5.2.

### CONDITIONS PRIOR TO OCCURRENCE:

Mode 1, POWER OPERATION (80%)

### DESCRIPTION OF OCCURRENCE:

At 0300, during performance of SP-320, Operability of Boron Injection Sources and Pumps, it was discovered that DHV-111, "B" decay heat pump discharge throttle valve, would not control flow in automatic. DHV-111 did respond in manual control; maintenance actions were initiated.

### DESIGNATION OF APPARENT CAUSE:

The cause is attributed to water in the sensing lines.

### ANALYSIS OF OCCURRENCE:

There was no effect upon the general public health and safety. Redundancy was maintained by the "A" decay heat loop.

### CORRECTIVE ACTION:

The sensing lines were blown down and a functional check was completed. (The lines will be blown down after surveillance checks for three months to determine the extent of a condensation problem.) An engineering evaluation of the control system for DHV-111 and DHV-110 has determined the following additional corrective actions to be implemented:

1. Replace existing flow switches with electronic controls.
2. Change out helical gears in valve actuators.

### FAILURE DATA:

This is the second occurrence reported for DHV-111 and the tenth report made under this Specification.