

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Duane Arnold Energy Center										DOCKET NUMBER (2) 0 5 0 0 0 3 3 1 1					PAGE (3) 1 OF 02								
TITLE (4) RCIC Steam Supply Isolation																							
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)													
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES None				DOCKET NUMBER(S) 0 5 0 0 0										
0	5	0	7	8	4	8	4	0	1	8	0	0	0	6	0	7	8	4	0	5	0	0	0
OPERATING MODE (9) N		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																					
POWER LEVEL (10) 0 7 2		20.402(b)				20.406(c)				<input checked="" type="checkbox"/> 50.73(a)(2)(iv)				73.71(b)									
		20.406(a)(1)(i)				50.36(e)(1)				<input checked="" type="checkbox"/> 50.73(a)(2)(v)				73.71(c)									
		20.406(a)(1)(ii)				50.36(e)(2)				50.73(a)(2)(vii)				OTHER (Specify in Abstract below and in Text, NRC Form 366A)									
		20.406(a)(1)(iii)				50.73(a)(2)(i)				50.73(a)(2)(viii)(A)													
		20.406(a)(1)(iv)				50.73(a)(2)(ii)				50.73(a)(2)(viii)(B)													
		20.406(a)(1)(v)				50.73(a)(2)(iii)				50.73(a)(2)(x)													
LICENSEE CONTACT FOR THIS LER (12)																							
NAME James C. Smith, Technical Support Engineer										TELEPHONE NUMBER AREA CODE 3 1 9 8 5 1 - 7 3 0 8													
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																							
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDs		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDs													
A	B	N	R	L	Y	G	0	8	2	Y													
SUPPLEMENTAL REPORT EXPECTED (14)												EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR							
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)												<input checked="" type="checkbox"/> NO											

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

While operating at 72% power with steam line "C" isolated because of an inoperable inboard Main Steam Isolation Valve, a monthly surveillance test was being performed on the RCIC Steam Line High Differential Pressure (Steam Line Break Detection) system. While removing the cover from a RCIC Steam Leak High Differential Pressure Relay to perform one of the test steps, the relay was inadvertently jarred and the relay energized. This caused spurious RCIC isolation and RCIC turbine trip signals and closed the RCIC turbine inboard steam isolation valve. The RCIC system was in normal standby condition. Operators immediately reset the turbine trip signal and opened the turbine isolation valve. No changes in plant conditions were observed.

8406120386 840607  
PDR ADOCK 05000331  
S PDR

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Duane Arnold Energy Center	0500033184	01	8	0	0	2	OF 02

TEXT (If more space is required, use additional NRC Form 366A's) (17)

At 1602 hours on May 7, 1984, the plant was in run mode at 72% power with the "C" steam line isolated because of an inoperable inboard Main Steam Isolation Valve. A monthly surveillance test was being performed on the RCIC Steam Line High Differential Pressure (Steam Line Break Detection) system which required removing the cover from a relay in the RCIC Steam Leak Detection High Differential Pressure circuit (BN-RLY-E51A-K32). The relay was inadvertently jarred which caused it to be energized. RCIC isolation and turbine trip signals were received and the inboard turbine steam supply isolation valve (BN-ISV-2400) closed. The RCIC system was in normal standby mode at the time of the event. Operators immediately reset the turbine trip signal and reopened the valve.

Throughout the event, no changes in plant conditions were observed. HPCI was operable and available for high pressure coolant, and all low pressure systems and ADS were also operable. A search of past plant deviations revealed no other instances of RCIC turbine isolations or other spurious Type HGA relay actuations caused by jarring or vibrating the relays. However, when reviewing the event with Electrical Maintenance and involved technicians, it was stated that it is difficult to remove the covers from some of the Type HGA relays. This is caused by slight misalignment of the mounting spring tab clips on the sides of the covers.

Iowa Electric is currently conducting an engineering study to determine the feasibility of installing handwired test circuits and switches to perform safety related surveillance test procedures. These will be used instead of temporary jumpers and complicated test sequences that alter circuit configurations. A request has been made to specifically include HGA relays that meet the above criteria.

Note that this event is reportable under 10 CFR 50.73(a)(2)(IV) because an engineered safety feature (Containment Isolation) was initiated. It is also reportable under 10 CFR 50.73(a)(2)(V) as inoperability of single train Engineered Safety features (RCIC, EIS System BN).

Iowa Electric Light and Power Company

June 7, 1984  
DAEC-84- 344


U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

Subject: Duane Arnold Energy Center  
Docket No. 50-331  
Op. License DPR-49  
Licensee Event Report No. 84-018

Gentlemen:

In accordance with 10 CFR 50.73 please find attached a copy of the  
subject Licensee Event Report.

Very truly yours,



Daniel L. Mineck  
Plant Superintendent - Nuclear  
Duane Arnold Energy Center

DLM/JCS/kp

attachment

cc: Mr. James G. Keppler  
Regional Administrator  
Region III  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

NRC Resident Inspector - DAEC

File A-118a

IE22  
11