

LICENSEE EVENT REPORT

UPDATE REPORT:

PREVIOUS REPORT DATE: 1/05/83

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7	0	1	8	9	N	C	B	E	P	1	2	0	0	-	0	L	0	0	-	0	0	3	4	1	1	1	1	4			5				
				LICENSEE CODE								LICENSE NUMBER												LICENSE TYPE								57 CAT 58			

CON'T

REPORT SOURCE: 01 L 6 0 5 0 - 0 3 2 5 7 1 0 2 7 8 2 8 0 4 3 0 8 4 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During unit power operation, while investigating an event reported in LER 1-82-114, it was discovered that

0 3 RHR System discharge valves to the plant Radwaste System, 1-E11-F040 and F049, would not fully close.

0 4 Subsequent testing of those respective valves on Unit 2 on November 5, 1982, revealed the same condition.

0 5 In each case, both valves were declared inoperable, deactivated, and manually closed. These events did

0 6 not affect the health and safety of the public.

0 7

0 8 Technical Specifications 3.6.3, 6.9.1.9b

SYSTEM CODE S D 11		CAUSE CODE D 12		CAUSE SUBCODE Z 13		COMPONENT CODE V A L V O P 14		COMP. SUBCODE A 15		VALVE SUBCODE Z 16	
LER/RO REPORT NUMBER 17		EVENT YEAR 8 2 21 22		SEQUENTIAL REPORT NO. 1 1 6 24 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 2 32	
ACTION TAKEN G 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22 37 40		ATTACHMENT SUBMITTED N 23 41	
NPRD-4 FORM SUB. Y 24 42		PRIME COMP. SUPPLIER N 25 43		COMPONENT MANUFACTURER L 2 0 0 0 26 44 47							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Improperly assembled spring packs in the valves' operators, resulting from a deficient maintenance procedure,

1 1 caused the operators' motors to turn off at too low of a torque value. New spring packs were installed in

1 2 the F040 and F049 valve operators, Model Nos. SMB-000 and SMB-00, respectively, and the valves were

1 3 returned to service. On October 26, 1983, appropriate revisions to the subject maintenance procedure were

1 4 incorporated to help future similar events.

7	8	9	FACILITY STATUS		% POWER		OTHER STATUS		30	METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		32	80	
1	5	E	28	0	6	0	29	NA	B	31	Special Investigation				80	
7	8	9	ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		35	LOCATION OF RELEASE		36	80			
1	6	Z	33	Z	34	NA	44	45	46					80		
7	8	9	PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION		39	80				
1	7	0	0	0	37	Z	38	NA					80			
7	8	9	PERSONNEL INJURIES		NUMBER		DESCRIPTION		41	80						
1	8	0	0	0	40	NA					80					
7	8	9	LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION		43	80						
1	9	Z	42	NA					80							
7	8	9	PUBLICITY		ISSUED		DESCRIPTION		44	80						
2	0	N	44	8406190126 840430		PDR ADOCK 05000325		PDR		80						
7	8	9	NRC USE ONLY		68		69		80							

NAME OF PREPARED

M. J. Pastva, Jr.

PHONE

919-457-9521



Carolina Power & Light Company

MAY 3 P12:44
Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429
April 30, 1984

FILE: B09-13510C
SERIAL: BSEP/84-0893

Mr. James P. O'Reilly, Administrator
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street N.W.
Atlanta, GA 30303

BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1
DOCKET NO. 50-325
LICENSE NO. DPR-71
SUPPLEMENT TO LICENSEE EVENT REPORT 1-82-116

Dear Mr. O'Reilly:

In accordance with Section 6.9.1.9b of the Technical Specifications for Brunswick Steam Electric Plant, Unit 1, the enclosed supplemental Licensee Event Report is submitted. The original report fulfilled the requirement for a written report within thirty (30) days of a reportable occurrence and both are in accordance with the format set forth in NUREG-0161, July, 1977.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

RMP/jlh/LETJH1

Enclosure

cc: Mr. R. C. DeYoung
NRC Document Control Desk

OFFICIAL COPY

IE 22

11