



TUELECTRIC

Log # TXX-92046  
File # 10200  
Ref. # 10CFR50.73(a)(2)(v11)

February 19, 1992

William J. Cahill, Jr.  
Group Vice President

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)  
DOCKET NOS. 50-445  
INOPERABLE TRAIN/CHANNEL IN SAFETY RELATED SYSTEM  
LICENSEE EVENT REPORT 91-025-01

Gentlemen:

Enclosed is a supplement to Licensee Event Report 91-025-00 for Comanche Peak Steam Electric Station Unit 1, "Component Cooling Water Stop Check Valves Inoperable due to Less Than Adequate Preventive Maintenance."

This report is being provided to supplement the safety consequences and implications of the event, which were addressed during various discussions with your staff.

Sincerely,

William J. Cahill, Jr.

OB/tg

c - Mr. R. D. Martin, Region IV  
Mr. T. A. Bergman, NRR  
Mr. L. A. Yandell, Region IV  
Resident Inspectors, CPSES (2)

9202250330 920219  
PDR ADCK 05000445  
S PDR

P. O. Box 1002 Glen Rose, Texas 76043-1002

NRC FORM 308				U.S. NUCLEAR REGULATORY COMMISSION				APPROVED OMB NO. 3150-0104 EXPIRES 4/30/92			
<b>LICENSEE EVENT REPORT (LER)</b>								ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-300), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.			
Facility Name (1) <b>COMANCHE PEAK - UNIT 1</b>								Docket Number (2) <b>0151010101415</b>		Page (3) <b>1</b> of <b>017</b>	
Title (4) <b>COMPONENT COOLING WATER STOP CHECK VALVES INOPERABLE DUE TO LESS THAN ADEQUATE PREVENTIVE MAINTENANCE</b>											
Event Date (5)			LER Number (6)			Report Date (7)			Other Facilities Involved (8)		
Month	Day	Year	Year	Sequential Number	Revision Number	Month	Day	Year	Facility Names	Docket Numbers	
10	29	91	91	0215	01	10	21	99	N/A	015101010111	
This report is submitted pursuant to the requirements of 10 CFR § (Check one or more of the following) (11) <input type="checkbox"/> 20.402(b) <input type="checkbox"/> 20.405(c) <input type="checkbox"/> 50.73(a)(2)(iv) <input type="checkbox"/> 73.71(b) <input type="checkbox"/> 20.405(a)(1)(i) <input type="checkbox"/> 50.36(a)(1) <input type="checkbox"/> 50.73(a)(2)(v) <input type="checkbox"/> 73.71(c) <input type="checkbox"/> 20.405(a)(1)(ii) <input type="checkbox"/> 50.36(a)(2) <input checked="" type="checkbox"/> 50.73(a)(2)(vi) <input type="checkbox"/> Other (Specify in Abstract below and in Text, NRC Form 300A) <input type="checkbox"/> 20.405(a)(1)(iii) <input type="checkbox"/> 50.73(a)(2)(i) <input type="checkbox"/> 50.73(a)(2)(vii)(A) <input type="checkbox"/> 20.405(a)(1)(iv) <input type="checkbox"/> 50.73(a)(2)(ii) <input type="checkbox"/> 50.73(a)(2)(vii)(B) <input type="checkbox"/> 20.405(a)(1)(v) <input type="checkbox"/> 50.73(a)(2)(iii) <input type="checkbox"/> 50.73(a)(2)(viii)											
Licensee Contact For This LER (12)											
Name <b>D.E. BUSCHBAUM</b>								Area Code <b>81117</b>		Telephone Number <b>819171-15181511</b>	
Complete One Line For Each Component Failure Described in This Report (13)											
Cause	System	Component	Manufacturer	Reportable To NPDOS		Cause	System	Component	Manufacturer	Reportable To NPDOS	
BF	CIC	VIA/ME	R31410	Y							
Supplemental Report Expected (14)											
<input type="checkbox"/> Yes (If yes, complete Expected Submission Date) <input checked="" type="checkbox"/> No										Expected Submission Date (15)	
Abstract (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)  <p>At 1215 on October 29, 1991, the stop check valves (SCV) in the Component Cooling Water lines to the Reactor Coolant Pump thermal barriers were being tested to satisfy inservice testing requirements. During the test, five of the eight SCVs failed to stroke closed. The five SCVs were subsequently manually exercised, after which they operated as designed. On November 6, 1991, two of the SCVs were inspected. A small accumulation of corrosion products between the plug and stem of the valves, and a slight scaling along the bore, were found. Larger accumulations of corrosion products that may have been present were flushed out when the valves were manually exercised. At approximately 0215 on November 23, 1991, all five SCVs were in service and determined to be capable of performing their intended function.</p> <p>The root cause of this event is believed to be the accumulation of corrosion products in the SCVs due to less than adequate preventive maintenance (PM). Corrective action includes the development of a PM procedure to manually exercise these valves and monitoring of the effectiveness of the PM.</p>											

NRC FORM 366A  <b>LICENSEE EVENT REPORT (LER)</b> <b>TEXT CONTINUATION</b>		U.S. NUCLEAR REGULATORY COMMISSION  APPROVED OMB NO. 3150-0104 EXPIRES: 4/30/92 ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-500), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.							
Facility Name (1)  <b>COMANCHE PEAK - UNIT 1</b>	Docket Number (2)  <b>015101010141415</b>	LER Number (6) <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th style="width: 10%;">Year</th> <th style="width: 10%;">Sequential Number</th> <th style="width: 10%;">Revision Number</th> </tr> <tr> <td style="text-align: center;">91</td> <td style="text-align: center;">01215</td> <td style="text-align: center;">011</td> </tr> </table>	Year	Sequential Number	Revision Number	91	01215	011	Page (3)  <b>012 OF 017</b>
Year	Sequential Number	Revision Number							
91	01215	011							

Text (If more space is required, use additional NRC Form 366A's) (17)

**I. DESCRIPTION OF THE REPORTABLE EVENT**

**A. REPORTABLE EVENT CLASSIFICATION**

Any event where a single cause or condition caused at least one independent train or channel to become inoperable in multiple safety related systems or two independent trains or channels to become inoperable in a single safety related system.

**B. PLANT OPERATING CONDITIONS PRIOR TO THE EVENT**

On October 29, 1991, Comanche Peak Steam Electric Station (CPSES) Unit 1 was in Mode 6, Refueling, with the Reactor Coolant System (RCS)(EIS:(AB)) at a temperature of 100 degrees Fahrenheit and approximately atmospheric pressure.

**C. STATUS OF STRUCTURES, SYSTEMS, OR COMPONENTS THAT WERE INOPERABLE AT THE START OF THE EVENT AND THAT CONTRIBUTED TO THE EVENT**

There were no inoperable structures, systems or components that contributed directly to the event.

**D. NARRATIVE SUMMARY OF THE EVENT, INCLUDING DATES AND APPROXIMATE TIMES**

At CPSES, the Reactor Coolant Pump (RCP) thermal barriers (EIS:(HX)(AB)) are cooled by the Component Cooling Water (CCW) System (EIS:(CC)). With the plant in operation, pressure in the RCP thermal barriers is approximately 2250 pounds per square inch-gage (psig) while CCW pressure is approximately 150 psig. In the event of an RCP thermal barrier tube rupture, CCW system overpressurization protection is provided by: 1) two motor operated valves (MOV) (EIS:(ISV)(CC)) in series, downstream of the RCP thermal barriers, which automatically close on high flow/high temperature; 2) eight, two inch, stop check valves (SCV) (EIS:(V)(CC)), two per line, in series upstream of the RCP thermal barriers; and 3) CCW piping between the MOVs and the SCVs rated at RCS pressure. The eight SCVs are full-stroke exercised during each refueling outage to satisfy inservice testing requirements.

NRC FORM 366A		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED OMB NO. 3150-0104 EXPIRES: 4/30/92	
<b>LICENSEE EVENT REPORT (LER)</b> <b>TEXT CONTINUATION</b>				ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 60.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.	
Facility Name (1)	Docket Number (2)	LER Number (6)		Page (3)	
		Year	Sequential Number	Revision Number	
COMANCHE PEAK - UNIT 1	0151010141415	91	-	01215	- 011 013 OF 017

Text (if more space is required, use additional NRC Form 366A's) (17)

At 1215 on October 29, 1991, the SCVs were being reverse flow tested. During the test, five of the eight SCVs failed to stroke closed. The five SCVs were subsequently manually exercised, after which they operated as designed. On November 6, 1991, two of the SCVs were inspected. The plug, stem, seating surface, and bore of the valves were inspected for roughness, burrs, and sharp edges. No deficient conditions were found. The valves were also inspected for the presence of foreign material, as well as cleanliness of the sliding surfaces. A small accumulation of corrosion products between the plug and stem of the valves, and a slight scaling along the bore, were found. Subsequent valve movement showed no evidence of interference. Larger accumulations of corrosion products that may have been present were flushed out when the valves were manually exercised. At approximately 0215 on November 23, 1991, all five SCVs were in service and determined to be capable of performing their intended function.

**E. THE METHOD OF DISCOVERY OF EACH COMPONENT OR SYSTEM FAILURE, OR PROCEDURAL OR PERSONNEL ERROR**

The SCVs were being tested to satisfy inservice testing requirements. Five of the eight SCVs were discovered to be inoperable as a result of this test.

**II. COMPONENT OR SYSTEM FAILURES**

**A. FAILURE MODE, MECHANISM, AND EFFECT OF EACH FAILED COMPONENT**

Five of the eight SCVs failed to stroke closed during testing. The five SCVs are believed to have failed due to corrosion product accumulation between the plug and bore during long periods of valve inactivity. In the event of an RCP thermal barrier tube rupture, failure of these five SCVs could lead to the overpressurization of the CCW system. No actual overpressurization occurred.

**B. CAUSE OF EACH COMPONENT OR SYSTEM FAILURE**

The five SCVs are believed to have failed due to corrosion product accumulation between the plug and bore during long periods of valve inactivity.

# **LICENSEE EVENT REPORT (LER)** **TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

Facility Name (1)	Docket Number (2)	LER Number (6)			Page (3)		
		Year	Sequential Number	Revision Number			
COMANCHE PEAK - UNIT 1	0151010141415	911	- 01215	- 011	014	OF	017

Text (If more space is required, use additional NRC Form 366A's) (17)

## **C. SYSTEMS OR SECONDARY FUNCTIONS THAT WERE AFFECTED BY FAILURE OF COMPONENTS WITH MULTIPLE FUNCTIONS**

Not applicable - no failures of components with multiple functions occurred during this event.

## **D. FAILED COMPONENT INFORMATION**

SCV 1CC-0657  
Manufacturer: Rockwell-Edward  
Model Number: D3664T1

SCVs 1CC-1075, 1076, 1077, 1078  
Manufacturer: Rockwell-Edward  
Model Number: B36164T3

These stop check valves, although different models, are different generations of the same design. Each valve has a carbon steel body with a cobalt alloy plug which slides down the bore to seat on a loss of forward flow. These valves do not have a spring assist.

## **III. ANALYSIS OF THE EVENT**

### **A. SAFETY SYSTEM RESPONSES THAT OCCURRED**

Not applicable - no safety system responses occurred as a result of this event.

### **B. DURATION OF SAFETY SYSTEM TRAIN INOPERABILITY**

On October 29, 1991, the five SCVs were declared inoperable. On November 23, 1991, the five SCVs were returned to operable status. The five SCVs were inoperable for twenty-four days, fourteen hours.



NRC FORM 366A		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED OMB NO. 3150-0104 EXPIRES: 4/30/92	
<b>LICENSEE EVENT REPORT (LER)</b> <b>TEXT CONTINUATION</b>				ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.	
Facility Name (1)	Docket Number (2)	LER Number (6)		Page (3)	
		Year	Sequential Number	Revision Number	
COMANCHE PEAK - UNIT 1	015101010141415	91	01215	011	015 OF 017
Text (If more space is required, use additional NRC Form 366A's) (17)					

### C. SAFETY CONSEQUENCES AND IMPLICATIONS OF THE EVENT

Operability of the CCW systems ensures that sufficient cooling capacity is available for continued operation of safety-related equipment during normal and accident conditions. Operability of the SCVs is required to prevent overpressurization of the CCW system due to a postulated RCP thermal barrier tube rupture. Two SCVs in series are provided in each CCW to RCP thermal barrier line for single failure consideration.

SCV operability is determined using a low capacity demineralized water header to create a reverse differential test pressure of not greater than 100 pounds per square inch (psi) across the valve. Based on the lack of significant deficient conditions found during the visual inspection of two SCVs, and the lack of noticeable binding or resistance during manual valve cycling, engineering judgement concludes that the SCVs would likely have performed their function if challenged at higher differential pressure.

In this event, five of the eight SCVs failed to stroke closed during testing. Three of the four CCW to RCP thermal barrier lines were still protected by the redundant, OPERABLE, SCVs.

If an RCP thermal barrier tube rupture would have occurred during this event, only one CCW to RCP thermal barrier line would have been unprotected. The consequences of this event are dependent upon the actual break size. Small leaks cause no automatic action and are detectable by the CCW radiation monitors or routine Technical Specification monitoring of RCS leakage. These leaks do not challenge the SCVs. Larger leaks would cause the two MOVs, in series, downstream of the RCP thermal barriers, to isolate on high temperature or high flow. When this occurs, RCS leakage would flow in reverse through the non-functioning SCV into the CCW lines, to all four RCP motor and bearing coolers. Ultimately, RCS pressure and flow relieves to the CCW surge tank (E11S:(TK)(CC)) which is designed to withstand the full insurge of the RCP thermal barrier rupture without damage.

# **LICENSEE EVENT REPORT (LER)** **TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

Facility Name (1)

Docket Number (2)

LER Number (6)

Page (3)

COMANCHE PEAK - UNIT 1 0151010141415 911 - 01215 - 011 016 OF 017

Text (If more space is required, use additional NRC Form 366A's) (17)

These events are detectable when the two downstream RCP thermal barrier MOVs isolate and the CCW surge tank level rises and alarms. For analysis purposes it is assumed that no action is taken to manually isolate the SCV for thirty minutes, and that the SCV did not close at the elevated differential pressure. For RCP thermal barrier breaks resulting in RCS leak rates up to 190 gallons per minute (gpm), the dose consequences are bounded by the Chemical and Volume Control System (EHS:(CB)) letdown line rupture outside containment analysis (CPSES Final Safety Analysis Report, Chapter 15.6.2). For larger breaks, up to the worst case RCP thermal barrier rupture resulting in a 433 gpm leak rate, offsite and control room doses may exceed the previously analyzed values, but estimates of the doses do not exceed the guidelines of 10CFR100 or General Design Criteria 19.

## **IV. CAUSE OF THE EVENT**

### **ROOT CAUSE**

The root cause of this event is believed to be the accumulation of corrosion products in the SCVs due to less than adequate preventive maintenance. Valves which remain in one position for a long period of time may be subject to some degree of reduction of operability as the result of surface corrosion of moving parts, or accumulation of deleterious solids. These SCVs were last exercised in October, 1989.

## **V. CORRECTIVE ACTIONS**

### **A. CORRECTIVE ACTIONS TO PREVENT RECURRENCE**

#### **ROOT CAUSE**

Less than adequate SCV preventive maintenance.

NRC FORM 366A		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED OMB NO. 3150-0104 EXPIRES: 4/30/92 ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC, 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC, 20503.			
<b>LICENSEE EVENT REPORT (LER)</b> <b>TEXT CONTINUATION</b>							
Facility Name (1)		Docket Number (2)		LER Number (6)		Page (3)	
COMANCHE PEAK - UNIT 1		0151010141415		911-01215-011		017 OF 017	
Text (If more space is required, use additional NRC Form 366A's) (17)							
<div style="margin-bottom: 20px;"> <p><b><u>CORRECTIVE ACTION</u></b></p> <p>A preventive maintenance (PM) procedure will be developed to periodically manually exercise these valves. This process will help to avoid any accumulation of corrosion products. PM effectiveness will be monitored and the frequency in which the valves are exercised changed as necessary.</p> </div> <div> <p><b>VI. <u>PREVIOUS SIMILAR EVENTS</u></b></p> <p>There have been no previous similar events reported pursuant to 10CFR50.73.</p> </div> <div> <p><b>VII. <u>ADDITIONAL INFORMATION</u></b></p> <p>The times listed in the report are approximate and Central Standard Time.</p> </div>							