

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)  
Washington Nuclear Plant - Unit 2DOCKET NUMBER (2)  
0 5 0 0 0 3 9 7 1 OF 0 2TITLE (4)  
Inadvertent Initiation of Control Room Emergency Filtration Units

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0	6	0	7	8	4	8	4	0	5	8	0
0	6	0	7	8	4	8	4	0	5	8	0

OPERATING MODE (9)	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)																														
4	<table border="1"><tr><td>20.402(b)</td><td>20.406(a)</td><td>X</td><td>50.73(a)(2)(iv)</td><td>73.71(b)</td></tr><tr><td>20.406(a)(1)(i)</td><td>50.38(a)(1)</td><td></td><td>50.73(a)(2)(v)</td><td>73.71(c)</td></tr><tr><td>20.406(a)(1)(ii)</td><td>50.38(a)(2)</td><td></td><td>50.73(a)(2)(vii)</td><td>X OTHER (Specify in Abstract below and in Text, NRC Form 365A)</td></tr><tr><td>20.406(a)(1)(iii)</td><td>50.73(a)(2)(i)</td><td></td><td>50.73(a)(2)(viii)(A)</td><td>50.72(b)(2)(ii)</td></tr><tr><td>20.406(a)(1)(iv)</td><td>50.73(a)(2)(ii)</td><td></td><td>50.73(a)(2)(viii)(B)</td><td></td></tr><tr><td>20.406(a)(1)(v)</td><td>50.73(a)(2)(iii)</td><td></td><td>50.73(a)(2)(ix)</td><td></td></tr></table>	20.402(b)	20.406(a)	X	50.73(a)(2)(iv)	73.71(b)	20.406(a)(1)(i)	50.38(a)(1)		50.73(a)(2)(v)	73.71(c)	20.406(a)(1)(ii)	50.38(a)(2)		50.73(a)(2)(vii)	X OTHER (Specify in Abstract below and in Text, NRC Form 365A)	20.406(a)(1)(iii)	50.73(a)(2)(i)		50.73(a)(2)(viii)(A)	50.72(b)(2)(ii)	20.406(a)(1)(iv)	50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)		20.406(a)(1)(v)	50.73(a)(2)(iii)		50.73(a)(2)(ix)	
20.402(b)	20.406(a)	X	50.73(a)(2)(iv)	73.71(b)																											
20.406(a)(1)(i)	50.38(a)(1)		50.73(a)(2)(v)	73.71(c)																											
20.406(a)(1)(ii)	50.38(a)(2)		50.73(a)(2)(vii)	X OTHER (Specify in Abstract below and in Text, NRC Form 365A)																											
20.406(a)(1)(iii)	50.73(a)(2)(i)		50.73(a)(2)(viii)(A)	50.72(b)(2)(ii)																											
20.406(a)(1)(iv)	50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)																												
20.406(a)(1)(v)	50.73(a)(2)(iii)		50.73(a)(2)(ix)																												

LICENSEE CONTACT FOR THIS LER (12)  
NAME  
C.M. Powers, Reactor Engineering SupervisorTELEPHONE NUMBER  
AREA CODE  
5 0 9 3 7 7 - 2 5 0 1

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13) Ext. 2996

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC
A	I	L	R	A	K	0	2	0	N

SUPPLEMENTAL REPORT EXPECTED (14)  
YES (if yes, complete EXPECTED SUBMISSION DATE) X NO  
EXPECTED SUBMISSION DATE (15)  
MONTH DAY YEAR

ABSTRACT - Limit to 1400 spaces (i.e. approximately fifteen single-space typewritten lines) (16)

The Control Room Emergency Filtration Unit (an EFS system) was inadvertently initiated due to a technician performing maintenance on the associated radiation monitoring sample rack.

After verifying that radiation levels were not above normal background, the radiation monitor and emergency filtration unit were reset and returned to a normal lineup.

8407030226 840628  
PDR ADOCK 05000397  
S PDRIE22  
1/1

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (8)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Washington Nuclear Plant - Unit 2	0 5 0 0 0 3 9 7 8 4 -	0 5 8 -	0 0 0 2 OF	0 2			

TEXT (If more space is required, use additional NRC Form 388A's) (17)

Plant Conditions

- a) Power Level - 0%  
b) Plant Mode - 4

Event

The Control Room Emergency Filtration Unit (EPN: WMA-FN-54B) was inadvertently initiated on 6-7-84 by a High-High radiation alarm originating from a Control Room Outside Air Intake Monitor (EPN: WOA-RIS-32B). While replacing a low flow switch relay in the associated sample rack (EPN: WOA-SR-19B), a technician was relanding the 110 VAC supply when the monitor alarmed on High and High-High radiation. The monitor spike and resultant alarms were attributed to this voltage transient.

Immediate Corrective Action

Normal background radiation levels were observed at the monitors. The technician involved promptly informed operations of the event that occurred and the cause. The alarms were reset and the ESF system returned to normal.

Notification was given to the NRC in accordance with the requirements of 10CFR50.72(b)(2)(ii).

Long Term Corrective Action

This is a unique event and requires no further corrective action.

Safety Significance

There were no safety consequences associated with this event and all Plant systems performed as required.

## Washington Public Power Supply System

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000

Docket No. 50-397

June 28, 1984

Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555


Subject: NUCLEAR PLANT NO. 2  
LICENSEE EVENT REPORT NO. 84-058

Dear Sir:

Transmitted herewith is Licensee Event Report No. 84-058 for WNP-2 Plant. This report is submitted in response to the report requirements of Technical Specification Section 6.9.1.7 and discusses the item of reportability, corrective action taken, and action taken to preclude recurrence.

This is the follow-up report to the verbal notification given at 1617 hours on June 7, 1984.

Very truly yours,



J. D. Martin (M/D 927M)  
WNP-2 Plant Manager

JDM:mm

Enclosure:

Licensee Event Report No. 84-058

cc: Mr. John B. Martin, Administrator  
Region V, Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
1450 Maria Lane  
Walnut Creek, California 94596  
Mr. A. D. Toth, NRC Resident Inspector (901A)  
Ms. Dottie Sherman  
American Nuclear Insurers  
The Exchange Suite 245  
270 Farmington Ave.  
Farmington, CT 06032

IE22  
1/1