

## LICENSEE EVENT REPORT (LER)

|   |        |  |                |                     |                 |                  |                 |           |                |   |   |  |                  |  |                      |      |   |   |   |   |   |   |   |  |  |
|---|--------|--|----------------|---------------------|-----------------|------------------|-----------------|-----------|----------------|---|---|--|------------------|--|----------------------|------|---|---|---|---|---|---|---|--|--|
| FACILITY NAME (1)<br>Nine Mile Point Unit #1  |        |  |                |                     |                 |                  |                 |           |                | DOCKET NUMBER (2)<br>0 5 0 0 0 2 2 0                |   |  |                  |  | PAGE (3)<br>1 OF 0 2 |      |   |   |   |   |   |   |   |  |  |
| TITLE (4)<br>Diesel Generator Start when back feeding Powerboard 102 from Powerboard 16 |        |  |                |                     |                 |                  |                 |           |                |   |   |  |                  |  |                      |      |   |   |   |   |   |   |   |  |  |
| EVENT DATE (6)  |        |  | LER NUMBER (8) |                     |                 |                  | REPORT DATE (7) |           |                | OTHER FACILITIES INVOLVED (9)                       |   |  |                  |  |                      |      |   |   |   |   |   |   |   |  |  |
| MONTH   | DAY    | YEAR   | YEAR           | SEQUENTIAL NUMBER   | REVISION NUMBER | MONTH            | DAY             | YEAR      | FACILITY NAMES |   |   |  | DOCKET NUMBER(S) |  |                      |      |   |   |   |   |   |   |   |  |  |
| 0   | 6      | 0  | 1              | 8                   | 4               | 8                | 4               | 0         | 1              | 2   | 0 | 0                                      | 0                | 7  | 0                    | 1    | 8 | 4 | 0 | 5 | 0 | 0 | 0 |  |  |
| OPERATING MODE (9)<br>N   |        | THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5: (Check one or more of the following) (11) |                |                     |                 |                  |                 |           |                |   |   |  |                  |  |                      |      |   |   |   |   |   |   |   |  |  |
| POWER LEVEL (10)<br>0 1 0 1 0   |        | 20.402(b)  |                |                     |                 | 20.405(c)        |                 |           |                | <input checked="" type="checkbox"/> 80.73(a)(2)(iv) |   |  |                  | 73.71(b)   |                      |      |   |   |   |   |   |   |   |  |  |
|   |        | 20.405(a)(1)(i)  |                |                     |                 | 80.38(a)(1)      |                 |           |                | <input type="checkbox"/> 80.73(a)(2)(v)             |   |  |                  | 73.71(a)   |                      |      |   |   |   |   |   |   |   |  |  |
|   |        | 20.405(a)(1)(ii)   |                |                     |                 | 80.38(a)(2)      |                 |           |                | <input type="checkbox"/> 80.73(a)(2)(vi)            |   |  |                  | OTHER (Specify in Abstract below and in Text, NRC Form 366A) |                      |      |   |   |   |   |   |   |   |  |  |
|   |        | 20.405(a)(1)(iii)  |                |                     |                 | 80.73(a)(2)(i)   |                 |           |                | <input type="checkbox"/> 80.73(a)(2)(vii)(A)        |   |  |                  |  |                      |      |   |   |   |   |   |   |   |  |  |
|   |        | 20.405(a)(1)(iv)   |                |                     |                 | 80.73(a)(2)(ii)  |                 |           |                | <input type="checkbox"/> 80.73(a)(2)(viii)(B)       |   |  |                  |  |                      |      |   |   |   |   |   |   |   |  |  |
|   |        | 20.405(a)(1)(v)  |                |                     |                 | 80.73(a)(2)(iii) |                 |           |                | <input type="checkbox"/> 80.73(a)(2)(ix)            |   |  |                  |  |                      |      |   |   |   |   |   |   |   |  |  |
| LICENSEE CONTACT FOR THIS LER (12)  |        |  |                |                     |                 |                  |                 |           |                |   |   |  |                  |  |                      |      |   |   |   |   |   |   |   |  |  |
| NAME<br>Robert Randall, Supervisor Technical Services                                   |        |  |                |                     |                 |                  |                 |           |                | TELEPHONE NUMBER<br>3 1 5 3 4 9 - 2 4 4 5           |   |  |                  |  |                      |      |   |   |   |   |   |   |   |  |  |
| COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)              |        |  |                |                     |                 |                  |                 |           |                |   |   |  |                  |  |                      |      |   |   |   |   |   |   |   |  |  |
| CAUSE   | SYSTEM | COMPONENT  | MANUFACTURER   | REPORTABLE TO NPROS |                 | CAUSE            | SYSTEM          | COMPONENT | MANUFACTURER   | REPORTABLE TO NPROS                                 |   |  |                  |  |                      |      |   |   |   |   |   |   |   |  |  |
|   |        |  |                |                     |                 |                  |                 |           |                |   |   |  |                  |  |                      |      |   |   |   |   |   |   |   |  |  |
|   |        |  |                |                     |                 |                  |                 |           |                |   |   |  |                  |  |                      |      |   |   |   |   |   |   |   |  |  |
| SUPPLEMENTAL REPORT EXPECTED (14)   |        |  |                |                     |                 |                  |                 |           |                |   |   | EXPECTED SUBMISSION DATE (15)          |                  | MONTH  | DAY                  | YEAR |   |   |   |   |   |   |   |  |  |
| <input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)                |        |  |                |                     |                 |                  |                 |           |                |   |   | <input checked="" type="checkbox"/> NO |                  |  |                      |      |   |   |   |   |   |   |   |  |  |

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

## ABSTRACT

On June 1, 1984, during a refueling outage, work was to be done on breaker R1012, which supplies 4160 Volt Powerboard 102. This made it necessary to backfeed Powerboard 102 through 600 Volt Powerboard 16. Breaker R1012 was opened in preparation for this maintenance. Immediately thereafter, new protective relays sensed undervoltage on 4160 Volt Powerboard 102. As a result, tie breaker R1042 tripped, and Diesel Generator 102 started at approximately 1000 hrs. The undervoltage condition experienced on 4160 Volt Powerboard 102 was due to the combination of the voltage drops associated with the backfeeding process and the new 4160 Volt Powerboard 102 protective relay settings (which are considerably higher than previously set). Immediate corrective action taken included returning to the normal 115K Volt supply on Powerboard 102. Operating procedures are being reviewed to determine if any procedural changes are required which will prevent this type of event from occurring in the future.

8407030424 840701  
PDR ADOCK 05000220  
S PDRIE22  
111

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES 8/31/85

|  |  |                |                   |                 |          |    |     |
|--|--|----------------|-------------------|-----------------|----------|----|-----|
| FACILITY NAME (1)<br><br>Nine Mile Point Unit #1 | DOCKET NUMBER (2)<br><br>0 5 0 0 0 2 2 0 8 4 — | LER NUMBER (6) |                   |                 | PAGE (3) |    |     |
|  |  | YEAR           | SEQUENTIAL NUMBER | REVISION NUMBER |          |    |     |
|  |  | 0 1 2 —        | 0 0               | 0 2             | 0 2      | OF | 0 2 |

TEXT (If more space is required, use additional NRC Form 365A's) (17)

TEXT

On June 1, 1984, during a refueling outage, maintenance work was to be done on breaker R1012, which supplies 4160V Powerboard 102. This made it necessary to backfeed Powerboard 102 through 600V Powerboard 16. The interlock between sections A and B on Powerboard 16 was defeated to allow tie breaker R1042 to be closed, which completed the backfeed to 4160V Powerboard 102. At that point, breaker R1012 was opened in preparation for maintenance. Immediately after this breaker was opened, new protective relays sensed an undervoltage condition on 4160V Powerboard 102. As a result, tie breaker R1042 was tripped and Diesel Generator 102 started at approximately 1000 hrs. The undervoltage condition experienced on 4160V Powerboard 102 was due to the combination of the voltage drops associated with the backfeeding process and the new 4160V Powerboard 102 protective relay settings (which are considerably higher than previously set).

ASSESSMENT OF POTENTIAL SAFETY CONSEQUENCES

There are no potential safety consequences arising out of this event because: 1) the reactor was in cold shutdown and subcritical; 2) all control rods were fully inserted at the time of the event; 3) there were no loads on the 4160V Powerboard 102 at the time of the event; and 4) all engineered safety features involved in this event operated as designed; therefore there was no possibility of damage to the plant or danger to plant personnel arising out of this event. The effect of this event on the plant and its personnel, had the plant been at any other power level, would still be negligible, because all of the engineered safety features involved in this event operated as designed.

CORRECTIVE ACTION

Immediate corrective action taken included returning to the normal 115KV supply on Powerboard 102. Operating procedures are being reviewed to determine if any procedural changes are required which will prevent this type of event from occurring in the future.

## NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK300 ERIE BOULEVARD, WEST  
SYRACUSE, N. Y. 13202

June 29, 1984

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

RE: Docket No. 50-220  
LER 84-12


Gentlemen:

In accordance with 10 CFR 50.73, we hereby submit the following  
Licensee Event Report:

LER 84-12      Which is being submitted in accordance with  
10 CFR 50.73 (a)(2)(iv), "Any event or condition  
that resulted in manual or automatic actuation of  
any Engineered Safety Feature (ESF), including  
the Reactor Protection System (RPS)."

A 10 CFR 50.72 report was made at 1015 hrs on June 1, 1984. This  
report was completed in the format designated in NUREG-1022, dated  
September 1983.

Very truly yours,



Thomas E. Lempges  
Vice President  
Nuclear Generation

TEL/lo  
attachments  
cc: Dr. Thomas E. Murley  
Regional Administrator

IE22  
1/1