

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)

Prairie Island Unit 1

DOCKET NUMBER (2)

0 5 0 0 0 2 8 2 1 OF 0 2

PAGE (3)

TITLE (4)

Reactor Trip

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0	8	3	0	8	4	0	0	5	0	0	0
0	8	3	0	8	4	0	0	9	2	8	8
OPERATING MODE (9)			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5: (Check one or more of the following) (11)								
N			20.402(b)			20.406(e)			X 50.73(a)(2)(iv)		
POWER LEVEL (10)			20.406(a)(1)(i)			50.36(e)(1)			50.73(a)(2)(v)		
1 0 0			20.406(a)(1)(ii)			50.36(e)(2)			50.73(a)(2)(vii)		
			20.406(a)(1)(iii)			50.73(a)(2)(i)			50.73(a)(2)(viii)(A)		
			20.406(a)(1)(iv)			50.73(a)(2)(ii)			50.73(a)(2)(viii)(B)		
			20.406(a)(1)(v)			50.73(a)(2)(iii)			50.73(a)(2)(ix)		

LICENSEE CONTACT FOR THIS LER (12)

NAME	TELEPHONE NUMBER
Arne A. Hunstad, Staff Engineer	6 1 1 2 3 1 8 1 8 - 1 1 1 2 1

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)	NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
X					

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During surveillance testing in excore nuclear instrumentation cabinets, improper use of test leads caused a reactor trip. Procedures have been revised.

8410150300 840928
PDR ADUCK 05000282
S PDR

IE22
11

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1) Prairie Island Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 2 8 2 8 4 — 0 0 5 — 0 0	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
					0 2	OF	0 2

TEXT (If more space is required, use additional NRC Form 386A's) (17)

At 1439 on August 30, 1984, during performance of the monthly surveillance tests on core power distribution, voltage readings were being taken on the upper and lower NIS power range detectors (DET) to verify their calibration. The test leads being used to measure the voltages contacted the handle on the NIS cabinet (IG), shorting the lower detector section channel N41 to ground momentarily, generating a negative rate trip signal from N41. Moments later a similar circumstance on the upper detector section of N42 caused a second negative rate trip signal, which satisfied the 2/4 logic for a reactor trip.

Cause of the event was improper use of test leads which had an exposed connector midway between the meter and the test probes. The rate trip signals lock in and must be manually reset. The first trip signal caused control room annunciation (ANN) but the control board operator did not have time to prevent the trip; the computer log showed that only 6 seconds elapsed between the first and second trip signals.

Corrective action was revision of appropriate procedures. Precautions were added to ensure no rate trip signals are present in a channel before taking readings in the next channel. Involved personnel have reviewed the event and have been instructed in the proper use of test leads.

Health and safety of the public were unaffected.



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

September 28, 1984

U S Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-282 License No. DPR-42
50-306 DPR-60

Reactor Trip

The License Event Report for this occurrence is attached.

This event was reported via Emergency Notification System per 10 CFR Part 72
on August 30, 1984.

for *Eugene Eckhoff*
David Musolf
Manager - Nuclear Support Services

DMM/EFE/dab

c: Regional Administrator-III, NRC
NRR Project Manager, NRC
Resident Inspector, NRC
MPCA
Attn: J W Ferman

Attachment

IE22
1/1