

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)  
Vermont Yankee Nuclear Power Station

DOCKET NUMBER (2)

0 5 0 0 0 2 7 1

PAGE (3)

1 OF 0 2

TITLE (4)  
Reactor scram due to personnel error during surveillance testing

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)								
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)							
0	6	1	7	8	4	8	4	0	0	9	0	5	0	0	0		
											0	5	0	0	0		

OPERATING MODE (9) N

POWER LEVEL (10) 0 0 0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5: (Check one or more of the following) (11)

20.402(b)	20.405(e)	X	50.73(a)(2)(iv)	73.71(b)
20.405(a)(1)(i)	50.36(a)(1)		50.73(a)(2)(v)	73.71(c)
20.405(a)(1)(ii)	50.36(a)(2)		50.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
20.405(a)(1)(iii)	50.73(a)(2)(i)		50.73(a)(2)(vii)(A)	
20.405(a)(1)(iv)	50.73(a)(2)(ii)		50.73(a)(2)(vii)(B)	
20.405(a)(1)(v)	50.73(a)(2)(iii)		50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME  
James P. Pelletier

TELEPHONE NUMBER

AREA CODE

8 0 2 2 5 7 - 7 7 1 1

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS

SUPPLEMENTAL REPORT EXPECTED (14)

YES // If yes, complete EXPECTED SUBMISSION DATE: X NO

EXPECTED SUBMISSION DATE (15)

MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 6/17/84 while performing control rod drive friction testing, with the reactor shutdown, a scram occurred due to a valving error on a reactor level instrument being calibrated. After verifying the cause of the scram the scram was reset and friction testing recommenced.

8407240286 840717  
PDR ADOCK 05000271  
S PDR


IE 22 11

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Vermont Yankee Nuclear Power Station	0500027184	0	09	00	2	OF	02

TEXT (If more space is required, use additional NRC Form 385A's) (17)

On 6/17/84 the reactor was shut down with control rod drive friction testing in progress. Instrument and control department personnel were performing calibration of reactor level instruments per plant procedure OP 4313. At 0756 a reactor scram occurred. The cause of the scram was determined to be due to a valving error by the technician performing the instrument calibration. After verifying the cause of the scram the scram was reset and friction testing recommenced. OP 4313 was reviewed to verify that there was no problem with the procedure which contributed to the scram, and thus it was concluded that the procedure was adequate as written. The event and possible consequences were reviewed with the technician involved to insure he understood the need for strict compliance with procedures. There have been no prior occurrences of this type reported to the Commission. There were no adverse affects to public health or safety.



VERMONT YANKEE NUCLEAR POWER CORPORATION

P. O. BOX 157  
GOVERNOR HUNT ROAD  
VERNON, VERMONT 05354

July 17, 1984

VYV84-372


U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

REFERENCE: Operating License DPR-28  
Docket No. 50-271  
Reportable Occurrence No. LER 84-09

Dear Sirs:

As defined by 10CFR50.73, we are reporting the attached Reportable Occurrence as LER 84-09.

Very truly yours,

  
James P. Pelletier  
Plant Manager

RDP/cjm

cc: Regional Administrator  
USNRC Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

IE22  
1/1