

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Browns Ferry - Unit 1										DOCKET NUMBER (2) 0 5 0 0 0 2 5 9 1 OF 0 2												
TITLE (4) Possible Block Wall Failure During A Tornado Due to Design Miscalculations of Loading																						
EVENT DATE (6)			LER NUMBER (8)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)												
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES					DOCKET NUMBER(S)								
0	9	2	8	8	4	8	4	0	3	0	0	1	0	2	6	8	4	0 5 0 0 0				
OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)																				
N		20.402(b)				20.406(c)				50.73(a)(2)(iv)				73.71(b)								
POWER LEVEL (10)		0 9 9				20.406(a)(1)(i)				50.36(a)(1)				50.73(a)(2)(v)				73.71(c)				
		20.406(a)(1)(ii)				50.36(a)(2)				50.73(a)(2)(vi)				OTHER (Specify in Abstract below and in Text, NRC Form 365A)								
		20.406(a)(1)(iii)				50.73(a)(2)(i)				50.73(a)(2)(vii)(A)												
		20.406(a)(1)(iv)				50.73(a)(2)(ii)				50.73(a)(2)(viii)(B)												
		20.406(a)(1)(v)				50.73(a)(2)(iii)				50.73(a)(2)(ix)												
LICENSEE CONTACT FOR THIS LER (12)																						
NAME Jimmy B. Walker										TELEPHONE NUMBER 2 0 5 7 2 9 - 3 8 6 5												
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																						
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC												
SUPPLEMENTAL REPORT EXPECTED (14)										EXPECTED SUBMISSION DATE (15)					MONTH	DAY	YEAR					
YES (If yes, complete EXPECTED SUBMISSION DATE)										X NO												
ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)																						
A number of block walls in the control bay and reactor building have been identified by Engineering Design to have higher load requirements than originally calculated. This condition was identified as a result of new tornado depressurization analysis performed on the walls and doors. Selected interior doors have been added to plant procedures to be blocked open in the event of a tornado warning to reduce the loading on the block walls. Long term resolution is being handled in conjunction with IE Bulletin 80-11 modifications.																						

8410310092 840928
PDR ADOCK 05000259
S PDRIE22
11

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES 8/31/85

FACILITY NAME (1) Browns Ferry - Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 2 5 9 8 4 - 0 3 0 - 0 0 0 2 OF 0 2	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Unit 1 was operating at 99 percent power, unit 2 and unit 3 were in a refueling outage. This event affects all units but has the most effect on unit 3.

TVA's Engineering Design determined that certain block walls in the reactor building and control bay could potentially fall on certain safety system equipment and/or components in the event of a tornado. This effect on the block (BLK) walls can be reduced by blocking open certain doors (DR) in the general area of these walls.

Plant procedures were revised to open selected doors during a tornado warning until permanent modifications are implemented in accordance with IE Bulletin 81-11. One wall in the unit 3 control bay area has been reinforced to reduce the number of doors being blocked opened.

The schedule for long term modifications for IE Bulletin 80-11 is described in the integrated schedule submittal of August 14, 1984, to NRC. A revised response to the Bulletin discussing the details of this new analysis will be submitted by December 15, 1984.

Responsible Plant Section - ED

Previous Similar Events - None

BCM:JBW:BDL
October 26, 1984

TENNESSEE VALLEY AUTHORITY
Browns Ferry Nuclear Plant
P. O. Box 2000
Decatur, Alabama 35602

October 26, 1984

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555


Dear Sir:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT (BFN) UNIT 1 -
DOCKET NO. 50-259 - FACILITY OPERATING LICENSE DPR-09 - REPORTABLE
OCCURRENCE REPORT BFR0-50-259/84030

The enclosed report provides details that concern the possible block wall failure during a tornado due to design miscalculations of loading. This report is submitted in accordance with 10 CFR 50.73 (a)(2)(ii).

Very truly yours,

TENNESSEE VALLEY AUTHORITY



G. T. Jones
Plant Manager
Browns Ferry Nuclear Plant

Enclosure

cc (Enclosure):
Regional Administrator
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 2900
Atlanta, Georgia 30303

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

NRC Resident Inspector, BFN

TE22
1/1