

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)

DOCKET NUMBER (2)

PAGE (3)

D. C. COOK UNIT TWO

0 5 0 0 0 3 1 1 6 1 OF 0 1

TITLE (4)

REACTOR TRIP SYSTEM INSTRUMENTATION SURVEILLANCE MISSED

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)			
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)	
07	04	84	84	017	00	07	26	84			0 5 0 0 0	
OPERATING MODE (9)			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5: (Check one or more of the following) (11)									
3			20.402(b)			20.408(e)			80.73(a)(2)(iv)			73.71(b)
POWER LEVEL (10)			20.408(a)(1)(i)			80.38(a)(1)			80.73(a)(2)(v)			73.71(a)
01010			20.408(a)(1)(ii)			80.38(a)(2)			80.73(a)(2)(vi)			OTHER (Specify in Abstract below and in Text, NRC Form 306A)
			20.408(a)(1)(iii)			80.73(a)(2)(i)			80.73(a)(2)(vii)(A)			
			20.408(a)(1)(iv)			80.73(a)(2)(ii)			80.73(a)(2)(vii)(B)			
			20.408(a)(1)(v)			80.73(a)(2)(iii)			80.73(a)(2)(ix)			

LICENSEE CONTACT FOR THIS LER (12)

NAME

TELEPHONE NUMBER

K. R. BAKER OPERATIONS SUPERINTENDENT

AREA CODE

616 465-5901

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS

SUPPLEMENTAL REPORT EXPECTED (14)

EXPECTED SUBMISSION DATE (15)

MONTH DAY YEAR

YES (If yes, complete EXPECTED SUBMISSION DATE)

X NO

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

ON 7/4/84 AT 0330 WHILE THE UNIT WAS IN MODE 3 (HOT STANDBY), IT WAS DISCOVERED THAT THE SURVEILLANCE REQUIREMENTS OF T.S. 3.3.1.1 TABLE 4.3-1 ITEM 5 WERE NOT PERFORMED AS REQUIRED. THE SURVEILLANCE REQUIREMENTS WERE PREVIOUSLY COMPLETED IN THEIR ENTIRETY ON 7/1/84 JUST PRIOR TO MODE CHANGE INTO MODE 3. THE SURVEILLANCE WAS FOR THE INTERMEDIATE RANGE EXCORE DETECTORS SHIFTLY CHANNEL CHECKS. THE PROCEDURE'S ACCEPTANCE CRITERIA IDENTIFIED THE CHANNEL CHECK REQUIREMENTS FOR ONLY MODES 1 AND 2. THE TECHNICAL SPECIFICATION ALSO REQUIRES A CHANNEL CHECK WHENEVER THE REACTOR TRIP BREAKERS ARE IN THE CLOSED POSITION AND THE CONTROL ROD DRIVE SYSTEM CAPABLE OF ROD WITHDRAWAL. THE PROCEDURES HAVE BEEN CHANGED TO ADD THE EXTRA REQUIREMENT.

THE HEALTH AND SAFETY OF THE PUBLIC WAS NOT AFFECTED.

8408060151 840726  
PDR ADOCK 05000316  
S PDRIE22  
1/1



**INDIANA & MICHIGAN ELECTRIC COMPANY**

DONALD C. COOK NUCLEAR PLANT  
P.O. Box 458, Bridgman, Michigan 49106  
(616) 465-5901

July 26, 1984

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555


Operating License DPR-74  
Docket No. 50-316

Document Control Manager:

In accordance with the criteria established by 10CFR50.73  
entitled Licensee Event Reporting System, the following  
report/s are being submitted:

RO 84-017-0

Sincerely,

  
W.G. Smith, Jr.  
Plant Manager

/cbm

Attachment

cc: John E. Dolan  
J.G. Keppler, RO:III  
M.P. Alexich  
R.F. Kroeger  
H. Brugger  
E.R. Swanson, RO:III  
R.C. Callen, MPSC  
G. Charnoff, Esq.  
J.M. Hennigan  
R.O. Bruggee, EPRI  
INPO  
PNSRC  
J.F. Stietzel  
E.L. Townley  
Dottie Sherman, ANI Library

IE22  
11