

John D. O'Toole
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003
Telephone (212) 460-2533

July 30, 1984

Re: Indian Point Unit No. 2
Docket No. 50-247

Dr. Thomas E. Murley, Regional Administrator
Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406


Dear Dr. Murley:

This letter is in response to IE Bulletin No. 84-02 "Failures of General Electric Type HFA Relays In Use in Class 1E Safety Systems." We have reviewed the relays in use at Indian Point Unit No. 2 and have determined that there are no GE Type HFA relays in safety related applications.


In addition, we have reviewed the general concerns described in the bulletin. We have concluded that they do not apply to Indian Point 2 since we previously modified relays having these general concerns, including relay coil burnout (coil style 1271C50G01 in relays 5072A49-G-XX). The modification includes improved baked coils, coil style 1293C51G01 with improved insulating material, to prevent binding of the relay plunger in the coil. These relays do not have the problems discussed in the bulletin, nor have they failed at Indian Point. Additional replacements and a replacement schedule are not required as the performance has been found to be satisfactory.

Should you or your staff have any questions, please contact us.

Very truly yours,



Signed and sworn to
before me this 31 day
of July, 1984.


Notary Public

CONRAD TROMBA
Notary Public State of New York
No. 30-4022875
Qualified in Nassau County
Terms expires March 30, 1985

8408070425 840730
PDR ADOCK 05000247
PDR

IE 11
/10

cc: U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Senior Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, New York 10511