

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Peach Bottom Atomic Power Station - Unit 2	DOCKET NUMBER (2) 0500027784	LER NUMBER (5)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
			0112	010	02	OF	03

TEXT (If more space is required, use additional NRC Form 308A (1-77))

Description of the Event:

At approximately 3:30 p.m. on June 28, 1984, with Unit 2 in cold shutdown for refueling and Unit 3 at 99% full power, surveillance testing discovered an inoperable horizontal fire damper in the Cable Spreading Room. Investigation revealed that the horizontal fire damper was inoperable because its spring closure device was missing. In accordance with Technical Specification 3.14.D, either a continuous fire watch is required to be established within one hour, or verification of smoke detector operability on one side of the inoperable fire barrier must be made and an hourly fire watch patrol must be established.

A continuous fire watch was already in place in the CSR at the time of event. The existing continuous fire watch was notified of the deficient damper.

Consequences of the Event:

Following this event, the seven other similar horizontal fire dampers located in the Cable Spreading Room (3 in addition to the inoperable damper) and the Control Room (4) were tested and found operable in accordance with ST 16.22 criteria which includes an inspection of the spring closure device.

Two other horizontal fire dampers are located in the Control Room and are part of the CARDOX system. These two fire dampers are tested in accordance with Surveillance Test 16.4, "Cable Spreading Room CARDOX Simulated Actuation and Air Flow Test". These fire dampers were most recently tested and found operable on May 14, 1984.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES 8/31/86

FACILITY NAME (1) Peach Bottom Atomic Power Station - Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 2 7 7 8 4	LER NUMBER (8)			PAGE (3)	
		YEAR 0	SEQUENTIAL 1	REVISION 2	03	OF 03

TEXT (If more space is required, use additional NRC Form 366A) (17)

Cause of the Event:

The cause of the event was a construction or design error and inadequacies in the previous fire damper inspection program.

The surveillance test that discovered this inoperable fire damper, ST 16.22, 'Fire Damper Inspection', had just been reviewed and upgraded prior to this testing. Included within Revision 2 to ST 16.22 was a new step requiring visual inspection of the spring closure device.

Corrective Actions:

A new 3-hour horizontal fire damper will be installed as a replacement to the existing damper. The fire watch requirements of Technical Specification 3.14.D.3 will continue to be met until the new damper is placed in service. The appropriate replacement damper will be installed within one month of delivery.

Previous Similar Occurrence

LER 2-83-20/3L

PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

(215) 841-4000

July 27, 1984

Docket Nos. 50-277
50-278

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555


SUBJECT: Licensee Event Report

This LER concerns the discovery of an inoperable fire damper in the Peach Bottom Atomic Power Station Cable Spreading Room.

Reference:	Docket Nos. 50-277/278
Report Number:	2-84-12
Revision Number:	00
Event Date:	June 28, 1984
Report Date:	July 27, 1984
Facility:	Peach Bottom Atomic Power Station RD #1, Box 208, Delta, PA 17314

This LER is submitted pursuant to the requirements of 10 CFR 50.73(a)(2)(i)(B).

Very truly yours,



R. H. Logue
Superintendent
Nuclear Services

cc: Dr. Thomas E. Murley, Administrator
Mr. A. R. Blough, Site Inspector

IE22
1/1