

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.5 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555 AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1)

South Texas, Unit 1

DOCKET NUMBER (2)

0 5 0 0 0 4 9 8

PAGE (3)

1 OF 0 4

TITLE (4)

Erratic Containment Extended Range Pressure Channel Output

| EVENT DATE (5) | | | LER NUMBER (6) | | REPORT DATE (7) | | | OTHER FACILITIES INVOLVED (8) | |
|--------------------|-----|------|--|-----------------|------------------|-----|----------------------|-------------------------------|--|
| MONTH | DAY | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | MONTH | DAY | YEAR | FACILITY NAMES | DOCKET NUMBER(S) |
| 04 | 20 | 91 | 014 | 02 | 01 | 15 | 92 | | 0 5 0 0 0 |
| OPERATING MODE (9) | | | THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following) (11) | | | | | | |
| POWER LEVEL (10) | | | 20.402(b) | | 20.405(a) | | 50.73(a)(2)(iv) | | 73.71(b) |
| 100 | | | 20.405(a)(1)(i) | | 50.36(a)(1) | | 50.73(a)(2)(v) | | 73.71(c) |
| | | | 20.405(a)(1)(ii) | | 50.36(a)(2) | | 50.73(a)(2)(vi) | | OTHER (Specify in Abstract below and in Text, NRC Form 366A) |
| | | | 20.405(a)(1)(iii) | | 50.73(a)(2)(i) | | 50.73(a)(2)(viii)(A) | | |
| | | | 20.405(a)(1)(iv) | | 50.73(a)(2)(ii) | | 50.73(a)(2)(viii)(B) | | |
| | | | 20.405(a)(1)(v) | | 50.73(a)(2)(iii) | | 50.73(a)(2)(ix) | | |

LICENSEE CONTACT FOR THIS LER (12)

NAME

Charles Ayala - Supervising Licensing Engineer

TELEPHONE NUMBER

5 1 2 9 7 2 - 8 6 2 8

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

| CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NRC | CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NRC |
|-------|--------|-----------|--------------|-------------------|-------|--------|-----------|--------------|-------------------|
| B | I | P P D T | I 2 0 4 | Yes | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

SUPPLEMENTAL REPORT EXPECTED (14)

EXPECTED SUBMISSION DATE (15)

MONTH DAY YEAR

YES (If yes, complete EXPECTED SUBMISSION DATE)

X

NO

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

On April 20, 1991, Unit 1 was in mode 1 at 100% power. At 0406 hours, while conducting a containment supplemental purge to lower the containment pressure in response to a Containment High Pressure alarm, containment extended range pressure channel 9759 was found to read 5 psig while channel 9760 read 0 psig. Channel 9759 was declared inoperable at 0407 hours. Review of historical computer records indicated that the channel had been inoperable in excess of the seven-day allowed outage time. After initial recalibration, subsequent channel check surveillance revealed an additional erratic output signal by the transmitter. The transmitter control card was replaced and the transmitter was calibrated. Channel checks were performed weekly for one month to confirm the channel was repaired. Although no generic failure mechanism has been established, the failure rates are consistent with industry experience. These transmitters are being monitored under the facility trending program.

LER\92007001.U1

9201220010 920113
PDR ADOCK 05000498
S PDR

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 600 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20586, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

TEXT (If more space is required, use additional NRC Form 854's) (17)

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 60.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

| | | | | | | | |
|--|-----------------------------------|----------------|----------------------|--------------------|----------|----|----|
| FACILITY NAME (1) South Texas, Unit 1 | DOCKET NUMBER (2) 05000498 | LER NUMBER (6) | | | PAGE (3) | | |
| | | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | | | |
| | | 91 | 014 | 010 | 3 | OF | 04 |

TEXT (If more space is required, use additional NRC Form 365A's) (17)

CAUSE OF EVENT:

This channel failed due to a bad control card. The specific failure mechanism for the control card is unknown, but may be due to a cracked thermistor. Further investigation has not identified any generic concerns with the Barton 752 transmitter.

ANALYSIS OF EVENT:

Monitoring of containment pressure is important during an accident to ensure containment integrity. The consequences of this instrument malfunction are an increased risk of inappropriate actions in an accident condition due to erroneous indication. However, instrument redundancy was provided by channel 9760. This event did not result in any adverse safety or radiological concerns, nor did it threaten the safety of the public at any time. Reportability of this event was discussed with the Senior Resident Inspector and Mr. J. Crooks of the NRC. Since firm evidence in computer historical data was available regarding the length of time the channel was out-of-service, Question 2.3 of NUREG-1022, Supplement 1, was found to apply. Accordingly, this event represents operation in a condition prohibited by Technical Specifications, which is reportable pursuant to 10CFR50.73(a)(2)(i)(B).

CORRECTIVE ACTIONS:

The following corrective actions are being taken as a result of this event:

1. After the first discovery of the inoperable channel, the channel was calibrated and returned to service on April 21, 1991.
2. After the second discovery of the inoperable channel, the channel was removed from service, the control card was replaced, and the channel was returned to service on May 3, 1991.
3. Weekly channel checks were performed until May 31, 1991, to verify that the channel had been repaired by the card replacement.

LER\92007001.U1

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

| | | | | | |
|--|--|----------------|-------------------|-----------------|--|
| FACILITY NAME (1) South Texas, Unit 1 | DOCKET NUMBER (2) 0 5 0 0 0 4 9 8 9 1 - 0 1 4 - 0 1 | LER NUMBER (6) | | PAGE (3) | |
| | | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | |
| | | | | | |

TEXT (If more space is required, use additional NRC Form 386A's) (17)

CORRECTIVE ACTIONS: (Cont'd)

- .. Using NPRDS data, HL&P has evaluated the failure rate of safety-related Barton Model 752 transmitters in pressure-related applications at STPEGS where repair or replacement was required. No generic concern has been identified. The failures at STPEGS have been attributed to normal aging or to unknown causes. No evidence of improper maintenance or operation is indicated as a cause for failure. These transmitters are being monitored under the facility trending program to identify failure trends should they develop.

No generic mechanism for failures of the STPEGS Barton 752 transmitters has been identified. Review of the NPRDS database up to December 19, 1991, indicates that the failure rate is consistent with that experienced by the rest of the industry as reported to NPRDS.

5. Procedures have been clarified to ensure that plant operators check the extended range containment pressure readings when Containment High Pressure is annunciated in the Control Room. This action was taken to minimize the potential for exceeding the allowed outage time of the extended range containment pressure channel.

ADDITIONAL INFORMATION:

The affected transmitter is a Barton Model 752. No corrective maintenance has previously been required on the Barton Model 752 for containment pressure channel 9759. Necessary information has been submitted to NPRDS.

NPRDS includes fourteen previously reported failures of safety-related Barton 752 transmitters in pressure-related applications at STPEGS which required repair or replacement since December 1988 (ten from Unit 1, and four from Unit 2).

There have been no previous LERs due to transmitter failure.

LER\92007001.U1