



Nuclear Group  
P.O. Box 4  
Shippingport, PA 15077-0004

Telephone (412) 393-6000

November 10, 1995  
NPD1VPO:0402

*Beaver Valley Power Station, Unit No. 1  
Docket No. 50-334, Licensee No. DPR-66  
LER-95-008-00*

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555


In accordance with Appendix A, Beaver Valley Technical Specifications, the following Licensee Event Report is submitted:

LER 95-008-00, 10 CFR 50.73.a.2.i.B, "Technical Specification 3.0.3 Entry Due to Isolation of Control Room Emergency Habitability System".

T. P. Noonan  
Division Vice President  
Nuclear Operations/Plant Manager

JHK/jcd

Attachment



**The Nuclear Professionals**

9511140139 951110  
PDR ADDCK 05000334  
S PDR

*JE221*

November 10, 1995

NPD1VPO:0402

Page 2

cc: Mr. T. T. Martin, Regional Administrator  
United States Nuclear Regulatory Commission  
Region 1  
475 Allendale Road  
King of Prussia, PA 19406

Mr. D. S. Brinkman  
BVPS Licensing Project Manager  
United States Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Larry Rossbach  
BVPS Senior Resident Inspector  
United States Nuclear Regulatory Commission

Mr. J. A. Hultz  
Ohio Edison Company  
76 S. Main Street  
Akron, OH 44308

Mr. Mark Burns  
Centerior Energy Corporation  
6200 Oak Tree Boulevard  
Independence, OH 44101-4661

INPO Records Center  
700 Galleria Parkway  
Atlanta, GA 30339-5957

Mr. Robert Maiers  
Department of Environmental Resources  
P.O. Box 8469  
State Office Building, 13th Floor  
Harrisburg, PA 17105-8469

Director, Safety Evaluation & Control  
Virginia Electric & Power Company  
P.O. Box 26666  
One James River Plaza  
Richmond, VA 23261

## LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

Beaver Valley Power Station Unit 1

DOCKET NUMBER (2)

05000334

PAGE (3)

1 OF 3

## Technical Specification 3.0.3 Entry Due to Isolation of Control Room Emergency Habitability System

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER	
10	13	95	95	008	00	11	10	95	Beaver Valley Unit 2	05000412	
									FACILITY NAME	DOCKET NUMBER	
										05000	
OPERATING MODE (9)		1	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 20 CFR § (Check one or more) (11)								
			20.402(b)			20.405(c)			50.73(a)(2)(iv)		73.71(b)
POWER LEVEL (10)		100	20.405(a)(1)(i)			50.36(c)(1)			50.73(a)(2)(v)		73.71(c)
			20.405(a)(1)(ii)			50.36(c)(2)			50.73(a)(2)(vii)		OTHER
			20.405(a)(1)(iii)			X 50.73(a)(2)(i)			50.73(a)(2)(viii)(A)		(Specify in abstract below and in Text
			20.405(a)(1)(iv)			50.73(a)(2)(ii)			50.73(a)(2)(viii)(B)		
			20.405(a)(1)(v)			50.73(a)(2)(iii)			50.73(a)(2)(x)		NRC Form 366A)

## LICENSEE CONTACT FOR THIS LER (12)

NAME

T. P. Noonan, Division Vice President Nuclear Operations/Plant Manager

TELEPHONE NUMBER (include Area Code)

(412) 393-7622

## COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS				COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
X	IL	XXXX	XXXX	N						

## SUPPLEMENTAL REPORT EXPECTED (14)

YES (if yes, complete EXPECTED SUBMISSION DATE)	X	NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limited to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On 10/13/95 at 0914 hrs., with both Units at full power, a spurious Train A Control Room Emergency Habitability System (CREHS) actuation occurred during a radiation monitor source check. A health physics technician was performing a quarterly source check on the monitors, per an inventory verification procedure which allows for inference of source material by verifying monitor response. The check source button is depressed which inhibits control room alarms and blocks a CREHS actuation on high control room radiation. The source check was performed on the Train B monitor first without any problems or alarms. During the check of the Train A monitor a spurious CREHS actuation occurred, and the air bottles began discharging into the common Beaver Valley control rooms. After verifying that no valid actuation signals existed, an operator was dispatched to isolate the air bottles. This was performed to maintain the air bottles above the Technical Specification (TS) limit of 1825 psig, and to eliminate the need to recharge the air bottles prior to returning them to service. The bottles were isolated at 0917 hrs., which intentionally placed both Beaver Valley Units in TS 3.0.3. After the high radiation alarm cleared, the Train A signal was reset and the air bottles were unisolated at 0936 hrs., and TS 3.0.3 was exited. All of the air bottles remained above the TS value of 1825 psig.

**LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)		DOCKET NUMBER (2)		LER NUMBER (6)			PAGE (3)
Beaver Valley Power Station Unit 1		05000334		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 3
				95	008	00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

**DESCRIPTION OF EVENT**

On October 13, 1995 at 0914 hours, with both Units in Operational Mode 1 at full power, a spurious Train A Control Room Emergency Habitability System actuation occurred during a radiation monitor source check. A health physics technician was performing a source check on the control room radiation monitors, RM-1RM-218A and RM-1RM-218B, in accordance with a quarterly source inventory verification procedure. The health physics procedure allows for inference of source material contained in radiation monitoring equipment by verifying a proper operational response check. The check source pushbutton is depressed which inhibits control room annunciators and blocks a Control Room Emergency Habitability System actuation on high control room radiation while the radiation source is exposed to the detector. The radiation source strength is greater than the high alarm setpoint for the radiation monitor.

The source check was performed on the Train B monitor (RM-1RM-218B) first without any problems or alarms. During the check of the Train A monitor (RM-1RM-218A), as the detector's response rose above the high alarm setpoint, a spurious Control Room Emergency Habitability System actuation occurred, and the Control Room Emergency Habitability Air Bottles began discharging into the control rooms. Both Beaver Valley control rooms share a common pressure boundary envelope. After verifying that no valid actuation signals existed at either Unit, an operator was dispatched to isolate the air bottles. This action was taken to maintain the air bottles above the Technical Specification limit of 1825 psig, and to eliminate the need to recharge the air bottles prior to returning them to service. The bottles were isolated at 0917 hours, which intentionally placed both Beaver Valley Units in Technical Specification 3.0.3.

After the high radiation alarm cleared, the Control Room Emergency Habitability System was restored in accordance with operating manual procedure 1/2OM-44A.4A.A, Post Control Room Habitability System Actuation/Recovery. The Train A signal was reset and the air bottles were unisolated at 0936 hours, and Technical Specification 3.0.3 was exited at this time. All of the air bottles remained above the Technical Specification value of 1825 psig.

It should be noted that prior to this event, on October 12, 1995, an Operations Surveillance Test, 1/2OST-43.17A, Control Room Area Monitor [RM-1RM-218A] Functional Test, was performed. The surveillance test performs a source check of the monitor. No abnormal alarms or actuations occurred during the source check.

**CAUSE OF EVENT**

An investigation into the cause of the spurious Control Room Emergency Habitability System is continuing by the Instrumentation and Control Department. Operations Surveillance Test 1/2OST-43.17A was performed on RM-1RM-218A on November 2, 1995. No abnormal alarms or actuations occurred during the source check.

**LICENSEE EVENT REPORT (LER)**  
**TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)		DOCKET NUMBER (2)		LER NUMBER (6)			PAGE (3)
				YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Beaver Valley Power Station Unit 1		05000334		95	008	00	3 OF 3

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

**CORRECTIVE ACTIONS**

1. As an interim measure, a caution tag was placed on the check source pushbutton for RM-IRM-215A to prevent operation without authorization from the Nuclear Shift Supervisor.
2. Additional corrective actions will be implemented following the ongoing investigation by the Instrumentation and Control Department.
3. Health Physics will eliminate the quarterly source check, and instead will rely on the source check conducted by Operations during routine surveillance testing.

**REPORTABILITY**

Entry into Technical Specification 3.0.3 is considered a condition prohibited by Technical Specifications. This written report is being submitted in accordance with 10 CFR 50.73.a.2.i.B.

**SAFETY IMPLICATIONS**

There were no safety implications as a result of this event. The Control Room Emergency Habitability System functioned as designed upon receipt of an actuation signal. Since the bottles were isolated in a timely manner, the air bottle subsystem remained above the Technical Specification limit of 1825 psig. This minimized the time in Technical Specification 3.0.3 by eliminating the need to repressurize the air bottles. The subsystem was inoperable solely because it was manually isolated for 19 minutes, during which it could have been returned to service if a valid need arose, as an operator was stationed at the bottle isolation valves for this purpose.

**SIMILAR EVENTS**

The following similar events have been previously reported regarding the isolation of the Control Room Emergency Habitability System air bottles and entry into Technical Specification 3.0.3:

Beaver Valley Power Station Unit 1:

LER 93-003 - involved a spurious signal on a radiation monitor while manipulating a monitor control switch during testing.

LER 95-005 - involved an electrical noise spike on either the control room radiation monitor drawer or a containment high range monitor drawer, which are physically adjacent in the rack in the control room.

Beaver Valley Power Station Unit 2:

LER 95-001 - involved a spurious signal on a radiation monitor during reconnection of a power connector on a containment high range radiation monitor.

LER 95-002 - involved a spurious signal caused by an alligator clip accidentally contacting an adjacent terminal while installing an electrical jumper for testing.