

DUKE POWER COMPANY

P.O. BOX 33189

CHARLOTTE, N.C. 28242

HAL B. TUCKER

VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

August 22, 1984


Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Subject: Oconee Nuclear Station
Docket No. 50-287
RO-287/83-13 Supplement

Dear Sir:

This information supplements Reportable Occurrence Report RO-287/83-13 Revision 1 submitted January 9, 1984 concerning a containment isolation valve, 3CS-5, which was declared inoperable due to leakage past the seat. In accordance with the corrective actions stated in the report, an investigation into the valve failure was conducted. During the Unit 3 End of Cycle 7 Refueling Outage, valve 3CS-5 was checked to determine the cause for the leak past its seat. Leads to the motor were checked for proper motor wiring connections. The bonnet and limotorque operator were removed. The diaphragm was checked with no damage found. However, the diaphragm was replaced with a new one for the purpose of preventative maintenance. The valve was cycled with no additional problems being found.

Very truly yours,



Hal B. Tucker

JCP:slb

cc: Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

Mr. J. C. Bryant
NRC Resident Inspector
Oconee Nuclear Station

8408300497 840822
PDR ADOCK 05000287
S PDR

IE22
1/0

Document Control Desk
August 22, 1984
Page 2

cc: Ms. Helen Nicolaras
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555