

LICENSEE EVENT REPORT

UPDATE REPORT:

PREVIOUS REPORT DATE: 5-5-83

CONTROL BLOCK:

1	2	3	4	5	6
					1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	2	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36
LICENSEE CODE		LICENSE NUMBER										LICENSE TYPE										57 CAT 58							

CON'T

0	1	L	6	0	5	0	-	0	3	2	4	7	0	4	0	8	8	3	8	0	9	0	6	8	4	9
7	8	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80				
REPORT SOURCE		DOCKET NUMBER										EVENT DATE										REPORT DATE				

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During unit power operation, a routine channel check of reactor level instrumentation

0 3 | revealed reactor level instrument 2-B21-LT-N017D-1 was indicating a level of 194" while

0 4 | redundant instrumentation indicated a level of 187". N017D-1 supplies a low level in-

0 5 | put to the RPS and PCIS to initiate a reactor scram and a Group 2, 6, 7, and 8 isola-

0 6 | tion signal at $\geq 162.5"$. This event did not affect the health and safety of the

0 7 | public.

0 8 | Technical Specifications 2.2.1, 3.3.2, 6.9.1.9b

0	9	I	A	11	B	12	C	13	P	I	P	E	X	X	14	A	15	Z	16
7	8	9	10	11	12	13	14	15	16	17	18	19	20						
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE							
17		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.									
8 3		0 4 5		0 3		L		1											
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
X 18		Z 19		Z 20		Z 21		0 0 0 0		Y 23		Y 24		A 25		R 3 6 9 26			
33		34		35		36		37		41		42		43		44			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | It is believed that crud accumulation in the N017D-1 variable sensing leg tubing

1 1 | resulted in a high variable leg level, which caused N017D-1 to detect a higher than

1 2 | actual level. During unit shutdown on April 8, 1983, the N017D-1 reference and

1 3 | variable sensing leg tubing was flushed to clear the tubing of any crud accumulation.

1 4 | No further action specifically regarding this event is planned.

1	5	E	28	1	0	0	29	30	NA	31	A	32	Operator Surveillance
7	8	9	10	11	12	13	14	15	16	17	18	19	20
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
1 5		1 0 0		NA		A		Operator Surveillance					
ACTIVITY		CONTENT		AMOUNT OF ACTIVITY		LOCATION OF RELEASE							
1 6		Z 33		NA		NA							
PERSONNEL EXPOSURES		TYPE		DESCRIPTION									
1 7		0 0 0		NA									
PERSONNEL INJURIES		TYPE		DESCRIPTION									
1 8		0 0 0		NA									
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION									
1 9		Z 42		NA									
PUBLICITY		TYPE		DESCRIPTION									
2 0		N 44		NA									
ISSUED		DESCRIPTION											

8409240263 840906
PDR ADOCK 05000324
S PDR
NA

IE22 1/1

NAME OF PREPARER M. J. Pastva, Jr.

PHONE: 919-457-9521

NRC USE ONLY

LER ATTACHMENT - RO #2-83-45

Facility: BSEP Unit 2

Event Date: April 8, 1983

During Unit 2 power operation on April 8, 1983, a routine channel check of reactor level instrumentation revealed that reactor level instrument 2-B21-N017D-1 showed a level indication of 194 inches. At the time, redundant instrumentation showed a level indication of 187 inches. 2-B21-N017D-1 supplies a reactor low level input to the Reactor Protection System (RPS) and the Primary Containment Isolation System (PCIS) to initiate a reactor scram and a PCIS Group 2, 6, 7, and 8 signal at a reactor level of greater than or equal to 162.5 inches.

Initial investigation of this event revealed small leaks on the valve packing nut of the N017D-1 reference leg flow bypass valve. The leaks were suspected of allowing the instrument reference leg level to decrease and cause N017D-1 to sense a higher than actual reactor level. The leaks were eliminated, the reference leg was refilled to compensate for level decrease, and N017D-1, Rosemount Inc., Model No. 1152, was returned to service. In addition, during subsequent shutdown of Unit 2 on April 8, 1983, the N017D-1 reference and variable sensing leg tubing was flushed to ensure the tubing was clear of any possible crud accumulation which may have caused or contributed to the event.

Following the return of N017D-1 to service, further investigation of this event was conducted by plant Engineering with assistance from the plant I&C Maintenance group and from the General Electric Company. During this investigation, the equalizing valve between the reference and variable sensing legs of N017D-1 was checked for valve seat leakage which could have caused a level decrease in the instrument reference leg. The check of this equalizing valve revealed no valve seat leakage.

The reference leg tubing to N017D-1 was installed in July 1980, as part of a modification to install analog-type reactor level instrumentation on Unit 2. No other similar problems have occurred involving N017D-1 on Unit 2 since the April 8, 1983, back flush of the instrument's sensing leg tubing. It is concluded the event resulted from crud in the tubing which was in the tubing prior to installation of the involved modification. The investigation determined the crud problem was confined to instruments operating off the subject sensing leg tubing installed by the July 1980 modifications; therefore, no further action is required regarding this event.



Carolina Power & Light Company

34 SEP 10 1:20

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429
September 6, 1984

FILE: B09-13510C
SERIAL: BSEP/84-1926

Mr. James P. O'Reilly, Administrator
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street N.W.
Atlanta, GA 30323

BRUNSWICK STEAM ELECTRIC PLANT UNIT 2
DOCKET NO. 50-324
LICENSE NO. DPR-62
SUPPLEMENT TO LICENSEE EVENT REPORT 2-83-45

Dear Mr. O'Reilly:

In accordance with Section 6.9.1.9b of the Technical Specifications for Brunswick Steam Electric Plant Unit 2, the enclosed supplemental Licensee Event Report is submitted. The original report fulfilled the requirement for a written report within thirty (30) days of a reportable occurrence and both are in accordance with the format set forth in NUREG-0161, July 1977.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

RMP/sdl/LETC4

Enclosure

cc: Mr. R. C. DeYoung
NRC Document Control Desk

OFFICIAL COPY

11
1622