

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) EDWIN I. HATCH, UNIT 2										DOCKET NUMBER (2) 0 5 0 0 0 3 6 6				PAGE (3) 1 OF 0 1		
TITLE (4) ESF System Actuation Due to Procedure Inadequacy																
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)						
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES			DOCKET NUMBER(S)				
0 8	2 1	8 4	8 4	0 2 0	0 0	0 9	2 0	8 4				0 5 0 0 0				
OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following) (11)														
5		20.402(b)				20.405(c)				<input checked="" type="checkbox"/> 50.73(a)(2)(iv)		73.71(b)				
POWER LEVEL (10)		20.405(a)(1)(i)				50.38(c)(1)				<input type="checkbox"/> 50.73(a)(2)(v)		73.71(c)				
0 0 0		20.405(a)(1)(ii)				50.38(c)(2)				<input type="checkbox"/> 50.73(a)(2)(vii)		OTHER (Specify in Abstract below and in Text, NRC Form 366A)				
		20.405(a)(1)(iii)				50.73(a)(2)(i)				<input type="checkbox"/> 50.73(a)(2)(viii)(A)						
		20.405(a)(1)(iv)				50.73(a)(2)(ii)				<input type="checkbox"/> 50.73(a)(2)(viii)(B)						
		20.405(a)(1)(v)				50.73(a)(2)(iii)				<input type="checkbox"/> 50.73(a)(2)(x)						
LICENSEE CONTACT FOR THIS LER (12)																
NAME T. L. Elton, Acting Superintendent of Regulatory Compliance										TELEPHONE NUMBER AREA CODE 9 1 2 3 6 7 1 7 8 5 1						
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS						
SUPPLEMENTAL REPORT EXPECTED (14)										EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR		
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)										<input checked="" type="checkbox"/> NO						
ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)																
<p>On 8/21/84 at approximately 1305 CDT, during the performance of "TURBINE FIRST STAGE PRESSURE PERMISSIVE FT&C" procedure (HNP-2-3010) an unplanned full RPS actuation occurred.</p> <p>Further investigation revealed that a full RPS actuation occurred because links were opened when the turbine was off line when HNP-2-3010 step F.5 was performed.</p> <p>HNP-2-3010 will be revised by 10/1/84 so that it can be performed in any turbine condition without causing a full RPS actuation.</p>																
8409280263 840920 PDR ADOCK 05000366 S PDR																

IE22
111

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
EDWIN I. HATCH, UNIT 2	0 5 0 0 0 3 6 6 8 4	—	0 2 0	— 0 0 0	2	OF 0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)


This 30 day report is required by 10CFR50.73(a)(2)(iv) due to this event's resulting in automatic actuation of an ESF (RPS).

On 08/21/84 at approximately 1305 CDT, the unit was in shutdown in a recirculation pipe outage when an unplanned full RPS actuation occurred. All the control rods were already inserted so a scram did not occur. Personnel were opening links as listed in Table 1 following step F.5 of the "TURBINE FIRST STAGE PRESSURE PERMISSIVE FT&C" procedure (HNP-2-3010) when a full RPS logic actuation occurred.

Further investigation revealed that this event is due to a procedural inadequacy. The RPS actuation occurred because the turbine was off line when HNP-2-3010 step F.5 was performed. During normal performance of this step when the reactor is below 30% power, opening these links will bypass the turbine stop valves' closure. But when this procedure was most recently performed, the turbine stop valves were already closed. Opening these links removed the bypass and caused an RPS actuation.

HNP-2-3010 will be revised by 10/1/84 to allow for procedure performance in any turbine condition without causing a full RPS actuation.

Georgia Power Company
Post Office Box 439
Baxley, Georgia 31513
Telephone 912 367-7781
912 537-9444




Edwin i. Hatch Nuclear Plant

September 20, 1984
GM-84-819

PLANT E. I. HATCH
Licensee Event Report
Docket No. 50-366

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Attached is Licensee Event Report No. 50-366/1984-020. This report
is required by 10CFR 50.73(a)(2)(iv).


H. C. Nix
General Manager

see
HCN/TLE/vlz

xc: R. J. Kelly
R. E. Conway
J. T. Beckham, Jr.
P. D. Rice
K. M. Gillespie
Superintendent of Regulatory Compliance
R. D. Baker
Control Room
Document Control

IE22
1/1