

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Dresden Nuclear Power Station										DOCKET NUMBER (2) 0 5 0 0 0 2 4 9										PAGE (3) 1 OF 0 2																																		
TITLE (4) Reactor Scram on Low Water Level																																																						
EVENT DATE (5)										LER NUMBER (6)										REPORT DATE (7)										OTHER FACILITIES INVOLVED (8)																								
MONTH			DAY			YEAR			YEAR			SEQUENTIAL NUMBER			REVISION NUMBER			MONTH			DAY			YEAR			FACILITY NAMES										DOCKET NUMBER(S)																	
																											N/A										0 5 0 0 0																	
0 8			2 1			8 4			8 4			0 1 0			0 0			0 9			1 0			8 4			N/A										0 5 0 0 0																	
OPERATING MODE (9) N										THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5: (Check one or more of the following) (11)																																												
POWER LEVEL (10) 0 9 7										20.402(b)										20.406(c)										<input checked="" type="checkbox"/> 50.73(a)(2)(iv)										73.71(b)														
										20.406(a)(1)(i)										50.36(c)(1)																				73.71(c)														
										20.406(a)(1)(ii)										50.36(c)(2)																				OTHER (Specify in Abstract below and in Text, NRC Form 366A)														
										20.406(a)(1)(iii)										50.73(a)(2)(i)																																		
										20.406(a)(1)(iv)										50.73(a)(2)(ii)																																		
										20.406(a)(1)(v)										50.73(a)(2)(iii)																																		
										20.406(a)(1)(vi)										50.73(a)(2)(iv)																																		
LICENSEE CONTACT FOR THIS LER (12)																																																						
NAME Lawrence Coyle (X-483)																				TELEPHONE NUMBER 8 1 1 5 9 1 4 2 1 - 1 2 1 9 2 1 0																																		
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																																																						
CAUSE					SYSTEM					COMPONENT					MANUFACTURER					REPORTABLE TO NPROS					CAUSE					SYSTEM					COMPONENT					MANUFACTURER					REPORTABLE TO NPROS									
X					SIJ					IFICIV					CI6165					N																																		
SUPPLEMENTAL REPORT EXPECTED (14)																																																						
YES (If yes, complete EXPECTED SUBMISSION DATE)																				<input checked="" type="checkbox"/> NO										EXPECTED SUBMISSION DATE (15)																								
																														MONTH DAY YEAR																								

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During normal operation, the "A" feedwater regulating valve operator vibrated loose from the valve stem coupling. The valve disc failed in the closed direction, causing the reactor to scram on low water level. Safety significance was minimal, since all emergency systems operated as designed. Previous similar occurrence reported by R.O. 84-09 on Docket 50-237.

The operator and valve stem were reconnected and holes were drilled into the coupling block and locknuts so set screws could be placed to secure the valve stem and valve operator to the coupling block.

8409280586 840910  
PDR ADDCK 05000249  
S PDR

FE22  
11

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Dresden Nuclear Power Station Unit 3	05000249	84	010	00	02	OF	02

TEXT (If more space is required, use additional NRC Form 368A's) (17)

During normal operation the "A" feedwater regulating valve (A03-642A) operator separated from the valve stem coupling. The valve disc failed in the closed direction, causing a reactor scram on low water level. Safety significance was minimal, since all emergency systems operated as designed. Previous similar occurrence reported by R.O. 84-09 on Docket 50-237.

The cause of the event was the loosening, due to vibration, of the locknut securing the operator to the coupling block at the top of the valve stem. The loose locknut permitted the operator to vibrate loose from the coupling block allowing the coupling block and the attached valve stem to fall into the closed position. The valve operator was reattached to the coupling block. To prevent a recurrence holes were drilled into the top and bottom side of the coupling block and set screws were installed to wedge against the valve operator and the valve stem. Also, holes were drilled into the top and bottom locknuts and set screws were installed to wedge against the top and bottom of the coupling block to prevent the locknuts from moving. This procedure was repeated on the "B" feedwater regulating valve. Set screws will be installed in the Unit 2 "A" feedwater regulating valve coupling block and associated locknuts during the fall 1984 refuel outage. The 2"B" feedwater regulating valve is of a different type, and will not require set screws.



**Commonwealth Edison**

Dresden Nuclear Power Station

R.R. #1

Morris, Illinois 60450

Telephone 815/942-2920

September 13, 1984

DJS Ltr #84-908

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Licensee Event Report #84-010-0, Docket #050-249 is being submitted as required by Technical Specification 6.6, NUREG 1022 and 10 CFR 50.73 (a)(2)(iv).

D.J. Scott  
Station Superintendent  
Dresden Nuclear Power Station

DJS/kjl

Enclosure

cc: J.G. Keppler, Regional Administrator, Region III  
File/NRC  
File/Numerical

IE22  
11