

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) JAMES A. FITZPATRICK NUCLEAR POWER PLANT										DOCKET NUMBER (2) 0 5 0 0 0 3 3 3					PAGE (3) 1 OF 0 1						
TITLE (4) Reactor Scram During Surveillance Testing																					
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)											
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES				DOCKET NUMBER(S)								
1	0	2	8	8	4	0	2	2	0	0	1	1	1	3	8	4	0	5	0	0	0
OPERATING MODE (9) N		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																			
POWER LEVEL (10) 0 1 0 1 0		20.402(b)				20.406(c)				<input checked="" type="checkbox"/> 50.73(a)(2)(iv)				73.71(b)							
		20.406(a)(1)(i)				50.36(c)(1)				<input type="checkbox"/> 50.73(a)(2)(v)				73.71(e)							
		20.406(a)(1)(ii)				50.36(c)(2)				<input type="checkbox"/> 50.73(a)(2)(vii)				OTHER (Specify in Abstract below and in Text, NRC Form 365A)							
		20.406(a)(1)(iii)				50.73(a)(2)(i)				<input type="checkbox"/> 50.73(a)(2)(viii)(A)											
		20.406(a)(1)(iv)				50.73(a)(2)(ii)				<input type="checkbox"/> 50.73(a)(2)(viii)(B)											
		20.406(a)(1)(v)				50.73(a)(2)(iii)				<input type="checkbox"/> 50.73(a)(2)(x)											
LICENSEE CONTACT FOR THIS LER (12)																					
NAME Douglas J. Lindsey										TELEPHONE NUMBER											
										AREA CODE 3 1 5 3 4 2 - 3 8 4 0											
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																					
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDs		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDs											
SUPPLEMENTAL REPORT EXPECTED (14)												EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR					
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)												<input checked="" type="checkbox"/> NO									

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During a cold shutdown condition, a full scram trip occurred while conducting surveillance testing as required by Technical Specifications Table 4.1-1 on the "Average Power Range Monitors (APRM)". Testing had been completed on an "A" Reactor Protection System APRM; however its scram signal was not reset prior to commencing "B" Reactor Protection System APRM testing. This testing resulted in a "B" side trip signal which resulted in a full scram. The cause of the full scram was operator error due to a communication break down between the Control Room Operator and the operator performing the testing. The operators were counseled on the event.

8411260540 841113
PDR ADOCK 05000333
S PDRIE 22
11

James A. FitzPatrick
Nuclear Power Plant
P.O. Box 41
Lycoming, New York 13093
315 342.3840



Harold A. Glovier
Resident Manager

November 13, 1984
JAFP 84-1051

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

REFERENCE: DOCKET NO. 50-333 Licensee Event Report: 84-022-00

Dear Sir:

We have enclosed the referenced Licensee Event Report in accordance with
10CFR50.73

If there are any questions concerning this report, please contact Mr. Douglas J.
Lindsey at (315) 342-3840, Extension 302.

by dir. R. Cameron

H. A. GLOVIER

HAG
HAG:DJL:dmh

Enclosure

CC: USNRC, Region I (1)
INPO Records Center, Atlanta, Georgia (1)
Internal Power Authority Distribution
American Nuclear Insurers (1)
NRC Resident Inspector
Document Control Center
LER/OR File

IE22
11