

LICENSEE EVENT REPORT (LER)

| | | | | | | | | | | | | | | | | |
|--|--------|--|----------------|-------------------|-----------------|------------------|-----------------|-----------|----------------|--|--|-------------------------------|------------------|--|-----|------|
| FACILITY NAME (1) Susquehanna Steam Electric Station - Unit 1 | | | | | | | | | | DOCKET NUMBER (2) 0 5 0 0 0 3 8 7 | | | | PAGE (3) 1 OF 0 1 | | |
| TITLE (4) Fire Barrier Penetration Not Sealed. | | | | | | | | | | | | | | | | |
| EVENT DATE (5) | | | LER NUMBER (6) | | | | REPORT DATE (7) | | | OTHER FACILITIES INVOLVED (8) | | | | | | |
| MONTH | DAY | YEAR | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | MONTH | DAY | YEAR | FACILITY NAMES | | | | DOCKET NUMBER(S) | | | |
| 0 8 | 2 2 | 8 4 | 8 4 | 0 4 6 | 0 0 1 1 | 1 6 | 8 4 | | | | | | 0 5 0 0 0 | | | |
| OPERATING MODE (9) | | THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 8: (Check one or more of the following) (11) | | | | | | | | | | | | | | |
| 1 | | 20.402(b) | | | | 20.406(e) | | | | 80.73(a)(2)(iv) | | | | 73.71(b) | | |
| POWER LEVEL (10) | | 20.406(a)(1)(ii) | | | | 80.38(a)(1) | | | | 80.73(a)(2)(v) | | | | 73.71(c) | | |
| 1 1 0 1 0 | | 20.406(a)(1)(iii) | | | | 80.38(a)(2) | | | | 80.73(a)(2)(vi) | | | | OTHER (Specify in Abstract below and in Text, NRC Form 365A) | | |
| | | 20.406(a)(1)(iii) | | | | 80.73(a)(2)(i) | | | | 80.73(a)(2)(viii)(A) | | | | | | |
| | | 20.406(a)(1)(iv) | | | | 80.73(a)(2)(ii) | | | | 80.73(a)(2)(viii)(B) | | | | | | |
| | | 20.406(a)(1)(v) | | | | 80.73(a)(2)(iii) | | | | 80.73(a)(2)(ix) | | | | | | |
| LICENSEE CONTACT FOR THIS LER (12) | | | | | | | | | | | | | | | | |
| NAME T.P. Baileys | | | | | | | | | | TELEPHONE NUMBER | | | | | | |
| | | | | | | | | | | AREA CODE 7 1 1 7 5 4 2 1 - 1 3 2 4 1 1 | | | | | | |
| COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13) | | | | | | | | | | | | | | | | |
| CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NRC | | CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NRC | | | | | | |
| B | * | S I E A L | X 1 9 9 9 | N | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | |
| SUPPLEMENTAL REPORT EXPECTED (14) | | | | | | | | | | | | EXPECTED SUBMISSION DATE (15) | | MONTH | DAY | YEAR |
| YES (If yes, complete EXPECTED SUBMISSION DATE) | | | | | | | | | | | | X NO | | | | |

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (15)

A Quality Control inspector discovered an open penetration in the ceiling of the Unit 1 Lower Cable Spreading Room on August 22, 1984. The inspector notified the work group responsible for sealing penetrations and a work authorization was initiated. The personnel identifying the problem and personnel responsible for the repair activities failed to recognize this as a condition which required action per Technical Specification 3.7.7 and did not report it to the Operations Section. When the work authorization was presented to Operations for approval to do the work on October 15, 1984, the Technical Specification 3.7.7 action statement was implemented. It could not be determined how or when the penetration was breached. The penetration has been sealed and this LER will be discussed with Quality Control and Maintenance personnel to ensure proper recognition and handling of potential LCO conditions.

The fire barrier was not included in the surveillance procedure due to incomplete incorporation of revisions to the Fire Protection Plan after the procedure was issued. The procedure has been reviewed to ensure its completeness and the affected fire barriers will be added to the procedure and inspected. An update to this LER will be submitted if additional unsealed penetrations are found.

*Fire Barrier

8411280568 841116
PDR ADDCK 05000387
S PDRIE22
11

PP&L

SUSQUEHANNA STEAM ELECTRIC STATION
PO BOX 467, BERWICK, PA 18603

November 16, 1984

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 84-046-00
ER 100450 FILE 841-23
PLAS-013

Docket No. 50-387
License No. NPF-14

Attached is Licensee Event Report 84-046-00. This event was determined reportable per 10CFR50.73(a)(2)(i)(B), in that an unsealed fire barrier penetration was discovered. The fire barrier penetration was sealed and the barrier will be added to the surveillance procedure.

H.W. Keiser

H.W. Keiser
Superintendent of Plant-Susquehanna

TPB/pjg

cc: Dr. Thomas E. Murley
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Mr. R.H. Jacobs
Senior Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 52
Shickshinny, PA 18655

IE22
11