

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) EDWIN I. HATCH, UNIT 366										DOCKET NUMBER (2) 0 5 0 0 0 3 6 6 1 OF 0 2										PAGE (3) 1 OF 0 2	
TITLE (4) Obstructed Fire Door																					
EVENT DATE (5)			LER NUMBER (8)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)											
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES				DOCKET NUMBER(S)								
0 8	1 0	8 4	8 4	0 2 9	0 0 1	1 2	1 8	4					0 5 0 0 0								
OPERATING MODE (9) 5			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)																		
POWER LEVEL (10) 0 0 0			20.402(b)				20.406(c)				50.73(a)(2)(iv)				73.71(b)						
			20.406(a)(1)(i)				50.36(c)(1)				50.73(a)(2)(v)				73.71(c)						
			20.406(a)(1)(ii)				50.36(c)(2)				50.73(a)(2)(vii)				OTHER (Specify in Abstract below and in Text, NRC Form 366A)						
			20.406(a)(1)(iii)				X 50.73(a)(2)(i)				50.73(a)(2)(viii)(A)										
			20.406(a)(1)(iv)				50.73(a)(2)(ii)				50.73(a)(2)(viii)(B)										
			20.406(a)(1)(v)				50.73(a)(2)(iii)				50.73(a)(2)(x)										
LICENSEE CONTACT FOR THIS LER (12)																					
NAME T. L. Elton Acting Supt. of Regulatory Compliance										TELEPHONE NUMBER 9 1 2 3 6 7 - 1 7 8 5 1											
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																					
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE				SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC									
A	K P	I D I R O 1 1 Q 5	N																		
SUPPLEMENTAL REPORT EXPECTED (14)																					
YES (If yes, complete EXPECTED SUBMISSION DATE)										X NO		EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR					

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 08/10/84, during performance of the "CONTROL OF TRANSIENT COMBUSTIBLES" procedure (40-AC-FPX01-0), plant personnel determined that the sliding fire door for the 600V station service switchgear room 2-C was obstructed by the door of switchgear cabinet 2H21-P051. It is postulated that the switchgear cabinet's door had been left in the open position by contractor personnel. The cabinet door opened into the closing path of the switchgear room's sliding fire door, and would have prevented the fire door's completely closing in the event of a fire. This event is contrary to the requirements of Tech. Specs. section 3.7.7. The switchgear cabinet's panel door was closed by fire protection personnel on 08/10/84, thus restoring the sliding fire door's fire protection integrity. This event is reportable per 10CFR 50.73 (a)(2)(i)(B).

IE22
11/8412060382 841121
PDR ADDOCK 05000366
S PDR

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
EDWIN I. HATCH, UNIT 2	0 5 0 0 0 3 6 6 8 4	-	0 2 9	-	0 0 0 2	OF 0 2

TEXT (If more space is required, use additional NRC Form 368A's) (17)

This 30 day LER is required by 10CFR 50.73(a)(2)(i)(B), because this event shows that the plant was operated contrary to Tech. Specs. section 3.7.7.

On 08/10/84 at approximately 0900 CDT, with the reactor in cold shutdown, and during performance of the weekly "CONTROL OF TRANSIENT COMBUSTIBLES" procedure (40-AC-FPX01-0), plant personnel noted that contract personnel were working on switchgear cabinet 2H21-P051 (inside switchgear room 2-C). At approximately 1130 CDT on the same day, plant personnel noted that the contract personnel were no longer in the vicinity, and that the access door to panel 2H21-P051 had been left in a position which would have prevented complete closing of the sliding fire door. Thus, the fire door was inoperable, and no fire watch was posted. The event was contrary to the requirements of Tech. Specs. section 3.3.7 which requires that either fire barriers be operable or fire watches be posted.

This event was determined to be non-reportable on 8/16/84. During the followup review by the PRB on 10/25/84, the determination was made that the event was reportable.


This event is the result of contractor personnel error. The 600V station service switchgear cabinet (2H21-P051) door was left in the open position which would have interfered with the complete closing of the sliding fire door. After plant personnel noted that contract personnel had left the 600V station service switchgear room 2-C and that no fire watch was present, they closed the switchgear cabinet's access door (at approximately 1130 CDT on 08/10/84). This removed the sliding fire door's obstruction and restored the fire door's fire protection integrity.

Contract personnel were cautioned about obstructing fire doors. This caution was reiterated at the retrofit contractor meeting on 11/13.

Smoke detectors located in the ceiling of station service switchgear room 2-C, which alarm in the main control room, were operable during this event.

This non-repetitive event had no effect on any other system in Unit 2, or Unit 1, nor did it affect the health and safety of the public.

Georgia Power Company
Post Office Box 439
Baxley, Georgia 31513
Telephone 912 367-7781
912 537-9444




Edwin I. Hatch Nuclear Plant

November 21, 1984
GM-84-1036

PLANT E. I. HATCH
Licensee Event Report
Docket No. 50-366

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Attached is Licensee Event Report No. 50-366/1984-029. This report is required by 10CFR 50.73(a)(2)(i)(B).


H. C. Nix
General Manager

HCN/TLE/djs

xc: R. J. Kelly
R. E. Conway
J. T. Beckham, Jr.
P. D. Rice
K. M. Gillespie
Superintendent of Regulatory Compliance
R. D. Baker
Control Room
Document Control

IE22
11