

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)
Sequoyah, Unit 1

DOCKET NUMBER (2)

0 5 0 0 0 3 2 7 1 OF 0 2

PAGE (3)

TITLE (4)

Auxiliary Building Ventilation Isolation

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)																		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)																	
1	1	0	4	8	4	8	4	0	6	8	0	0	1	1	3	0	8	4	Sequoyah, Unit 2	0	5	0	0	0	3	2	8
																				0	5	0	0	0			

OPERATING MODE (9)

1

POWER LEVEL (10)

1 0 0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)

20.402(b)

20.405(c)

50.73(a)(2)(iv)

73.71(b)

20.405(a)(1)(i)

50.38(c)(1)

50.73(a)(2)(v)

73.71(c)

20.405(a)(1)(ii)

50.39(c)(2)

50.73(a)(2)(vi)

OTHER (Specify in Abstract below and in Text, NRC Form 366A)

20.405(a)(1)(iii)

50.73(a)(2)(i)

50.73(a)(2)(vii)(A)

20.405(a)(1)(iv)

50.73(a)(2)(ii)

50.73(a)(2)(vii)(B)

20.405(a)(1)(v)

50.73(a)(2)(iii)

50.73(a)(2)(ix)

LICENSEE CONTACT FOR THIS LER (12)

NAME

TELEPHONE NUMBER

Glenn E. Duggin, Compliance Section Engineer

AREA CODE

6 1 5 8 7 0 - 6 1 4 6

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)

X NO

EXPECTED SUBMISSION DATE (15)

MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

An inadvertent relay actuation caused an auxiliary building ventilation isolation (ABI) to occur. Investigation revealed that a relay was jarred while personnel were working inside a cabinet in the main control room (MCR). The relay was found to be not fully seated in its terminal block. This relay gives a high radiation signal for the spent fuel pool radiation monitor, which causes an ABI. Radiation monitors were checked and no abnormal levels or spikes were found. The ABI was reset and the system returned to normal. Radiation levels were not above normal during this time.

8412060608 841130
PDR ADDOCK 05000327
S PDR1000
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Sequoyah, Unit 1	0 5 0 0 0 3 2 7 8 4 —	0	6	8	—	0	0 0 2 CF 0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

This auxiliary building isolation (ABI) occurred at 1228 CST on 11/04/84 while unit 1 was in mode 1 (100 percent power, 2235 psig, 578 degrees F) and unit 2 was in mode 6 (0 percent power, 0 psig, 95 degrees F). The ABI was reset at 1255 CST on 11/04/84. All associated equipment and personnel responded and performed as expected during the ABI. The operator responded to the alarm and determined that the alarm was in fact caused by inadvertent relay actuation and not by a high radiation level and reset the ABI. Radiation monitors were checked and no abnormal levels or spikes were found.

Modifications personnel were working in main control room (MCR) cabinet, 0-M-12, when the ABI occurred. They were connecting wiring between the Technical Support Center (TSC) and the Post Accident Sampling radiation monitors per an approved workplan. Personnel jarred a relay (R102) which actuated the high radiation signal for radiation monitor 102, the spent fuel pool (SFP) radiation monitor. The relay was subsequently found not fully seated in its terminal block. The relay contacts made up momentarily when it was jarred. The relay was placed back into its correct position, the ABI reset, and the ventilation system returned to normal. Radiation levels were not above normal during this time.

Personnel have been cautioned to be extremely careful when terminating wires due to potential spurious relay actuation.

There was no effect on public health or safety, and no plant safety margins were exceeded.

Previous occurrences of ABIs in 1984 on unit 1 - 14. This is the first ABI caused by this particular event.

TENNESSEE VALLEY AUTHORITY

Sequoyah Nuclear Plant
Post Office Box 2000
Soddy Daisy, Tennessee 37379

November 30, 1984

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555


Gentlemen:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET NO.
50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE REPORT
SQRO-50-327/84068

The enclosed licensee event report provides details concerning the auxiliary building ventilation isolation caused by an inadvertent signal in a radiation monitor circuit. This event is reported in accordance with 10 CFR 50.73, paragraph a.2.IV.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



P. R. Wallace
Plant Manager

Enclosure
cc (Enclosure):

James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street, NW
Atlanta, Georgia 30323

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30330

NRC Inspector, NUC PR, Sequoyah

1522
1/1