



**Northern States Power  
Company**

**Prairie Island Nuclear Generating Plant**

1717 Wakonade Dr. East  
Weich, Minnesota 55089

February 14, 1996

10 CFR Part 50  
Section 50.73

U S Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

**PRAIRIE ISLAND NUCLEAR GENERATING PLANT**  
Docket Nos. 50-282 License Nos. DPR-42  
50-306 DPR-60

Failure of Containment Isolation Valve to Pass its Leak Rate Test

The Licensee Event Report for this occurrence is attached. In the report, we made no new NRC commitments.

Please contact us if you require additional information related to this event.

*Jack Leveille*

for Roger O Anderson  
Director  
Licensing and Management Issues

c: Regional Administrator - Region III, NRC  
NRR Project Manager, NRC  
Senior Resident Inspector, NRC  
Kris Sanda, State of Minnesota

Attachment  
**2100 5**

9602230346 960214  
PDR ADDCK 05000282  
S PDR

*IE22*  
*11*

NRC FORM 366 (4-95)			U.S. NUCLEAR REGULATORY COMMISSION			APPROVED BY OMB NO. 3150-0104 EXPIRES 04/30/98 <small>ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS MANDATORY INFORMATION COLLECTION REQUEST: 50.0 HRS. REPORTED LESSONS LEARNED ARE INCORPORATED INTO THE LICENSING PROCESS AND FED BACK TO INDUSTRY. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (T-6 F33), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.</small>																														
<b>LICENSEE EVENT REPORT (LER)</b> (See reverse for required number of digits/characters for each block)																																				
FACILITY NAME (1) Prairie Island Nuclear Generating Plant Unit 1						DOCKET NUMBER (2) 05000 282		PAGE (3) 1 OF 3																												
TITLE (4) Failure of Containment Isolation Valve to Pass its Leak Rate Test																																				
EVENT DATE (5) <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>MONTH</th> <th>DAY</th> <th>YEAR</th> </tr> <tr> <td>01</td> <td>15</td> <td>96</td> </tr> </table>			MONTH	DAY	YEAR	01	15	96	LER NUMBER (6) <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>YEAR</th> <th>SEQUENTIAL NUMBER</th> <th>REVISION NUMBER</th> </tr> <tr> <td>96</td> <td>-- 003 --</td> <td>0</td> </tr> </table>			YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	96	-- 003 --	0	REPORT DATE (7) <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>MONTH</th> <th>DAY</th> <th>YEAR</th> </tr> <tr> <td>2</td> <td>14</td> <td>96</td> </tr> </table>			MONTH	DAY	YEAR	2	14	96	OTHER FACILITIES INVOLVED (8) <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>FACILITY NAME</th> <th>DOCKET NUMBER</th> </tr> <tr> <td></td> <td>05000</td> </tr> <tr> <th>FACILITY NAME</th> <th>DOCKET NUMBER</th> </tr> <tr> <td></td> <td>05000</td> </tr> </table>		FACILITY NAME	DOCKET NUMBER		05000	FACILITY NAME	DOCKET NUMBER		05000
MONTH	DAY	YEAR																																		
01	15	96																																		
YEAR	SEQUENTIAL NUMBER	REVISION NUMBER																																		
96	-- 003 --	0																																		
MONTH	DAY	YEAR																																		
2	14	96																																		
FACILITY NAME	DOCKET NUMBER																																			
	05000																																			
FACILITY NAME	DOCKET NUMBER																																			
	05000																																			
OPERATING MODE (9) N		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)																																		
POWER LEVEL (10) 0		20.2201(b)		20.2203(a)(2)(v)		X 50.73(a)(2)(i)		50.73(a)(2)(viii)																												
		20.2203(a)(1)		20.2203(a)(3)(i)		50.73(a)(2)(ii)		50.73(a)(2)(x)																												
		20.2203(a)(2)(i)		20.2203(a)(3)(ii)		50.73(a)(2)(iii)		73.71																												
		20.2203(a)(2)(ii)		20.2203(a)(4)		50.73(a)(2)(iv)		OTHER																												
		20.2203(a)(2)(iii)		50.36(c)(1)		50.73(a)(2)(v)		Specify in Abstract below or in NRC Form 366A																												
		20.2203(a)(2)(iv)		50.36(c)(2)		50.73(a)(2)(vii)																														
LICENSEE CONTACT FOR THIS LER (12)																																				
NAME Jack Leveille						TELEPHONE NUMBER (Include Area Code) 612-388-1121																														
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																																				
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS																										
B	CB	V	R340	Y																																
SUPPLEMENTAL REPORT EXPECTED (14)						EXPECTED SUBMISSION		<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>MONTH</th> <th>DAY</th> <th>YEAR</th> </tr> <tr> <td></td> <td></td> <td></td> </tr> </table>			MONTH	DAY	YEAR																							
MONTH	DAY	YEAR																																		
YES (If yes, complete EXPECTED SUBMISSION DATE).					X NO																															
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)																																				
<p>During January and February 1996, Unit 1 was at cold shutdown for refueling. Local leak rate testing of containment penetrations was performed during the refueling outage. On January 15, 1996, the leak rate through check valve VC-8-5, No. 11 Reactor Coolant Pump Seal Water Supply, located inside containment was calculated to be more than the 154,800 scc/min (0.6 L<sub>a</sub>) total allowable per Technical Specification 4.4.A.4 for all Type B and C penetrations combined. The redundant isolation for this penetration (13A) outside containment is the closed Chemical and Volume Control System (CVCS). Surveillance procedure SP-1366 verifies leak tightness of the CVCS valves that are required to perform a function as a closed system outside containment. This test was performed with satisfactory results on January 20, 1996. The leaking check valve was removed and replaced with a spare; the replacement valve was leak rate tested with satisfactory results.</p> <p>All other containment penetrations were tested with satisfactory results except that seven Type B flange tests remain to be performed; all of these flanges have had a good performance history, thus the total leak rate for containment is expected to be low.</p>																																				

## LICENSEE EVENT REPORT (LER)

## TEXT CONTINUATION

FACILITY NAME (1)	DOCKET	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Prairie Island Nuclear Generating Plant Unit 1	05000 282	96	-- 003	-- 00	2 OF 3

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

EVENT DESCRIPTION

During January and February 1996, Unit 1 was at cold shutdown for refueling. Local leak rate testing (LLRT) of containment penetrations (EIS Component Identifier - PEN) was performed during the refueling outage. On January 15, 1996, the leak rate through check valve VC-8-5 (EIS Component Identifier - V), No. 11 Reactor Coolant Pump Seal Water Supply, located inside containment was calculated to be more than the 154,800 scc/min (0.6 L<sub>a</sub>) total allowable per Technical Specification 4.4.A.4 for all Type B and C penetrations combined. The redundant isolation for this penetration (13A) outside containment is the closed Chemical and Volume Control System (CVCS) (EIS System Identifier - CB). Surveillance procedure SP-1366 verifies leak tightness of the CVCS valves that are required to perform a function as a closed system outside containment. This test was performed with satisfactory results on January 20, 1996. The leaking check valve was removed and replaced with a spare; the replacement valve was leak rate tested with satisfactory results.

All other containment penetrations were tested with satisfactory results except that seven Type B flange tests remain to be performed; all of these flanges have had a good performance history, thus the total leak rate for containment is expected to be low.

CAUSE OF THE EVENT

The valve disc was binding, causing it to hang up in the partially open position. The integral stellite bearings, which are part of the disc, were rubbing against the edges of the valve's outlet port causing rough worn spots to develop on the disc bearings. The worn spots on the bearings offered greater resistance to movement as the disc closed, causing it to hang up in the partially open position. There were several such wear areas on both the upper and lower surfaces.

ANALYSIS OF THE EVENT

The event is reportable pursuant to 10CFR50.73(a)(2)(i)(B) since the leak rate was above the limit given in Technical Specification 4.4.A.4.a.

Because the closed loop CVCS redundant isolation for Penetration 13A was intact and seal injection pressure is normally higher than the reactor coolant system pressure and the low likelihood of piping failure of the CVCS, the failure of VC-8-5 to meet the LLRT acceptance criteria is not perceived as risk significant. For this reason, the health and safety of the public were unaffected.

CORRECTIVE ACTION

The check valve was replaced and passed its LLRT.

## LICENSEE EVENT REPORT (LER)

## TEXT CONTINUATION

FACILITY NAME (1)	DOCKET	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Prairie Island Nuclear Generating Plant Unit 1	05000 282	96	-- 003	-- 00	3 OF 3

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

Analysis of Nuclear Plant Reliability Data System (NPRDS) failure data for this model of valve in similar service indicates the valves are performing well in the industry. Conversation with other utilities and review of their LLRT data for these valves confirmed the satisfactory performance of this style of valve in seal injection applications. Therefore, there are no plans for increased maintenance of these valves but we are considering increased inspection of this model of check valve as part of the plant check valve inspection program is being considered.

FAILED COMPONENT IDENTIFICATION

Rockwell-Edwards 2-C58 1500# check valve, Figure 3674F316J

PREVIOUS SIMILAR EVENTS

Previous similar events involving the same model valve have been reported as Unit 1 LERs 77-010 and 85-005 and Unit 2 LER 77-039.