

LICENSEE EVENT REPORT (LER)

APPROVED OMB NO. 3180-0104
EXPIRES - 8/31/85

FACILITY NAME (1) Limerick Generating Station - Unit 1										DOCKET NUMBER (2) 0 5 0 0 0 3 1 5 2 1										PAGE (3) OF 0 3																																																	
TITLE (4) Procedural Deficiency in the Fire Hose Station Visual Inspection																																																																					
EVENT DATE (5) 1 1 0 6 8 4 8 4 - 0 0 4 - 0 1 2 0 6 8 4										LER NUMBER (6) 20.402(a) 20.406(a)(1)(i) 20.406(a)(1)(ii) 20.406(a)(1)(iii) 20.406(a)(1)(iv) 20.406(a)(1)(v)										REPORT DATE (7) 20.406(a) 80.36(a)(1) 80.36(a)(2) 80.73(a)(2)(i) 80.73(a)(2)(ii) 80.73(a)(2)(iii)										OTHER FACILITIES INVOLVED (8) FACILITY NAMES DOCKET NUMBER(S) 0 5 0 0 0 1 1 0 5 0 0 0 1 1																																							
OPERATING MODE (9) 5										THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following) (11)																																																											
POWER LEVEL (10) 90.0										20.402(a)										20.406(a)										80.73(a)(2)(iv)										73.71(b)																													
										20.406(a)(1)(ii)										80.36(a)(1)										80.73(a)(2)(v)										73.71(a)																													
										20.406(a)(1)(iii)										80.36(a)(2)										80.73(a)(2)(vi)										OTHER (Specify in Abstract below and in Text, NRC Form 308A)																													
										20.406(a)(1)(iv)										80.73(a)(2)(i)										80.73(a)(2)(viii)(A)																																							
										20.406(a)(1)(v)										80.73(a)(2)(ii)										80.73(a)(2)(viii)(B)																																							
										20.406(a)(1)(v)										80.73(a)(2)(iii)										80.73(a)(2)(ix)																																							
LICENSEE CONTACT FOR THIS LER (12)																																																																					
NAME B. L. Clark, Senior Engineer-Special Projects															TELEPHONE NUMBER AREA CODE 2 1 5 8 4 1 - 5 0 1 7																																																						
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																																																																					
<table border="1"><thead><tr><th>CAUSE</th><th>SYSTEM</th><th>COMPONENT</th><th>MANUFACTURER</th><th>REPORTABLE TO NRC</th><th>CAUSE</th><th>SYSTEM</th><th>COMPONENT</th><th>MANUFACTURER</th><th>REPORTABLE TO NRC</th></tr></thead><tbody><tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>																														CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC																														
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC																																																												
SUPPLEMENTAL REPORT EXPECTED (14)															EXPECTED SUBMISSION DATE (15)																																																						
YES (If yes, complete EXPECTED SUBMISSION DATE)															NO																																																						

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

Abstract: 84-004

On November 6, 1984, during a comprehensive review of Surveillance Test (ST) Procedures against Technical Specification requirements, it was determined that 4 fire hose stations required to be inspected by the facility's Technical Specifications had been omitted from procedure ST-7-022-951-0, "Fire Hose Station Visual Inspection". As a result, a documented monthly inspection of these stations had not been performed. Upon discovery of the omission, a documented inspection of the 4 fire hose stations was performed immediately and the stations found to be properly equipped. The procedure was revised and approved on November 29, 1984.

8412120412 841206
PDR ADOCK 05000352
S PDRIE 22
111

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES 8/31/85

FACILITY NAME (1) Limerick Generating Station Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 5 2 8 4 - 0 0 4 - 0 0 0 0 2 OF 0 3	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			

TEXT (If more space is required, use additional NRC Form 366A (17))

Description of the Event:

On November 6, 1984, with the Unit at zero percent power during the initial core loading during a comprehensive review of the Surveillance Test (ST) Procedures against Technical Specification requirements, it was determined that 4 of the 38 fire hose stations required to be inspected per Technical Specification 4.7.6.5(a) had been omitted from procedure ST-7-022-951-0, "Fire Hose Station Visual Inspection".

As a result, a documented monthly inspection of these stations had not been performed. Upon discovery of the omission, a documented inspection of the 4 fire hose stations was performed immediately and the stations found to be properly equipped with the necessary hose and nozzle.

The other 34 fire hose stations were documented as inspected and found properly equipped on October 31, 1984.

Consequences of the Event:

Although the subsequent partial test performed on November 6, 1984, found these stations to be properly equipped, the omission of these 4 fire hose stations from ST-7-022-951-0 resulted in a temporary undocumented inspection of the fire hose equipment available at these stations.

Cause of the Event:

The failure to properly document the inspection of 4 of the 38 fire hose stations, as required by the Technical Specifications, was caused by a procedural deficiency in Surveillance Test ST-7-022-951-0.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES 8/31/84

FACILITY NAME (1) Limerick Generating Station Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 5 2 8 4 -	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		0	04	- 0 0	0 3	OF	0 3

TEXT (if more space is required, use additional NRC Form 366a) (17)

Corrective Actions:

The 4 omitted fire hose stations were immediately inspected and found to be properly equipped. The changes to ST-7-022-951-0 were approved by the facility's Plant Operational Review Committee on November 29, 1984. In addition, a review of the Technical Specifications against the Surveillance Tests for the other fire hose station inspections discovered no additional omissions nor discrepancies to the procedures.

PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

(215) 841-4000

December 6, 1984

Docket No. 50-352

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

SUBJECT: Licensee Event Report
Limerick Generating Station - Unit 1

This LER concerns the discovery of a procedural deficiency in the Fire Hose Station Visual Inspection Surveillance Test regarding the inspection of Fire Hose Stations required by the Technical Specification 4.7.6.5. The discovery of this deficiency occurred prior to initial criticality.

Reference:	Docket No. 50-352
Report Number:	84-004
Revision Number:	00
Event Date:	November 6, 1984
Report Date:	December 6, 1984
Facility:	Limerick Generating Station P.O. Box A, Sanatoga, PA 19464

This LER is submitted pursuant to the requirements of 10 CFR 50.73(a)(2)(i).

Very truly yours,



W. T. Ullrich
Superintendent
Nuclear Generation Division

cc: Dr. Thomas E. Murley, Administrator
Region I, USNRC

See Service List

IE22
11

cc: Judge Lawrence Brenner
Judge Peter A. Morris
Judge Richard F. Cole
Troy B. Conner, Jr., Esq.
Ann P. Hodgdon, Esq.
Mr. Frank R. Romano
Mr. Robert L. Anthony
Maureen Mulligan
Charles W. Elliott, Esq.
Zori G. Ferkin, Esq.
Mr. Thomas Gerusky
Director, Penna. Emergency
Management Agency
Angus Love, Esq.
David Wersan, Esq.
Robert J. Sugarman, Esq.
Martha W. Bush, Esq.
Spence W. Perry, Esq.
Jay M. Gutierrez, Esq.
Atomic Safety & Licensing Appeal Board
Atomic Safety & Licensing Board Panel
Docket & Service Section (3 copies)
James Wiggins
Timothy R. S. Campbell