

TENNESSEE VALLEY AUTHORITY

USNRC REGION II
CHATTANOOGA, TENNESSEE 37401
ATLANTA, GEORGIA
400 Chestnut Street Tower II

BLRD-50-438/84-55
BLRD-50-439/84-51
NOV 30 P 1:33 November 27, 1984

U.S. Nuclear Regulatory Commission
Region II

Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - DEFICIENT CATEGORY I COMPONENTS AND
MISCELLANEOUS STEEL - BLRD-50-438/84-55 AND BLRD-50-439/84-51 - FIRST INTERIM
REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
P. E. Fredrickson on October 29, 1984 in accordance with 10 CFR 50.55(e) as
NCR 3615. Enclosed is our first interim report. We expect to submit
our next report on or about March 25, 1985. We consider 10 CFR Part 21
applicable to this deficiency.

If you have any questions, please get in touch with R. H. Shell at
FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. W. Hufham
by RLS

J. W. Hufham, Manager
Licensing and Regulations

Enclosure

cc: Mr. Richard C. DeYoung, Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center (Enclosure)
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8412130544 841127
PDR ADOCK 05000438
S PDR

OFFICIAL COPY

11 IE27

ENCLOSURE

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2
DEFICIENT CATEGORY I COMPONENTS AND MISCELLANEOUS STEEL
BLRD-50-438/84-55, BLRD-50-438/84-51
10 CFR 50.55(e)
NCR 3615
FIRST INTERIM REPORT

Description of Deficiency

Reinspection of several structural components, which had been inspected and approved, revealed that several components do not meet requirements documented in Bellefonte Quality Control Procedure (QCP) 2.15 and design drawings. Some of the affected components include stairs, ladders, platforms, tank supports, and pipe supports. Approximately 73 percent of the total items reinspected failed to meet the referenced requirements.

Interim Progress

TVA is presently determining the scope of the problem and required corrective actions.