

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401  
400 Chestnut Street Tower II

84 NOV 30 P 1:33 November 27, 1984

BLRD-50-438/83-52  
BLRD-50-439/83-45

U.S. Nuclear Regulatory Commission  
Region II  
Attn: Mr. James P. O'Reilly, Regional Administrator  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

Dear Mr. O'Reilly:

BELLEFCNTE NUCLEAR PLANT UNITS 1 AND 2 - FRONT COVERS SEPARATED FROM BAILEY  
MEIER MODULES - BLRD-50-438/83-52, BLRD-50-439/83-45 - FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector  
Linda Watson on October 4, 1983 in accordance with 10 CFR 50.55(e) as NCR  
2454. This was followed by our interim reports dated November 1, 1983 and  
January 25 and April 18, 1984. A one-week delay of this submittal was  
discussed with Inspector P. E. Fredrickson on November 21, 1984. Enclosed  
is our final report. We consider 10 CFR Part 21 applicable to this  
deficiency.

If you have any questions, please get in touch with R. H. Shell at  
FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*J. W. Hufham*  
J. W. Hufham, Manager  
Licensing and Regulations

Enclosure

cc (Enclosure):

Mr. Richard C. DeYoung, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

H. B. Barkley  
205 Plant Project Services  
P.O. Box 10935  
Lynchburg, VA 24506-0935

OFFICIAL COPY

8412140227 841127  
PDR ADOCK 05000438  
S PDR

Equal Opportunity Employer

TE 27  
11

## ENCLOSURE

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2  
FRONT COVERS SEPARATED FROM BAILEY METER MODULES  
BLRD-50-438/83-52, BLRD-50-439/83-45  
NCR 2454  
10 CFR 50.55(e)  
FINAL REPORT

### Description of Deficiency

While inspecting Bailey Meter Company modules at Bellefonte Nuclear Plant (BLN), TVA's Office of Construction (OC) personnel discovered that front cover plates for several class 1E modules in control cabinets for the nonnuclear instrumentation (NNI) and essential controls instrumentation (ECI) systems had become separated from the frame body of the module. The front cover plate is attached to the frame body by means of two spot welds at the top and bottom of the front cover plate. These spot welds had been broken causing the front plate cover to separate from the module.

The root cause of this problem was inadequate process control by the vendor. This is documented in Babcock and Wilcox (B&W) letter D-4981. The vendor failed to supply sufficient current for the second and subsequent spot welds which secure the front cover to the module. This insufficient current resulted in smaller than acceptable weld nugget sizes.

A secondary contributor to failure of the front cover welds was the excessive forces required to remove the module. This excessive force resulted from a misalignment of the back plane contacts.

### Safety Implications

The spot welds on the front cover plates of the class 1E control modules have become separated from the frame body. This will allow the modules greater movement inside the cabinets. Unrestricted movement of the modules inside the cabinet could lead to the possible short-out of wiring in the modules or the module-to-cabinet plug-in coming out of the cabinet. The loss of essential safety-related controls would adversely affect the safe operation of the plant.

### Corrective Actions

The modules were returned to the vendor for rework. The vendor has completed the rework and returned the modules to BLN. For the smaller than acceptable weld sizes, the vendor revised his welding procedure to ensure that adequate current is supplied during the welding process so that acceptable welds are produced.

To address the misalignment problem, TVA will realign these back plane contacts that have been documented in this nonconformance report using a special alignment tool in accordance with the vendor's recommendations by March 22, 1985. TVA is obtaining this tool from B&W and requested that B&W provide maintenance instructions governing the tool's use. TVA will incorporate these instructions into the maintenance procedures used by site personnel. TVA anticipates receipt and approval of these instructions by February 15, 1985.