

## LICENSEE EVENT REPORT

CONTROL BLOCK: UPDATE REPORT - PREVIOUS REPORT DATE AUGUST 20, 1982  
(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	S	C	H	B	R	2	2	0	0	-	0	0	0	0	0	0	0	3	4	1	1	1	1	4		5																						
7	8	9	14						15	25										26	30				57	CAT	58																						
LICENSEE CODE																												LICENSE NUMBER										LICENSE TYPE											

CONT

0	1	L	6	0	5	0	0	0	2	6	1	7	0	1	1	3	8	1	8	1	2	0	6	8	4	9						
7	8	60										61	68										69	74				75	80			
REPORT SOURCE		DOCKET NUMBER										EVENT DATE										REPORT DATE										

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operation on 1/13/81, a review of the Service Water System revealed a

0 3 | potential unmonitored release path to the environment. This is due to the lack of

0 4 | radiation monitoring on the service water return lines from containment for the

0 5 | four HVH motor coolers (fan cooler returns are monitored). An unmonitored release

0 6 | could result if post accident containment pressure is above Service Water System

0 7 | pressure and there exists a system leak inside containment. This condition is

0 8 | considered reportable pursuant to Technical Specification 6.9.2.a(9).

0	9	W	A	11	B	12	A	13	Z	Z	Z	Z	Z	Z	14	Z	15	Z	16		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26		
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE								COMP. SUBCODE		VALVE SUBCODE					
17		LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAI REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.									
8		1		—		0 0 2		0 1		T		3									
21		22		23		24		25		26		27									
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER					
F		Z		Z		Z		0 0 0 0		Y		N		Z		Z 9 9 9					
33		34		35		36		37		40		41		42		43		44		47	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The above configuration is a result of the original system design. As a short term

1 1 | corrective action, the Service Water System inside containment was inspected daily,

1 2 | when above 200°F, for leaks. As a permanent corrective action, the HVH motor cooler

1 3 | discharge lines were modified to permit monitoring for radioactivity. The return

1 4 | lines from both the HVH motor coolers and fan coolers are now monitored for radio-

7 8 9 activity.

1	5	E	28	1	0	0	29	N/A	C	31	Review of System	32
7	8	9	10	11	12	13	14	15	16	17	18	19
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				
E		1 0 0		N/A		C		Review of System				
28		29		30		31		32				
33		34		35		36		37				
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE						
Z		Z		N/A		N/A						
33		34		35		36		37				
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION						
0		0		Z		N/A						
37		38		39		40		41				
PERSONNEL INJURIES		NUMBER		DESCRIPTION								
0		0		0		N/A						
40		41		42		43		44				
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION								
Z		N/A		N/A		N/A						
42		43		44		45		46				
PURLICITY		ISSUED		DESCRIPTION								
Z		N/A		N/A		N/A						
44		45		46		47		48				

NAME OF PREPARER Carson L. Wright

PHONE (803) 383-4524

IE22  
11

## SUPPLEMENTAL INFORMATION

FOR

### LICENSEE EVENT REPORT 81-003, UPDATE REPORT

#### 1. Cause Description and Analysis

On 1/9/81, Carolina Power and Light was informed by Westinghouse of a potential safety problem that had been reported to the NRC. This concerned the lack of radiation monitoring on the service water return lines from containment for the HVH motor coolers at Indian Point 2 (Consolidated Edison). Robinson 2 has a similar configuration. A review of the H. B. Robinson Service Water System was undertaken, and a special test was performed to verify service water pressure in the HVH motor cooler lines inside containment. The results of the special test found pressure in portions of the Service Water System to be below containment post accident design pressure (42 psig). Therefore, a potential unmonitored release path from containment could exist in an accident condition. On 1/13/81, it was determined that with a leak in the SW System inside the containment vessel and the lack of radiation monitoring on the HVH motor cooler discharge piping, coupled with the service water pressure inside containment being lower than design basis accident pressure, an undetected activity release path could exist during post accident conditions. This condition is reportable pursuant to Technical Specification 6.9.2.a(9).

#### 2. Corrective Action

Service water piping inside containment is being inspected daily for leaks. Should a leak occur, it will be considered a degradation of a containment boundary, and the requirements of Plant Operating Procedures and Technical Specifications will be applied. Operations personnel were instructed of the consequences of a Service Water System leak inside containment prior to February 2, 1981.

#### 3. Corrective Action to Prevent Recurrence

A review of the Service Water System was made which resulted in a modification of the HVH motor cooler return lines. Sample lines were installed from each HVH motor cooler return line to an existing radiation monitor. This radiation monitor now samples both the HVH motor cooler and fan cooler return lines.



Carolina Power & Light Company

ROBINSON NUCLEAR PROJECT DEPARTMENT  
POST OFFICE BOX 790  
HARTSVILLE, SOUTH CAROLINA 29550  
DEC - 6 1984

Robinson File No: 13510C

Serial: RSEP/84-984

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

ROBINSON NUCLEAR PROJECT DEPARTMENT, UNIT NO. 2  
DOCKET NO. 50-261  
LICENSE NO. DPR-23  
LICENSEE EVENT REPORT 81-002 REVISION 3

Dear Sir:

In accordance with Section 6.9.2 of the Technical Specifications for the H. B. Robinson Steam Electric Plant, Unit 2, the enclosed Licensee Event Report is submitted. The previous report, dated August 20, 1982, described a potential unmonitored release path to the environment through the Service Water System. This revision should replace all existing copies of the previous report. (The supplemental information has been barred for your convenience.)

Very truly yours,

R. E. Morgan  
General Manager  
H. B. Robinson S.E. Plant

CLW/ml

Enclosure

cc: INPO  
H. E. P. Krug  
J. P. O'Reilly

IE22  
11